

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सासाराम-2

पत्रांक २४० अम०

सासाराम 2/दिनांक 12/08/22

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-2

सेवा में,

नोडल पदाधिकारी (MR 3054)
ग्रामीण कार्य विभाग
पटना, बिहार


विषय :- नई अनुरक्षण नीति-2018 MR(3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुरक्षण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु० :- यथोक्त।

विश्वासभाजन


12/08/22

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-2

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to February 2022

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
s1	Construction of Rural roads Under MR	New Maintenance Policy-2018 MR (3054) BRRDA PATNA	1145.43532	Certified that out of Rs. 1145.43532 lakh of grants-in-aid sanctioned during the years 2018-21 Infavor of EE,RWD works division Sasaram-2 a sum of Rs 1134.29907 lakh has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 11.13625 lakh remaining unutilized at the end of the period under report.
Total:			1145.43532	

2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- i. Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii. Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii. Construction materials have been tested.
- iv. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- v. All other caudal formalities have been observed.

3. Physical Progress achieved:-

- i. Construction of Road Works.
- ii. Construction of CD works.


Divisional Accounts Officer
Rural Works Department
Works Div. Sasaram-2


Executive Engineer
Rural Works Department
Works Div. Sasaram-2

1. **Format for Scheme Head-MR(3054) under Bihar Rural Road Maintenance Policy-2016 (Initial recommendation)**

Name of Works Division:- Sasaram-2

Name of Works Division:- Sasaram-2																		
Sl no.	Package No	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1		Itimha Nonar - P.W.d. Roadgasara	10301002091	Lt-3274/Date-10.09.20	0.915	35.17600	20.69341	8.34000	RWD/SSM-2/NEW MR-78/2021-22 Dt 29.12.2021	28.12.22	-	2587	25.00	5.00%	0.00000	0.00000	20.59341	
MR-N/2020-21 sasaram-02/07																		
Total															0.00000	0.00000	20.59341	

Q3.22

Executive Engineer
Rural Works Department
Works Division, Sasaram-2

Road Name:- Itimha Nonar - P.W.d. Roadgasara

Date	Time	Section No.	Length in km	Bumps in mm	Speed	OR	IRI	TEGORY	Latitude	ongitude	Event
10/3/22	18:53:0	99	0.1	210	10.1	2100	2515	G	25.1012	84.3301	Normal
10/3/22	18:54:5	99	0.1	240	10.1	2400	2815	P	25.10041	84.33008	Normal
10/3/22	18:54:40	99	0.1	190	10.1	1900	2315	G	25.99857	84.33064	Normal
10/3/22	18:55:14	99	0.1	180	10.1	1800	2215	G	25.99852	84.33155	Normal
10/3/22	18:55:49	99	0.1	210	10.1	2100	2515	G	25.9958	84.33244	Normal
10/3/22	18:56:25	99	0.1	200	10.1	2000	2415	G	25.99343	84.3334	Normal
10/3/22	18:56:25	99	0.1	180	10.1	1800	2215	G	25.99097	84.33441	Normal
10/3/22	18:57:0	99	0.1	170	10.1	1700	2115	G	25.98782	84.3353	Normal
10/3/22	18:57:35	99	0.1	270	10.1	2700	3115	G	25.98378	84.33626	Normal
10/3/22	18:58:0	99	0.004	10	0	2500	2915	G	25.97913	84.33715	Normal

Revised
10/03/22
7E

25/03/22
84.33715

$$Y = 0 * X^2 + 1.000 * X + 415.2$$

$$X = 2172$$

$$Y = 2587$$

(R) RURAL ROAD
Good Average Poor
<4000 4001-5000 >5001

Name of Customer : NAND KISHORE SINGH
 Name of Work/ Road : PWD ROAD GASARA
 Lab Job number : 99
 Date : 10/03/2022
 Section No. : 99

Test Data : 10-03-2022
 Machine No : 391
 Start S No :
 Start E No :
 Weather :
 Sheet Location :
 End Location :
 Road Name : ITMHA NONAR - PWD ROAD
 Road Type : (R) RURAL ROAD
 Side :
 UIV Range : 1115 To 4000 Interval 1000 mm/km
 Dist Range : 0 To 1.2 0.1 1000 m
 Equation : $Y = 0 \cdot X^2 + 1.000 \cdot X + 415.2$


Print Generate Report and Graph

Redraw Graph

Map View

File : F:\1031619.Xls, Section No. : 99, Eqn : $Y = 0 \cdot X^2 + 1.000 \cdot X + 415.2$

Name of Customer : NAND KISHORE SINGH, Name of Work/ Road : ITMHA NONAR - PWD ROAD GASARA, Lab



Good
10/03/22
TE

10/03/22