

Dhanga To Khabas

Name of Road: Tol

Block: BENIPATTI

District: MADHUBANI

Length: 2.112 KM

Sr No.	Item	Item of Work	Nos	Length (M)	Width (M)	Depth (M)	Quantity	Unit	Rate	Amount
1	1.1	Labour for lying dry graded jhama khoa or Stone filter under Brick pitching or Boulder Pitching in slope or apron Including light ramming etc. all complete as per approved design, specification and direction of E/I								
						(0.6+0.9)/2				
		CH-0.600 KM	1	2.50	1.50	0.75	2.813			
						(0.6+0.9)/2				
		CH-0.600 KM	1	2.00	1.50	0.75	2.250			
						Total	5.063	Cum	1939.93	9822.00

Add GST 12% Rs= 1179.00

Add Labour Cess 1% Rs= 98.00

Add Signorance Fee (5.063x1032x10%) Rs= 523.00

Total Rs= 11622.00

[Signature]
JE
RWD BENIPATTI

[Signature]
AE
RWD BENIPATTI

[Signature]
EE
RWD BENIPATTI

[Signature]

[Signature]
20/12/21
EE

[Signature]
20.12.2021
J.E.

[Signature]
20/12/2021
A.E.

Post facto T/S awarded for Rs. 11622.00 (Eleven thousand six hundred twenty two only)
Reference to letter No. 233 dated 21/2/22 of EE darbhanga-2

[Signature]
Superintending Engineer
RWD Works Circle, Darbhanga

(17)

Inspection Report for Flood Damaged Work in the year 2021-22

Date of Inspection :- 20-12-21 Name of PIU :- RWD (W) Div. Doodharga-2
Name of Block / PIU :- Benipatti (RWD(W) Div Benipatti)
Name of Road :- Dhanga to khataba tal
For Road :-

1. Damage Location/ Chainage :- 0.600 km.

2. Damage Length :- 4.50 Mtr.

3. Nature of Damage :- ~~5.063 M3~~ Bricks due to Flood.

4. Details of Restoration Works :-


i. Material being used in Restoration Works :- Brick bats


ii. Equipment's/ Tools being used in Restoration Works :- Tractors

iii. Procedure taken up in Restoration Works :- Filling & compaction.

iv. Restored Length :- 4.500 Mtr, Restored Qty :- 5.063 M3.

Remarks :- Work found satisfactory.


20.12.21
Signature of JE/AE


20/12/21
Signature of E.E