



बिहार सरकार

ग्रामीण कार्य विभाग

Rural Works Department, Govt. of Bihar

HEAD-FDR/2245

STATE :- BIHAR

AA COPY

DISTRICT :- Madhubani

CIRCLE :- Darbhanga

BLOCK :- Rajangar

YEAR:- 2021-22

Estimate for Motorable in

**RLY GUMTI TO SOUTH EAST JANEWALI ROAD SANSKRIT SCHOOL
SE EAST MUKHIYA GUNANAND YADAV KE GHAR TAK
under FDR**

TOTAL LENGTH OF ROAD:-

1.00KM

TOTAL COST FOR MOTORABLE

Rs. 307494.55

Rs. 313345/-

Submitted by:

Executive Engineer

RWD(W) Division, Madhubani

प्रतिवेदन

पथ का नाम	:-	<u>RLY GUMTI TO SOUTH EAST JANEWALI ROAD SANSKRIT SCHOOL SE EAST MUKHIYA GUNANAND YADAV KE GHAR TAK</u>
पथ की लम्बाई	:-	<u>1.00KM</u>
प्राक्कलित राशि	:-	307495 रू0 <u>313345</u>
प्रमंडल का नाम	:-	<u>Madhubani</u>
अंचल का नाम	:-	<u>Darbhangha</u>
योजना का नाम	:-	<u>FDR-2245</u>


प्रस्तुत प्राक्कलन RLY GUMTI TO SOUTH EAST JANEWALI ROAD SANSKRIT SCHOOL SE EAST MUKHIYA GUNANAND YADAV KE GHAR TAK


पथ के लिए तैयार किया गया है जो कि बाढ़ एवं अतिवृष्टि के कारण हुए कटाव/जलजमाव/Wave Cut के कारण क्षतिग्रस्त हो गया था। जिसके कारण आवागमन बाधित हो गया था। फलतः ग्रामीणों को काफी कठिनाईयों का सामना करना पड़ रहा था। यह प्राक्कलन सचिव, ग्रामीण कार्य विभाग, बिहार, पटना के पत्रांक-मु0अ0-4 (मु0) विविध (कार्य) -23-60/2020-1937 पटना दिनांक 07.07.2021 के आलोक में तैयार किया गया है।


इस प्राक्कलन में क्षतिग्रस्त हुए पथांश को ईट के टुकड़ों से भरकर उसका सम्पीडन किया जाने का प्रावधान किया गया है।

प्रस्तुत प्राक्कलन वर्तमान स्वीकृति अनुसूचि दर पर तैयार किया गया है। यह कार्य लोकहित एवं जनहित में अत्यावश्यक है। अतः इस प्राक्कलन की स्वीकृति अपेक्षित है। यह कार्य विभागीय रूप से सम्पादित करा लिया गया है।

प्रस्तुत प्राक्कलन संपादित कार्य के समय लागू अनुसूचित दर पर जो संवेदक लाभांश को छोड़कर था। उसे प्रावधान करते हुए तैयार किया गया है।


कनीय अभियंता


सहायक अभियंता,


कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, मधुबनी

Estimate for Motorable in

RLY GUMTI TO SOUTH EAST JANEWALI ROAD SANSKRIT SCHOOL SE EAST
MUKHIYA GUNANAND YADAV KE GHAR TAK

Length:- 1.00KM

Sl No	Item No	Name of Item	Unit	No	Length	Width	Height	Qty.	Rate	Amount
1		Providing and filling brick bats in ditches including cost of brick bats and labour all complete job as per specification and direction of E/I.	Cum	As per Appendix 1				132.28 129.81	2004.96	265216.00 260264
								Add GST 12%		3182631232
								Add L.Cess 1%		2652 2603
								S Fee		136513396
								G. Total:-		307495

313345/-

[Signature]
Junior Engineer
RWD(W) Section
Rajangar

[Signature] 31/10/21
Assistant Engineer
RWD(W) Sub Division
Rajangar

[Signature] 01/11/21
Executive Engineer
RWD(W) Division, Madhubani

— कार्यपालक अभियन्ता, शांका-वि, कार्य प्रमंडल - विरेल के द्वारा
समिति जांच प्रतिवेदन के आधार पर

Post facto T/s for Rs. 3,13,345/- (Rupees
three Lac thirteen thousand three hundred and forty
five) only.

[Signature]
Superintending Engineer
R.W.D. (W) CIRCLE, DARBHANGA

Inspection Report of Flood Damage work

Name of PIUs:- Madhubani

Name of Block/ Road:- Rajnagar/Rly Gumti to south Gumti Jane wali road Sanskrit

School East Mukhiya Gunanand Yadav ke ghar tak

A. For Road

1. Damage Location Chainage:- CH 0.50, CH 0.610, CH 0.70.

2. Damage Length :- 139.2

3. Nature of Damage :- Damage of Crack

4. Details of Restoration Works

i. Material being used in Restoration works:- Brick Bat ✓

ii. Equipments's/Tools being used in Restoration works:- ✓

iii. Procedure taken up in Restoration works:- Brick Bat Filling ✓

iv. Restored Length:- 139.04.

B. For Bridge

1. Damage Location Chainage:-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works

i. Material being used in Restoration works:-

ii. Equipments's/Tools being used in Restoration works:-

iii. Procedure taken up in Restoration works:-

iv. Restored Length:-

Signature of JE/AE/EE
Satisfactory.
08/11/24

Signature
(Name of Inspection)