

Estimate for Restoration work of Road from Balha Ghat To Kamlabari for the year 2021-2022 in Bisfi Block

Length-4.206 KM

Sr NO.	Item of Work							
1	Labour for lying dry graded jhama khoa or Stone filter under Brick pitching in slope or apron including including light ramming etc. all complete as per approved design, specification and direction of E/I (Brick Bats)							
Ch	Nos	Length	Width	Height	Quantity	Unit	Rate	Amount
425	1	15.00	3.75	1.00	56.25	2	19.5	
	1	15.00	3.75	0.30	16.88		13.5	
	1	14.00	3.75	1.25	65.63		48.75	
545	1	4.00	3.00	1.00	12.00		4.8	
1410	1	8.75	3.75	0.30	9.84		4.8	
2190	1	15.00	3.75	0.30	16.88		10.8	
2660-2990	1	15.00	3.75	0.20	11.25		9.0	
	1	15.00	3.30	0.30	14.85		13.5	
	1	5.50	0.60	0.30	0.99		0.90	
	1	3.00	3.75	0.60	6.75		5.4	
	1	6.00	3.20	1.00	19.20		9.6	
	1	5.00	3.20	0.20	3.20		3.0	
	1	5.00	1.50	0.15	1.13		1.125	
	1	46.00	3.00	0.30	41.40		36.0	
3100	1	20.00	3.75	1.50	112.50		75.0	
	1	9.50	1.90	0.30	5.42		5.13	
	1	4.00	1.00	0.30	1.20			
3300	1	12.00	3.60	0.30	12.96		10.8	
					408.31	Cum	1939.93	

204 m

Add 12% GST
Add 1% L/Cess
Add Signorage Fee (408.31X1032X10%)
Total

280.00 m³ =Rs

=Rs

=Rs

=Rs

95051651822

7921 5432

42137 28896

937200 28896

Rs - 642690

[Signature]
22-11-21

JE
RWD
Bisfi

[Signature]
20/11/21

AE
RWD
Bisfi

[Signature]
27-11-21
EE

RWD
Benipatti

Damaged Length = 204 Metre

Restored Qty = 280.0 m³

Verified and found correct

[Signature]
27/11/21
JE

[Signature]
27/11/21
AE - Singh

[Signature]
27/11/21

Da

Na

Na

For

Name of Road: Balnaghat to Kamlaban
Road.

Post facto T/S awarded for Rs. 642690.00
(Rs Six Lacs forty two thousand six hundred
ninety only.)

Reference Letter no. 233 dated 21/2/22.


Superintending Engineer
RWD Works Circle, Darbhanga

04/2/22

R

S

tion Report for Flood Damaged Work in the year 2021-22

ction :- 27.11.2021 Name of PIU :- RWD (W) Div. Darbhanga-2
to 05.12.2021 (Inspected).

/PIU :- Bisti (RWD (W) Div. Benipatti)

:- Balhaghat to Kamlabari.

:-

Location/ Chainage :- In Between ch. 425 to 3300 .

Length :- ~~204.75~~ mtr. (204 meters)
f Damage :- Due to flood, pot patch develops.

Restoration Works :-

aterial being used in Restoration Works :- Bridge Bets .

ipment's/ Tools being used in Restoration Works :- Tractors Roller.

cedure taken up in Restoration Works :- Section wise work initiated and completed.

ored Length :- ~~217.75~~ mtr. 204 meters

ones found satisfactory.

Signature of E.E.

E.E. 19/02/2022

AE
19/02/22
SE