

Executive Engineer, RWD, (W) Division, ARARIA

Vame of Block:-

Khajauli

Vame of Road :-

LO44-TO3 TO Thengha(VR-44)

FOR ROAD

Damage Location/ Chainage - 0 & Re Cut at Ch 500m & 0 & 0

Damage Length :-

146.3 + 0 + 0 + 0 = 146.3 M

Nature of damage :-

Crust and Flank washed out.

Details of Restoration work

i Meterial being in Restoration work :-

Soil, Local Sand, Sand bag, Brickbat Bamboo etc.

ii Equipments/ Tools being used in Restoration works:- Tractor with trolly & others.

iii Procedure taken up in Restoration work:- Filling all damaged portion of Crust and Flank with above Meterial

iv Restored Length

146 M

FOR BRIDGE

Damage Location/ Chainage :-

2 Damage Length :-

Nature of damage :-

Details of Restoration work

Meterial being in Restoration work :-

Equipments/ Tools being used in Restoration works

Procedure taken up in Restoration work

Restored Length

Not Applicable

Name of Inspector EE, RWD, Madhubani

## GENERAL ABSTRACT OF COST

L044-T03 TO Thengha(VR-44)
Madhubani
Khajauli
Madhubani
146.30 M
DESCRIPTION AMOUNT (LAKHS)

1				1	- 1
	AMOUNT (LAKHS)	DESCRIPTION	13 (March 1989)	SJ. No.	
			TEMPORARY RESTORATION	PART-A	ſ
	43,408.00		EARTHWORK	.1	
	42,875.85		BAMBOO PILE	4	_
	5,07,064.63		BRICK BAT	5	_
	5,93,348.00		SUB TOTAL =	F. :	
	71,202.00	GST @ 12 % =			L
	5,933.00	LABOUR CESS @ 1 % =	E r m	ń.	d
l	41,013.00	SEIGNIORAGE FEE =			1
1	7,11,496.00	TOTAL =	:		1
1	7.115	COST (IN LACS) =	111		
1	7 120	TAL (IN LACS) =	GRAND TOT		

F20.10.21.

JE RWD Khajauli AE RWD Khajauli

EE RWD Madhubani

	k:-	2000 P	,* <u>\$</u>		a .		Kesi	UI	atton		4-T03 TO											_
- 1	Khaji	auli .					n my	3														_
ţ.	h 140	6.30	Meter	٠,		F	= 1												j.			
					i.				(A) Ten	nporar	y Restorat	tion			-							
N	GTH:-		1	_	146.3	30	М															
illing	and Spr	eading	local sa	and	over brid	cks	bats as per	r ted	chnical sp	ecificati	on clause				•					_		_
	1		x 27.0	0 x	2.500	: כ	x 1.25	=	84.38	M³												
		-				i	Net Qty.	=	84.38	M³												_
								=	84.38	M³@	Rs.514.43	/M³-Rs.	43	,408/	S.Fe	e 10% of F	Rs.34,81	/M³-R	is.		294	/
roviding nboo pil al piles	es to siz	e and	making ication a	sho and	es and direction	driv	ing etc. co	omp	elete job a	s per	-						_ ;	ra v				
nboo pil	es to siz	e and	making	sho	es and	driv	ing etc. co	omp	elete job a	M M							- :			5.		
nboo pil ≱al piles	es to siz	e and	making ication a	sho	direction	driv	ing etc. co	omp	363.60	M M			000110							ħ		
nboo pil ≱al piles	es to siz	e and specif	making ication a	sho and	direction	driv n of	E / I.	omp	363.60 176.70	M M									1	1.		
nboo pil ≱al piles	es to siz	e and specif	making ication a	sho	3.60	driv n of	E / I.	omp	363.60 176.70 540.30	M M	Rs.55.40	/M-Rs.	31,	,429 /								
al piles al piles al piles	Wastage	e and specific fixing	making fication at 101 57 62mm to mm long land La	x x x x x x x x x x x x x x x x x x x	3.60 3.5.000	% % % a ba	E / I.	tal	363.60 176.70 540.30 27.015 567.32	M M M M M M M M M M M M M M M M M M M	Rs.55.40	/M-Rs.	31,	,429 /	100							
al piles al piles al piles	Wastage	e and specific fixing	101 57 62mm t mm long l and La direct	x x x x x x x x x x x x x x x x x x x	3.60 3 5.000 5 mm dists or 38 r comp	% % % a ba	Total Qty	tal ners	363.60 176.70 540.30 27.015 567.32	M M M M M M M M M M M M M M M M M M M	Rs.55.40	/M-Rs.	31,	,429 /	100						***	
al piles al piles al piles	Wastage	e and specific fixing	fication a service of the service of	x x x x x x x x x x x x x x x x x x x	3.60 3 5.000 5 mm dials or 38 r compn of E / I	% % % a ba	Total Qty	tal incres	363.60 176.70 540.30 27.015 567.32 in positicluding coecification	M M M M M M M M M M M M M M M M M M M	Rs.55.40	/M-Rs.	31	,429 /	100							
al piles al piles al piles	Wastage	e and specific	fication a service of the service of	× × × o 75 naii	3.60 3 5.000 5 mm dialis or 38 r companof E / I.	% % a bas sw	Total Qty	tal mers	363.60 176.70 540.30 27.015 567.32 in positicluding coecification	M M M M M M M M M M M M M M M M M M M	Rs.55.40	/M-Rs.	31,	,429 //	100							
al piles al piles blying fit	Wastage	e and specific	fication a service of the service of	shoond × × ×  and o 75 nai bourtior × ×	3.60 3.5.000 5 mm dia ils or 38 r comp n of E / I. 24.50	% % a bas sw	Total Qty  Total Qty  amboo runr g G.I. wire	tal mers	363.60 176.70 540.30 27.015 567.32 in positicluding coecification	M M M M M M M M M	Rs.55.40	/M-Rs.	31,	,429 /	100							
al piles al piles olying fit	Wastage ting and ting and ting and ting and ting and ting and ting all m	e and specification of the spe	fication a service of the service of	sho and a x x x x x x x x x x x x x x x x x x	3.60 3.5.000 5 mm dia ills or 38 r comp of E / I. 24.50 27	% % a ba sw blete	Total Qty  Total Qty  amboo runr g G.I. wire	tal mers income	363.60 176.70 540.30 27.015 567.32 in positiciduding coecification 147.00 162.00 309.00	M M M M M M M M M M M	•	/M-Rs.	31	,429 /	100							
al piles al piles olying fit	Wastage ting and tiple with	e and specification of the spe	fication a service of the service of	sho and a x x x x x x x x x x x x x x x x x x	3.60 3.5.000 5 mm dia ills or 38 r comp of E / I. 24.50 27	% % a ba sw blete	Total Qty  Total Qty  amboo runr g G.I. wire	tal mers income	363.60 176.70 540.30 27.015 567.32 in positicidading coecification 147.00 162.00 309.00	M M M M M M M M M	•	/M-Rs.	31,	,429 /	100							

ular sub	200		and their		hoa/ B	ickba	t or sto	ne fill	ter un	ider bri	ck pitch	ing				:4					2		
bulder pitch	ning in s	one of	appr	on in	luding	light	rammin	g etc.	all co	mplete	ob as	per											
		3 F	ecific	ation	and di	rectio	n of E /	le .					-		-				*		111		
						_	/		1.1.	ŽĒ.	M³	Т.	_		_						-		
3.00		× 1.	_		1.000		L.	1	1 7	.75			3_	93						•			
-2.50	15	× 1					tow			130		77		73									
6.50	<u>~</u>	× 3.	-	-	1800	_	1000	M)		2.70	1007.	79											
6.50	_	× 4.2	_	+-+	.750	1			-	0.72 <b>\</b> 90	M3	-											
3.00		× 1.5	_	1	200:	+					1.2	$\dashv$											
22.50	_	× 1.6	_	-	.725	_	1-1-			5.10		20-			,	ń	Si.						
14.50	_	× 2.0	-	-	.000	_	10	W	-		310												
17.00	_	× 2.3		-	100	1 1	200	W)	-	-01-	CAST!	905 Z											
10.00		× 2.8	_	_	766	<del>3 ./</del>	90	-	= <del>50</del>		574	2											
5.20		× 1.0	_	-	400 (	+++	0	-	= <del>2.(</del> = 3.2		0.	1	7.										
6.30	- 1	× 1.30	_	_	400	400	15	-	3.6		NO 0	Ø	4									•	
14.80		2.50	$\rightarrow$	-	300	Ħ		_	- 5.6		Mi	$\exists$				2							
4.30	-	2.60	_	-	400 200	1.	7	_	7.3	-	MO	07	7										
4.50		1.00	-+	-	100	<b>0.</b> (	7.5		2.4		M'	9/											
• 6.00 • 15.00	= 1	2.05	-+	10.	300				9.2	_	M <sup>2</sup>	1											
2.00	7	1.00	-	-	100	+		-	0.60	_	M <sup>3</sup>	-											
3.00	<u> </u>	1.00		0.3	27100	+			0.7	_	M <sup>3</sup>	1											
3.00		1.50	$\pm$	0.6	-	1			2.9	-	IVI <sup>3</sup>	1					- ~	~		4.5			
5.70	I	2.00	1.	0.4				-	5.36		M³	1				1,87,	180	1					
40.70		2.00	17	J	-		1 -	Total	233.8	*	M¹@	P.c	2168.2	2 /M³-R	s	-5,07,005			Rs. 1260.0	ю /м³	-Rs.	29.4	60 /-
7	$\neg \Box$		T	F		-6	tu	811	+=7	~		5	915	housan	nd						usand		
						T	0				GI	RAND	TOTAL	Rs.	_	5,93,348 /-	1,8		8910TA	L Rs.		41,0	13 /-
ADD GOO			VICE	TAX		1		П		2.00				Rs.	1	71,202 /-	22	.5	35				
ADD LABO		SS	+	_		+		+		1.00	<b>%</b>	-	_	Rs.		- <del>5,933</del> /-	18	7	8				
GRAND T			+			+.		+		+			Rs.	Rs.	14	41,013 /- ,496 /-	9	0 9	2				
JOIONED 1	UIAL							LL.		-		_	٦5.		. 1 1,	,-30 /-	· 12 4	4					
					4	1		-	-			S	ay Rs.		- 4	11,500 /	-		÷ ,			- 12 12	
W.						1		_	7	•			.,,		7	Ofal:	- 1	7 5	21 '	9	41		
30.10.	21.					1		0	۱۰	21					1	-		-1	-,		1/		
ineer	/!		•	_		بلر		201	1	5		_		_					-		_/		
Section .							nt Eng. s, Sub										. %		Exe	ecutive	Engine	er	

Measurment checked and Varified

06/142/ 6/12/2/ 06/142/ 6/12/2/

कार्यपाल अमियेता, व भ्राव कार्व विव, कार्य समेडल्प - विदील के हारा समिविन के कावार पर

post facto T18 for Rs, 2,21,294/- (Rupers two Lakh twenty one Thousand And two Hundred Mity Fours only

Superintending Engineer
W.D. (W) CARCLE, DARBHANGA

## Inspection Report of Flood Damage work

Name of PIUs:- Madhubani

Name of Block/ Road:- Khajauli/T03 to Thengha

## A. For Road

- 1. Damage Location Chainage: 500 to 400 700 to 897 4.

  2. Damage Length :- 146.304.

  3. Nature of Damage :- Road court stile stope flower

4. Details of Restoration Works

- i. Material being used in Restoration works:- Brick Bat \
- ii. Equipments's/Tools being used in Restoration works:-
- iii. Procedure taken up in Restoration works:- Brick Bat Filling
- iv. Restored Length:-

## For Bridge В.

- 1. Damage Location Chainage:-
- 2. Damage Length

3. Nature of Damage

- 4. Details of Restoration Works
  - i. Material being used in Restoration works:-
  - ii. Equipments's/Tools being used in Restoration works:
  - iii. Procedure taken up in Restoration works:-
  - iv. Restored Length:-

Satistacto Signature

(Name of Inspection)