



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILED PROJECT REPORT FOR EMARGENT REPAIR (FDR)

YEAR (2021-2022)



DISTRICT	:-	MUNGER
BLOCK	:-	BRIYARPUR
NAME OF ROAD	:-	NH-80 TO AMAIYA PIPARA ROAD ASARGANG
TOTAL LENGTH OF ROAD	:-	1.300 KM
PART-A TOTAL COST OF EMERGENT REPAIR	:-	8.03 Lac
AVERAGE COST PER KM	:-	618 Lac
PART-B TOTAL COST OF 5 YEAR ORDINARY MAINTENANCE	:-	0.00 Lac
TOTAL COST OF PROJECT	:-	8.03 Lac

FORWARDED BY:

EXECUTIVE ENGINEER
PWD (W) DIVISION, MUNGER
MUNGER

DETAILED PROJECT REPORT FOR EMARGENT REPAIR (FDR)
YEAR (2021-2022)

GENERAL ABSTRACT OF COST

Block:--BRIYARPUR

District:--MUNGER

Length of Road:-- 1.300 KM

Name of Road:-- NH-80 TO AMAIYA PIPARA ROAD ASARGANG

SL. No.	Item of Work	Amount
A	COST OF EMARGENT REPAIR	6.97 Lacs
B	ADD 1% LABOUR CESS ON EMERGENT REPAIR	0.07 Lacs
C	ADD 12% GST ON EMERGENT REPAIR	0.84 Lacs
D	ADD 10% SEGNIORAGE FEE ON EMERGENT REPAIR	0.16 Lacs
E	TOTAL COST OF EMERGENT REPAIR	8.03 Lacs
F	AVERAGE COST PER KM	6.18 Lacs
G	FIVE YEAR MAINTENANCE COST INCLUDING LABOUR CESS & GST	0.00 Lacs
TOTAL COST FOR EMERGENT REPAIR OF ROAD		8.03 Lacs


1.11.21
Junior Engineer
RWD (w) Division,
Munger


11/11/21
Asstt. Engineer
RWD (w) Division, Munger


11/11/21
Executive Engineer
RWD (w) Division,
Munger

Verified &
found correct

25.11.2021
E.E. Sheikhyama

Ref. E.E. Letter No. 1513 dt. 10.12.21
Technically Sanctioned for Rs. 8.03 lakh
(Rupees Eight lakh three
thousand.....) Only.
for construction work & 5 Years Maintenance.
certified copy

sd
10/12/21
Superintending Engineer
Rural Works Department
Works Circle, Munger
Superintending Engineer
Rural Works Department
Works Circle, Munger

पत्रांक 1733 मृग /
प्रेषक,

शेखपुरा, दिनांक 25.11.2021 /

कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, शेखपुरा।

सेवा में,

अधीक्षण अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य अंचल, मुंगेर।

विषय:- वर्ष 2021-22 के बाढ़ में क्षतिग्रस्त पथों को मोटरेबुल करने हेतु किये गए कार्य की जाँच प्रतिवेदन समर्पित करने के संबंध में।

प्रसंग:- भवदीय पत्रांक-1162 दिनांक 16.11.2021.

महाशय,

उपर्युक्त विषयक प्रासंगिक पत्र द्वारा प्राप्त निदेश के अनुपालन में सूचित करना है कि ग्रामीण कार्य विभाग, कार्य प्रमण्डल, मुंगेर एवं खड़गपुर-तारापुर अन्तर्गत कराये गए का मात्र 01-01 पथ में मोटरेबुल कार्यों की शत प्रतिशत जाँच सहायक अभियन्ता श्री अनिल कुमार के साथ किया गया। जाँचोपरान्त निम्नांकित पथों का स्थल निरीक्षण प्रतिवेदन पत्र के साथ सलंग्न कर अग्रेत्तर कार्रवाई हेतु समर्पित किया जाता है :-

क्र० सं०	पथ का नाम
1.	बरियारपुर प्रखण्ड अन्तर्गत एन०एच०-80 से अमैया पिपरा पथ-असरगंज तक पथ।
2.	एल०९८ तुलसीपुर-लोहरा न्यू ब्रीज से पकड़ी, पैकेज संख्या-BR-22R-126

अनु०:- स्थल निरीक्षण प्रतिवेदन-2 अदद।

किशोरभाजन
25.11.2021
कार्यपालक अभियन्ता
ग्रा०का०वि०, कार्य प्रमण्डल,
शेखपुरा

स्थल निरीक्षण प्रतिवेदन

वर्ष-2021-22 के बाढ़ में क्षतिग्रस्त पथों में कराये गए मोटरेबुल कार्य की जाँच।

पथ का नाम :- बरियारपुर प्रखण्ड अन्तर्गत एन0एच0-80 से अमैया पिपरा पथ असरगंज तक पथ।

पथ की लम्बाई :- 1.300कि0मी0

प्राक्कलित राशि :- 8.03/- लाख।

अधीक्षण अभियन्ता, ग्रामीण कार्य विभाग, कार्य अंचल, मुंगेर के पत्रांक-1162 दिनांक 16.11.2021 द्वारा प्राप्त निदेश के अनुपालन में आज दिनांक 25.11.2021 को ग्रामीण कार्य विभाग, कार्य प्रमण्डल, मुंगेर के अधीन बाढ़ से क्षतिग्रस्त पथ का निरीक्षण सहायक अभियन्ता, श्री अनिल कुमार के साथ वर्ष 2021-22 में बाढ़ में क्षतिग्रस्त पथ का कराये गए मोटरेबुल कार्य का स्थल निरीक्षण किया। जाँच के समय कार्य प्रमण्डल, मुंगेर के कनीय अभियन्ता श्री रविशंकर मंडल उपस्थित रहे।

उक्त पथ के निरीक्षण के दौरान पाया गया कि पथ में बने बड़े गड्ढों में Brick Bats से भरकर उसके उपर G.S.B. (gr.II-150mm) डालकर सम्पीडन का कार्य कराया गया है, जिसका शत प्रतिशत जाँच किया गया है, एवं उक्त पथ के प्राक्कलन एवं मापीपुस्त में दर्ज की गई मापी को कार्य स्थल के अनुसार पाया।


सहायक अभियन्ता
ग्रा0का0वि0, कार्य प्रमं0
शेखपुरा


कार्यपालक अभियन्ता
ग्रा0का0वि0, कार्य प्रमं0
शेखपुरा

Inspection Report For Flood Damage Work

1 Name of PIUs
2 Name of Block/Road - NH 80 to Amiya Pipana Road Asargang.

A For Road

1 Damage Location /Chainage :- 0.00 KM to 1.300 KM

2 Damage Location /Chainage :- 0.00 KM to 1.30 KM

3 Nature of Damage:-

i Material Being Used in Restoration Works:- Brick Bats & GSB Grr-2

ii Equipments /Tools being used in Restoration Works:- Tractor mounted grader, Three wheel 80-100KN static roller

iii Procedure Taken up in Restoration Works:- Tractor with Rejuvenator, water tanker 6 KL capacity. The Road was restored by doing the work of Brick Bats & GSB Grr-2

iv Restored Length :- 0.00 KM to 1.300 KM

B For Bridge

1 Damage Location /Chainage:-

2 Damage Length:-

3 Nature of Damage:-

4 Details of Restoration Works:-

i Material Being Used in Restoration Works:-

ii Equipments /Tools being used in Restoration Works:-

iii Procedure Taken up in Restoration Works:-

iv Restored Length :-

 25.11.2021

Name of Inspector

Executive Engineer

R.W.D Works Division Mungor Sheikhupura