

Name of work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/work -	for	to	molenpur	to	
	Argham	via	malpur		
Authority,	E E R-wid	works			
	division	Phamdah.			
①	Providing Labour	for driving	62 MM		
	to 75 MM dia	bamboo piles			
	Including cutting	to in proper			
	size and	shoes . etc			
	do - do .	comp job			
	2 x 30 x	3.0 =	180 M		
	2 x 30 x	3.0 =	180 M		
	1 x 23 x	3.0 =	69 M		
					429 M
②	Supply Fitting and fixing of				
	Bamboo 62 MM to 75 MM dia				
	Runners fixed at every				
	vertical pile with nails				
	2 x	3 x 30 =	180 M		
	2 x	3 x 30 =	180 M		
	2 x	3 x 23 =	69 M		
					429 M
	Continuation				

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
③ providing and fixing in position split bamboo woven clackeri					
do - do all comp jobs.					
		3 X 30X	1.50		135 m ²
		1 X 30X	1.50		45 m ²
		1 X 23X	1.50		34.50 m ²
					214.50 m ²
④ providing Laying & compaction of Local Sand P.H. the empty cement bag and Plaster work site					
		2X 30X	0.60X	0.90	32.40 m ³
		2X 30X	0.60X	0.90	32.40 m ³
		1 X 23 X	0.60X	0.90	12.42 m ³
					77.22 m ³
		$2 \times \frac{77.22 \text{ m}^3}{0.034} = 2274 \text{ bag}$			
		limit to 2262 bag			
⑤ providing Laying & spreading of Aricae bats compaction with hammer do-do comp jobs					
		4 X 30X	(0.90 + 1.10 + 1.75 + 1.25 + 1.50)		
		X	(0.30 + 0.50 + 0.60 + 0.85)		
		4 X 30X	1.30 X 0.60		93.60 m ³
		1 X 23 X	(0.90 + 1.10 + 1.75 + 1.25 + 1.50)		
		X	(0.30 + 0.50 + 0.60 + 0.85)		
		1 X 23 X	1.30 X 0.60		17.94 m ³
					111.54 m ³

Continuation

10/10/2021
J.E.
Executive Engineer
Rural Works Department
Works Division Dhamdaha (Punjab)

Particulars	Details of actual measurement				Contents of area
	No.	L.	D.	D.	
<u>ABSTRACT of work</u>					
N/Work- For to Mangapur to Anglari via Malpur					
Authority- E. Z. R. W. D. works Division Dharmadala.					
(1) Providing bamboo piles including Labour for cutting of bamboo 75 mm dia bamboo piles					
429.0 m	P - (1)				
@ 52.64/m				Rs 22583.20	
(2) Providing & fixing of split bamboo woven checker in position with 20 swg 4.5 wire do. do. w.p. 703					
24.50 m ²	P - (2)				
@ 458.11/m ²				Rs. 98265.20	
(3) supply fixing and fixing of 62 mm to 75 mm dia Bamboo Runners in position at fixed at every vertical piles do. do. w.p. 703					
429.0 m	P - (3)				
@ 30.12/m				Rs 12921.60	

Continuation

Rs-133769.20

Date: 03.12.21 Inspection Report for flood damage work (Year 2021-22)

1. Name of PIUs- Dhamdaha

2. Name of Block/Road- Rupauli - 1032 - Mohanpur to Anjhan
via malpur (VR32)

A. For Road

1. Damage Location/Chainage :

2. Damage Length : - 143M

3. Nature of Damage : side crust cutting due to flood

4. Details of Restoration :

i Material being used in Restoration :

bamboo pile, sand bags, Bstex bags

ii Equipment/Tools being used in Restoration works:

excavator, JCB,

iii Procedure taken up in Restoration works :

manually

iv Restored Length :

143M (25,54,760) m

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration :

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works :

iv Restored Length :

संतोष प्रद

Signature of JE/AE/EE

03.12.21
Executive Engineer,
Rural Works Department,
Works Division Dhamdaha (Purnea)

Signature

(Name of Executive Engineer
in Charge of Works) Division
PURNEA