

I



ग्रामीण कार्य विभाग



(बिहार सरकार)

क्षतिग्रस्त पथ का नाम

(Kushamar)

SH To Hudra

(Estimated Cost:- ~~1.52885~~ Lakh)

91,643-00

ग्रामीण कार्य विभाग,
कार्य प्रमंडल- फुलपरास।

प्रकल्प - खुलेना

Inspection Report for Flood Damaged Work in the year 2021-22

Date of Inspection :- 1/5/22 Name Of PIU:-RWD, Works Division, Benipatti
Name of Block :- KHUTAUNA
Name of Road :- SH (Kushmer) To Andra
For Road :-


1. Damage Location/ Chainage :- 0m & 55m
2. Damage Length :- 55m
3. Nature of Damage :- pots patches.

4. Details of Restoration Works :-

- i. Material being used in Restoration Works Brick Bats
- ii. Equipment's/ Tools being used in Restoration Works Roller and Tractor
- iii. Procedure taken up in Restoration Works filling and compaction
- iv. Restored Length — 55m

Remarks :- Satisfactory.


Signature of JE/AE


Signature of E.E


1/5/22
AE

Detailed estimate For restoration of road From SH to Huobra

Under FDR 2021.

Abstract Of Cost.

1. Restoration of Road embankment using Brick Bats.....etc....

$\frac{41.25}{68.81}$ m3@Rs. 1874.91 /m3 = Rs. 77340.00 ✓
Add GST 12% = Rs. 1,29,013.00 ✓
Add LC 1% = Rs. 9280.80 ✓
@1032m3 x 10% = Rs. 15,481.00 ✓
Total = Rs. 773.40 ✓
Rs. 1,29,013.00 ✓
Rs. 9280.80 ✓
Rs. 15,481.00 ✓
Rs. 1,29,013.00 ✓
Rs. 1,52,885.00 ✓
Rs. 91,643.00 ✓
28.11.2021
J E

$\frac{350}{211/21}$

350
211/21

कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमाण लेखीपट्टी
के द्वारा FDR के सॉ-कोपेशन पत्रों - दिनांक - के आधार पर

Technically sanctioned for Rs:- 91,643.00 (Rupee - Ninty
One thousand six hundred. Forty three) only.

Superintending Engineer
RWD Work Circle, Darbhanga

Abhinav
05/05/22

(Kushagra)

ailed estimate For restoration of road From SH 1 to Huroda.

FDR 2021. Damage length 55m.

① Restoration of road embankment using brick bats.....etc.

Ch-D-55

$$\frac{1 \times 30.0 \times 0.0 + 3.75}{2} + \frac{0.5 + 0.4}{2} = 110.69 m^3$$

$$\frac{1 \times 25.0 \times 3.75 \times 0.4 + 0.2}{2} = 28.12 m^3$$

$$30 \times 3.75 \times 0.200 = 22.5 m^3$$

$$25 \times 3.75 \times 0.200 = 18.75 m^3$$

28.10.2021
JE

checked & pass

28-10-21
A

11/5/22
AE

350
211/21
Rk

Chand
15/12/21
AE

Damage length - 55 m
Damage quantity - 41.25 m³

Chand
11/5/22
21E
15/12/21
AE
Bisfi

27/11/21
08.5.22
EE
Amit Path.