

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Samsatipur

2. Name of Block – Khembar

3. Name of Road/Bridge – Bargawan Creek to Shabdan Ghat

A. for Road

1. Damage Location/Chainage : 1st Km, 2nd Km

2. Damage Length : 230 m

3. Nature of Damage : Embankment cut, Ditches

4. Details of Restoration Works :

i. Material being used in Restoration works : Bricks bats, sand bag & Bamboo

ii. Equipments/Tools being used in Restoration Works : labour, tractor

iii. Procedure taken up in Restoration works :

iv. Restored Length : 230 m

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

[Signature]
15/4/22

J.E.

[Signature]
18/4/22

A.E.

[Signature]
20.4.22
Executive Engineer,
R.W.D. Works Division,
Samsatipur

[Signature]
20/4/22
Signature
(Name of Inspector)
E.B. Baling