

Inspection Report for Flood Damage Work

Date.:

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Samastipur

2. Name of Block – Samastipur

3. Name of Road/Bridge – Dhurdakh Middle School to NH nohampur Road

A. for Road

1. Damage Location/Chainage : 0.600, 0.850, 1.1. KM

2. Damage Length : 0.50 KM

3. Nature of Damage : Surface Damage due to flood & heavy rainfall & water logging.

4. Details of Restoration Works :

i. Material being used in Restoration works : Brick Bat, G.S.D.

ii. Equipments/Tools being used in Restoration Works : Roller, tractor,

iii. Procedure taken up in Restoration works : Rolling.

iv. Restored Length : 0.50 KM

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

Sanjiv
20/4/22

J.E.

A.E.

20/4/22
Executive Engineer,
R.W.D. Works Division,
Samastipur

[Signature]
Signature
(Name of Inspector)