

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Modhepur

Name of Road :- Lilga - Tengraha

A. For Road

1. Damage Location Chainage :- 900 to 1000 & 1100 to 1200
2. Damage Length :- 0.105 Km
3. Nature of Damage :-
4. Details of Restoration Works

- i. Materials being used in restoration works:- Brick - Bat's
- ii. Equipment's/Tools being used in Restoration works:- Tractor & JCB
- iii. Procedure taken up in Restoration works:- 80.57 cum
- iv. Restored Length:- ~~0.105 Km~~ 70.8 m

B. For Bridge

1. Damage Location Chainage :-
 2. Damage Length :-
 3. Nature of Damage :-
 4. Details of Restoration Works
- i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-


C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

Signature of JE/AE/EE


26/04/22
JE


23/4/22
RR


26/4/22

Signature
(Name of Inspection)

L2159 - Tengraha.

Schedule XLV-Form No. 134

Jhgrjthgr pye

DIVISION

M ad h e p y e

SUB-DIVISION

MEASUREMENT BOOK

2036

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of Cost					
① p.v & Filling b.m.R bats in ditches / damaged embankment ———— C/I					
80.57 m ³ D.V.T.M.B.P. - ①					
@ Rs 2004.96/m ³					Rs - 161539.63
					Rs - 161539.63
Add 12% GST					Rs - 19384.76
Add 1% L.C					Rs - 1615.40
					8314.00
Add 5% Fee 10%					Rs - 8564.59
					190854.60
Total					Rs - 191104.38
					190855.00
Say					Rs - 191104.38

Rs. 190855.00

A. B. S. S.

7/5/2022
A.C.J. A. S. S.
10/05/2022
J.E.

Continuation