

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Maolhepur

Name of Road :- Loyg-Bheja Road to South 401

A. For Road

1. Damage Location Chainage :- ch. 200 to 900m

2. Damage Length :- 69 m

3. Nature of Damage :-

4. Details of Restoration Works

i. Materials being used in restoration works:- Brick Bats

ii. Equipment's/Tools being used in Restoration works:- Tractor

iii. Procedure taken up in Restoration works:- 42.12 cum

iv. Restored Length:- 69m 66.50m

B. For Bridge

1. Damage Location Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works

i. Materials being used in restoration works:-

ii. Equipment's/Tools being used in Restoration works:-

iii. Procedure taken up in Restoration works:-

iv. Restored Length:-

C. Requirement Of New CD/ Bridges

i. Name of Road:-


ii. Location/ Chainage:-

iii. Type of CD Work/ Length required:-

Signature of JE/AE/EE


23/4/22
R/E


28/04/2022
JE

— S —

Signature
(Name of Inspection)

L048-BHE7A ROAD TO SOUTH TOL

Schedule XLV-Form No. 134

JHANJHARPUR DIVISION

MADHEPUR SUB-DIVISION

MEASUREMENT BOOK

2034

Name of work—

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.


(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work:- mortable of the Road from L048-Bheja Road to South Tol under FDR					
Agency:- Departmental Work					
Authority:- E.E. RWD, Jhaujharpur					
Block:- Madhepur					
Record Measurement					
① providing and filling brick bats in ditches/ damaged embankment — E.I.T.					
$1 \times 7.0m \times \frac{0.30+0.45}{2} \times 0.30 = 0.79m^3$					
$1 \times 23.0m \times 0.30m \times 0.250 = 1.73 "$					
$1 \times 36.50m \times 3.10m \times \frac{0.30+0.40}{2} = 39.60 "$					
-66-50m					
Total = 42.12 m ³					
APD G/S/2022 AC					
DA/MSD 06/05/2022 S-E					

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of cost					
① Providing and filling brick bats in ditches/damaged embankment — E.I.D.					
2.12 m ³ A.V.T.M.B.P. ①					
@ 2004.96/m ³ —				RS.	84448.92
				RS.	84448.92
Add 12% L.S.T (+)				RS.	10133.87
Add 1% L.C.S.S (+)				RS.	844.49
					4346.78
Add 10% S. fee (+)				RS.	4477.36
				RS.	99904.64
					99774.06
Say				RS.	99905.00

RS. 99774.00


 7/5/22
 A.C.

J.P. Singh
 07/05/22
 J.P.