

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- *Madhepur*

Name of Road :- *L052 - Bhargawan Tomusohani Mushari*

A. For Road

1. Damage Location Chainage :- *00 to 950 m*
2. Damage Length :- *122 m*
3. Nature of Damage :- *Flood*
4. Details of Restoration Works
 - i. Materials being used in restoration works:- *Brick bats*
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:- *122 m - 173.65 m*

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

grad. 15,

*Chandellay
28/04/22*

Signature of JE/AE/EE

*3036
20/4/22
ER*

28/4/22

Signature
(Name of Inspection)

2052- BHAR BHAN TOMUSAHAE (NR49)

Measurement Book

Schedule XLV-Form No. 134

JHAAJHAE & PUE

DIVISION

MADH & PUE

SUB-DIVISION

2020

(These four lines should be repeated at the commencement of the measurements relating to each work).

[illegible]

Scanned with CamScanner

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of cost</u>					
① providing and laying filling brick bats in ditches/damaged embankment — c.I					
173.65 m ² @ 11.75 m ² — ①					
Rs. — 2004.96/22 Rs.					348/61.30
				Rs.	348/61.30
Add 12% GST (+) Rs.					41779.36
Add 1% L.Cess (+) Rs.					348/1.61
Add 10% S. Fee (+) Rs.					17920.68
					18452.99
				Rs.	411342.95
				Rs.	411881.16

Say Rs. 411881.00

Rs. 411343.00

A. B. Shrivastava

7/5/2022
AES. A. H. S.
09/05/2022
SE