

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Madhepur

Name of Road :- Main Road Daldal to Mahato Tol

A. For Road

1. Damage Location Chainage :-
2. Damage Length :- 108.50 m
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick Bats
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:- 111.03 Cum
 - iv. Restored Length:- 109m

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-


C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

Signature of JE/AE/EE


26/04/22
JE


22/4/22
KR



Signature
(Name of Inspection)

Schedule XLV-Form No. 134

Main Rd Daldal to Mah to Tol

Jharkhand Puz

DIVISION

Midhepuz

SUB-DIVISION

MEASUREMENT BOOK

2056

1

Name to work—
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Mortable					
of the Road from					
Main Rd Dada to					
Mah to Tol.					
Agency:- Departmental work					
Authority:- E.E. RW Dithan Thapya					
Block:- Madhepura					
Record measurement					

① Plv & Felling work					
bed in ditches /					
damaged embankment					
E.M.					
1x4.06m	$\times \frac{3.0+3.30}{2}$	$\times 0.60$	=	7.56 m ³	
1x7.00m	$\times \frac{1.1+0.80}{2}$	$\times 0.15$	=	1.00 "	
1x30.00m	$\times \frac{3.0+3.30}{2}$	$\times \frac{0.3+0.4}{2}$	=	34.13 "	
1x30.00m	$\times \frac{2.50+3.0}{2}$	$\times 0.30$	=	24.75 "	
1x30.00m	$\times \frac{3.00+3.25}{2}$	$\times 0.45$	=	42.19 "	
1x8.00m	$\times \frac{1.0+0.75}{2}$	$\times 0.20$	=	1.40 "	
109.4			=	111.03 m ³	
<i>Alpina</i> 7/5/22 A.E. <i>MAA</i> 09/05/22 J.E.					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	Abstract of Cost				
① P.W. Filling brick bank in ditches damaged embankment ————					611
11.03 m ³ B.R.T.M.G.P. — ①					
@ Rs 2004.96/m ³				Rs -	222610.71
				Rs -	222610.71
Add 12% GST				Rs -	26713.29
Add 1% L.C				Rs -	2226.11
					11458.3
Add S. Fee (11.03 x 1032 x 10%)				Rs -	11802.49
					263008.40
				Total Rs -	263352.60
					263008.40
				S.G. Rs -	263353.10
				Rs -	263008.40

[Signature]
7/5/22
A.C.

[Signature]
07/05/22
J.E

by:
e Er
Div