

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- *Madhepur*

Name of Road :- *PMGSY Road to Lahwan School*

A. For Road

1. Damage Location Chainage :-
2. Damage Length :- *65.00 m*
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- *E/W & Brick Bat* ^{BF}
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:- *65 m - 195.00 m³⁷ E/W*

B. For Bridge

1. Damage Location Chainage :- *55 m*
2. Damage Length :- *1 m*
3. Nature of Damage :- *flood*
4. Details of Restoration Works
 - i. Materials being used in restoration works:- *E/W*
 - ii. Equipment's/Tools being used in Restoration works:- *Tractor*
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:- *pmgsy Road to Lahwan school*
- ii. Location/ Chainage:- *55 m*
- iii. Type of CD Work/ Length required:- *slab culvert - 2x6x3m*
— 5 —

30/04/22
Signature of JE/AE/EE *2056*
24/4/22
RR

31/4/22
Signature
(Name of Inspection)

Schedule XLV-Form No. 134

PMGSY Road to Lahwan School

Jhanjharpur

DIVISION

Madhepur

SUB-DIVISION

2094

MEASUREMENT BOOK

① construction of

embankment with approved material

$$1 \times 20.00 \text{ m} \times 3.00 \text{ m} \times \frac{2.0 + 1.50}{2} = 105.00 \text{ m}^2$$

$$1 \times 15.00 \text{ m} \times 3.00 \text{ m} \times 2.00 \text{ m} = 90.00 \text{ m}^3$$

$$\textcircled{1} f_x = 195.00 \text{ m}^3$$

Shield

7/5/20
A/E

07/05/22

5.6

Scanned with CamScanner

[illegible]