

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Jhanjharpur

Name of Road :- Kheer Madanpur to Sonbaraha Mahadalat

A. For Road

1. Damage Location Chainage (KM):- 0.00, 0.050, 0.2, 0.250, 0.3, 0.35, 0.345, 0.700,
0.8, 0.85, 0.9
2. Damage Length :- 194 Mtrs.
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Block bats
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:- 155 m - 160.0/m³

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

grad 1 - 'S'

Chandlary
29/04/22

Signature of JE/AE/EE

3036,
22/4/22
FE

J
29/4/22

Signature
(Name of Inspection)

Schedule XLV-Form No. 134

Khoir Madanpur to Sonbarska Mahadalit Toj

Jhanjharpur _____ **DIVISION**

madhepur _____ **SUB-DIVISION**

2086

MEASUREMENT BOOK

