

कार्यपालक अभियंता का कार्यालय,

ग्रामीण कार्य विभाग, कार्य प्रमण्डल हथुआ।

पत्रांक:- 498 अगु / हथुआ।

दिनांक:- 05/05/2022

प्रेषक,

कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, हथुआ।

सेवा में,

सचिव,
बिहार ग्रामीण पथ विकास अभिकरण,
बिहार पटना।


विषय :- राशि उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में कहना है कि बिहार ग्रामीण पथ नई अनुरक्षण नीति-2018 के तहत पंचवर्षीय अनुरक्षण अवधि के अधीन पथों में कराये गये त्रैमासिक अनुरक्षण कार्य हेतु राशि की अधियाचना उपलब्ध कराये गये प्रपत्र में सभी सूचनाओं के साथ अंकित कर समर्पित किया जाता है।

अनु0- यथोक्त।

विश्वासभाजन,


कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, हथुआ।

STANDARD FORMAT FOR ROADS QUARTERLY STATEMENT

PIU Name : **EE RND WORKS DIVISION - HATHUA**

1st Quarter

1	Name of the Road	Sisai to Bangra Via Rampur.		
2	Batch No.	RM/90/HAT/19/0008		
3	Project ID	31406902023		
	Total Length of Road (in Km)	10.608		
5	Length of Road to Meet Required Service Level [Completed length] (in Km) [1]	10.608		
6	No. of Total Quarter (ie 3 Months as a unit) in 5 years	20		
7	Ordinary Maintenance Cost as per Schedule [Agreement Amount for Maintenance] (in Lakh)	99.30247		
8	Quarterly Payment : 1/20 of Ordinary Maintenance Cost as per Schedule (in Lakh) [2]	04.96512.		
Compliance Criteria	Standard Job Description	Non- Compliance		Reduction Payments [6] = [3] / [1] * [2] * [4]
		Length Non-Compliant [3]	Weighted value for Payment Reduction (%) [4]	
I	PAVED ROADS (CARRIAGEWAY)	00	60%	00
II	SHOULDERS AND EMBANMENTS	00	10%	00
III	CROSS DRAINAGE INCLUDING CULVERTS AND BRIDGES	00	15%	00
IV	SIGNAGE AND ROAD SAFETY	00	10%	00
V	VEGATAION	00	5%	00
TOTAL PAYMENT REDUCTION FOR THE QUARTER (in Lakh) [5]				00
TO HE PAID FOR THE QUARTER / DEMAND (in Lakh) [6]				04.96512.

Date of inspection by E/I or his agent
Prepared by Contractor's self Control unit

Name and Designation of person inspecting road

Rishi Raj (AE)
22/03/22

(Signature)

Date 22.03.2022.

Signature of person inspecting road

Certify by E/I [signature] Date:-

22/03/22

Name of work : Sisai to bangra Via Rampur

Name of customer : ANANDMISHRA CONSTRUCTION PRIVATE LIMITED

(R)Rural Road

Good	Average	Poor
< 4000	4001 - 5000	> 5000

Date	Time	Test No	Distance(m)	Total Distance(m)	BUMH/cm	Speed(Km/Hr)	UM(mm/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
09/03/22	12-40:38	10	0	0	0.0 cm	20.0 Km/Hr	0.0 mm/Km	245	0.43	Good	26.4312825	N	84.07726837	E	Normal
09/03/22	12-42:54	10	100	100	36.0 cm	2.8 Km/Hr	3600.0 mm/Km	3602	4.08	Good	26.4306574	N	84.07132279	E	Normal
09/03/22	12-43:12	10	100	200	34.0 cm	16.4 Km/Hr	3400.0 mm/Km	3428	4.54	Good	26.4299250	N	84.0738306	E	Normal
09/03/22	12-43:26	10	100	300	36.0 cm	26.7 Km/Hr	3600.0 mm/Km	3602	4.98	Good	26.4294446	N	84.0740213	E	Normal
09/03/22	12-43:36	10	100	400	32.0 cm	34.5 Km/Hr	3200.0 mm/Km	3241	4.32	Good	26.4294443	N	84.0756693	E	Normal
09/03/22	12-43:45	10	100	500	37.0 cm	40.0 Km/Hr	3700.0 mm/Km	3709	4.87	Good	26.4292002	N	84.0766458	E	Normal
09/03/22	12-43:56	10	100	600	36.0 cm	29.3 Km/Hr	3600.0 mm/Km	3696	5.09	Good	26.4288912	N	84.0776224	E	Normal
09/03/22	12-44:11	10	100	700	32.0 cm	27.9 Km/Hr	3200.0 mm/Km	3241	4.32	Good	26.4289160	N	84.0780954	E	Normal
09/03/22	12-44:23	10	100	800	31.0 cm	28.5 Km/Hr	3100.0 mm/Km	3147	4.2	Good	26.4287844	N	84.0791330	E	Normal
09/03/22	12-44:34	10	100	900	37.0 cm	33.9 Km/Hr	3700.0 mm/Km	3709	4.87	Good	26.4283953	N	84.0804687	E	Normal
09/03/22	12-44:45	10	100	1000	32.0 cm	31.6 Km/Hr	3200.0 mm/Km	3241	4.32	Good	26.4287367	N	84.0814753	E	Normal
09/03/22	12-44:55	10	100	1100	33.0 cm	35.6 Km/Hr	3300.0 mm/Km	3334	4.43	Good	26.4286454	N	84.0823808	E	Normal
09/03/22	12-45:05	10	100	1200	31.0 cm	36.7 Km/Hr	3100.0 mm/Km	3147	4.2	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12-45:27	10	100	1300	34.0 cm	16.8 Km/Hr	3400.0 mm/Km	3428	4.54	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12-45:42	10	100	1400	31.0 cm	24.5 Km/Hr	3100.0 mm/Km	3147	4.2	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12-45:53	10	100	1500	36.0 cm	33.1 Km/Hr	3600.0 mm/Km	3615	4.76	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12-46:06	10	100	1600	39.0 cm	26.4 Km/Hr	3900.0 mm/Km	3996	5.09	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12-46:16	10	100	1700	34.0 cm	35.2 Km/Hr	3400.0 mm/Km	3428	4.54	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12-46:27	10	100	1800	31.0 cm	35.6 Km/Hr	3100.0 mm/Km	3147	4.2	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12-46:36	10	100	1900	22.0 cm	28.1 Km/Hr	2200.0 mm/Km	2305	3.18	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12-46:44	10	100	2000	33.0 cm	42.3 Km/Hr	3300.0 mm/Km	3334	4.43	Good	26.4289160	N	84.0828104	E	Normal

Name of work : Sisai to bangara Via Rampur

Name of customer : ANANDMISHRA CONSTRUCTION PRIVATE LIMITED

(R)Rural Road

Good	Average	Poor
< 4000	4001 - 5000	> 5000

09/03/22	12:46:55	10	100	2100	36.0 cm	36.3 Km/Hr	3600.0 mm/Km	36.15	4.76	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:47:08	10	100	2200	30.0 cm	26.7 Km/Hr	3000.0 mm/Km	30.53	4.09	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:47:19	10	100	2200	27.0 cm	33.1 Km/Hr	2700.0 mm/Km	27.73	3.75	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:47:28	10	100	2400	28.0 cm	38.1 Km/Hr	2900.0 mm/Km	28.60	3.98	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:47:37	10	100	2500	27.0 cm	41.4 Km/Hr	2700.0 mm/Km	27.73	3.75	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:47:47	10	100	2600	20.0 cm	35.2 Km/Hr	2000.0 mm/Km	21.17	2.95	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:47:57	10	100	2700	36.0 cm	36.0 Km/Hr	3600.0 mm/Km	36.15	4.76	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:48:06	10	100	2800	29.0 cm	40.3 Km/Hr	2900.0 mm/Km	29.60	3.98	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:48:16	10	100	2900	31.0 cm	36.0 Km/Hr	3100.0 mm/Km	31.47	4.2	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:48:30	10	100	3000	33.0 cm	25.7 Km/Hr	3300.0 mm/Km	33.34	4.43	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:48:47	10	100	3100	38.0 cm	20.2 Km/Hr	3900.0 mm/Km	38.96	5.09	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:48:57	10	100	3200	32.0 cm	34.2 Km/Hr	3200.0 mm/Km	32.41	4.32	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:49:06	10	100	3300	31.0 cm	32.0 Km/Hr	3100.0 mm/Km	31.47	4.2	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:49:22	10	100	3400	28.0 cm	28.0 Km/Hr	2800.0 mm/Km	28.66	3.87	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:49:33	10	100	3500	26.0 cm	32.7 Km/Hr	2600.0 mm/Km	26.79	3.64	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:49:43	10	100	3600	32.0 cm	36.7 Km/Hr	3200.0 mm/Km	32.41	4.32	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:49:54	10	100	3700	31.0 cm	30.5 Km/Hr	3100.0 mm/Km	31.47	4.2	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:50:05	10	100	3800	36.0 cm	34.9 Km/Hr	3600.0 mm/Km	36.15	4.76	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:50:14	10	100	3900	23.0 cm	37.4 Km/Hr	2300.0 mm/Km	23.98	3.3	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:50:22	10	100	4000	35.0 cm	44.5 Km/Hr	3500.0 mm/Km	35.21	4.85	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:50:33	10	100	4100	28.0 cm	38.3 Km/Hr	2800.0 mm/Km	28.66	3.87	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:50:42	10	100	4200	23.0 cm	37.4 Km/Hr	2300.0 mm/Km	23.98	3.3	Good	26.4289160	N	84.0828104	E	Normal

Name of work : Sisai to bangara Via Rampur

Name of customer : ANANDMISHRA CONSTRUCTION PRIVATE LIMITED

(R)Rural Road

Good	Average	Poor
< 4000	4001 - 5000	> 5000

09/03/22	1250.51	10	100	4200	31.0 cm	39.5 Km/Hr	3100.0 mm/Km	3147	4.2	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1251.04	10	100	4400	30.0 cm	27.7 Km/Hr	3000.0 mm/Km	3053	4.09	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1251.16	10	100	4500	35.0 cm	30.9 Km/Hr	3500.0 mm/Km	3521	4.65	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1251.30	10	100	4600	31.0 cm	26.4 Km/Hr	3100.0 mm/Km	3147	4.2	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1251.48	10	100	4700	37.0 cm	19.2 Km/Hr	3700.0 mm/Km	3709	4.87	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1252.02	10	100	4800	33.0 cm	26.7 Km/Hr	3300.0 mm/Km	3334	4.43	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1252.13	10	100	4900	30.0 cm	33.1 Km/Hr	3000.0 mm/Km	3053	4.09	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1253.13	10	100	5000	35.0 cm	6.6 Km/Hr	3500.0 mm/Km	3521	4.65	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1253.35	10	100	5100	32.0 cm	15.7 Km/Hr	3200.0 mm/Km	3241	4.32	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1253.52	10	100	5200	36.0 cm	20.8 Km/Hr	3600.0 mm/Km	3615	4.76	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1254.10	10	100	5300	33.0 cm	19.6 Km/Hr	3300.0 mm/Km	3334	4.43	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1254.38	10	100	5400	25.0 cm	13.1 Km/Hr	2500.0 mm/Km	2585	3.53	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1254.59	10	100	5500	30.0 cm	16.3 Km/Hr	3000.0 mm/Km	3053	4.09	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1255.26	10	100	5600	38.0 cm	14.1 Km/Hr	3800.0 mm/Km	3802	4.96	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1255.48	10	100	5700	35.0 cm	16.7 Km/Hr	3500.0 mm/Km	3521	4.65	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1256.08	10	100	5900	30.0 cm	17.8 Km/Hr	3000.0 mm/Km	3053	4.09	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1256.30	10	100	5900	24.0 cm	16.5 Km/Hr	2400.0 mm/Km	2492	3.41	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1256.47	10	100	6000	38.0 cm	19.6 Km/Hr	3800.0 mm/Km	3802	4.96	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1257.05	10	100	6100	36.0 cm	21.2 Km/Hr	3600.0 mm/Km	3615	4.76	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1257.25	10	100	6200	18.0 cm	17.2 Km/Hr	1800.0 mm/Km	1930	2.72	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1257.38	10	100	6300	28.0 cm	26.4 Km/Hr	2800.0 mm/Km	2866	3.87	Good	26.4289160	N	94.0828104	E	Normal
09/03/22	1257.51	10	100	6400	37.0 cm	29.1 Km/Hr	3700.0 mm/Km	3709	4.87	Good	26.4289160	N	94.0828104	E	Normal

Name of work		: Sisai to bangara Via Rampur													
Name of customer		: ANANDMISHRA CONSTRUCTION PRIVATE LIMITED													
(R)Rural Road															
Good		Average						Poor							
< 4000		4001 - 5000						> 5000							
09/03/22	12:58:06	10	100	6500	36.0 cm	25.7 Km/Hr	3600.0 mm/Km	36.15	4.76	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:58:24	10	100	6600	27.0 cm	19.0 Km/Hr	2700.0 mm/Km	27.73	3.75	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:58:36	10	100	6700	24.0 cm	29.4 Km/Hr	2400.0 mm/Km	24.92	3.41	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:58:46	10	100	6800	24.0 cm	36.9 Km/Hr	2400.0 mm/Km	24.92	3.41	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:58:54	10	100	6900	35.0 cm	43.2 Km/Hr	3500.0 mm/Km	35.21	4.65	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:59:02	10	100	7000	30.0 cm	44.5 Km/Hr	3000.0 mm/Km	30.53	4.09	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:59:13	10	100	7100	23.0 cm	34.9 Km/Hr	2300.0 mm/Km	23.98	3.3	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	12:59:33	10	100	7200	34.0 cm	18.5 Km/Hr	3400.0 mm/Km	34.28	4.54	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13:00:02	10	100	7300	36.0 cm	12.3 Km/Hr	3600.0 mm/Km	36.15	4.76	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13:00:18	10	100	7400	39.0 cm	22.8 Km/Hr	3900.0 mm/Km	39.96	5.09	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13:00:29	10	100	7500	23.0 cm	29.4 Km/Hr	2300.0 mm/Km	23.98	3.3	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13:00:40	10	100	7600	27.0 cm	33.3 Km/Hr	2700.0 mm/Km	27.73	3.75	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13:00:56	10	100	7700	32.0 cm	23.1 Km/Hr	3200.0 mm/Km	32.41	4.32	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13:01:12	10	100	7800	32.0 cm	22.9 Km/Hr	3200.0 mm/Km	32.41	4.32	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13:01:23	10	100	7900	31.0 cm	30.3 Km/Hr	3100.0 mm/Km	31.47	4.2	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13:01:32	10	100	8000	31.0 cm	40.9 Km/Hr	3100.0 mm/Km	31.47	4.2	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13:01:40	10	100	8100	24.0 cm	40.8 Km/Hr	2400.0 mm/Km	24.92	3.41	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13:01:50	10	100	8200	34.0 cm	37.0 Km/Hr	3400.0 mm/Km	34.28	4.54	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13:01:59	10	100	8300	32.0 cm	40.0 Km/Hr	3200.0 mm/Km	32.41	4.32	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13:02:08	10	100	8400	22.0 cm	42.3 Km/Hr	2200.0 mm/Km	23.05	3.18	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13:02:18	10	100	8500	23.0 cm	34.8 Km/Hr	2300.0 mm/Km	23.98	3.3	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13:02:27	10	100	8600	27.0 cm	40.5 Km/Hr	2700.0 mm/Km	27.73	3.75	Good	26.4289160	N	84.0828104	E	Normal

Name of work : Sisai to bangara Via Rampur

Name of customer : ANANDMISHRA CONSTRUCTION PRIVATE LIMITED

(R)Rural Road


Good	Average	Poor
< 4000	4001 - 5000	> 5000

09/03/22	13.02.37	10	100	6700	29.0 cm	36.5 Km/Hr	2900.0 mm/Km	2960	3.98	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13.02.46	10	100	6800	31.0 cm	36.3 Km/Hr	3100.0 mm/Km	3147	4.2	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13.02.56	10	100	6900	33.0 cm	40.0 Km/Hr	3300.0 mm/Km	3334	4.43	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13.03.11	10	100	9000	34.0 cm	24.9 Km/Hr	3400.0 mm/Km	3428	4.54	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13.03.26	10	100	9100	27.0 cm	23.9 Km/Hr	2700.0 mm/Km	2773	3.75	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13.03.40	10	100	9200	38.0 cm	25.2 Km/Hr	3800.0 mm/Km	3802	4.98	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13.03.56	10	100	9300	24.0 cm	21.8 Km/Hr	2400.0 mm/Km	2492	3.41	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13.04.06	10	100	9400	37.0 cm	29.0 Km/Hr	3700.0 mm/Km	3709	4.87	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13.04.18	10	100	9500	34.0 cm	35.6 Km/Hr	3400.0 mm/Km	3428	4.54	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13.04.28	10	100	9600	30.0 cm	38.2 Km/Hr	3000.0 mm/Km	3053	4.09	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13.04.38	10	100	9700	36.0 cm	36.7 Km/Hr	3600.0 mm/Km	3615	4.76	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13.04.51	10	100	9800	34.0 cm	27.7 Km/Hr	3400.0 mm/Km	3428	4.54	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13.05.05	10	100	9900	38.0 cm	25.7 Km/Hr	3800.0 mm/Km	3802	4.98	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13.05.18	10	100	10000	33.0 cm	27.6 Km/Hr	3300.0 mm/Km	3334	4.43	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13.05.31	10	100	10100	36.0 cm	28.2 Km/Hr	3600.0 mm/Km	3615	4.76	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13.05.46	10	100	10200	36.0 cm	23.9 Km/Hr	3600.0 mm/Km	3615	4.76	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13.07.46	10	100	10300	37.0 cm	3.3 Km/Hr	3700.0 mm/Km	3709	4.87	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13.08.10	10	100	10400	32.0 cm	15.0 Km/Hr	3200.0 mm/Km	3241	4.32	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13.09.01	10	100	10500	29.0 cm	6.8 Km/Hr	2900.0 mm/Km	2960	3.98	Good	26.4289160	N	84.0828104	E	Normal
09/03/22	13.09.22	10	100	10600	26.0 cm	17.1 Km/Hr	2600.0 mm/Km	2679	3.64	Good	26.4289160	N	84.0828104	E	Normal

12/06/22

R.L. 12/06/22

Name of Customer: ANANDMISHRA CONSTRUCTION PRIVATE LIMITED, Machine no: 19193, Road: Sisai to bangara Via Rampur, Date: 09/03/22, Section No: 10, Equation: $Y=0.936X+245.3$



[Signature]
09/03/22

[Signature]
09/03/22

[Signature]
09/03/22

Requisition Formlet for Scheme Head-MR-(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

RWD, Works Division Hathua

1 Year (1st Quarter)

Government Of Bihar

OM01

Rural Works Department

SUMMARY OF ORDINARY MAINTENANCE INSPECTION REPORT

Road From:- Sisai to bangra via rampur
Length of Road :- 10.608 Km
Inspector :- J.E RWD Sub Division : Bhore

To:-

**Executive Engineer
RWD, Works Division Hathua**

Date:-

Position :- J.E

No	standard Of Work Item	Work Unit	Unit Of Required in each Kilometer										Comments
	Name		1	2	3	4	5	6	7	8	9	10	
OM100	Sealed payment												No Pot Hole Found.
OM101	Pothole Patching	m ²	Nil	Nil	Nil	Nil							Not Surface Depression & Rut Patching Found
OM102	Surface Depression and Rut patching	m ³	Nil	Nil	Nil	Nil							No Crack sealing Found
OM103	Crack Sealing	Lm	Nil	Nil	Nil	Nil							No Loss Of Aggregates (Surface Ravelling) Found
	Surface Treatment												No Bleeding/ Flushing Required
OM104	(a) Loss of Aggregate (Surface Ravelling)	m ²	Nil	Nil	Nil	Nil							No Crocodile Cracking Found
	(b) Bleeding / Flushing	m ²	Nil	Nil	Nil	Nil							No Edge Repair Required
	● Crocodile Cracking	m ²	Nil	Nil	Nil	Nil							
105	Edge Repair	m ²	Nil	Nil	Nil	Nil							
106	Digouts	m ²	N.A	N.A	N.A	N.A							
107	Concrete pavement	m ³	N.A	N.A	N.A	N.A							
	Other activities												
OM200	Shoulder												No Edge Drop-Off Required
	Unsealed Shoulder												Not Required
OM201	(a) Edge Drop-Off	Lm	Nil	Nil	Nil	Nil							No Holding Water Found
	(b) Roughness, Scouring or Potholes	Lm	Nil	Nil	Nil	Nil							Not Required
	(c) Holding water	Lm	Nil	Nil	Nil	Nil							Not Required
OM202	Embankment Repair	M ³	Nil	Nil	Nil	Nil							Not Required
	Other activities (Rain Cuts)												
OM300	Drainage Including culverts major	Lm	N.A	N.A	N.A	N.A							Not Required
OM301	Surface Drains & Verge	No	Nil	Nil	Nil	Nil							Not Required
OM302	Culvert Cleaning	M ³	Nil	Nil	Nil	Nil							Not Required
OM303	Culvert and pit Repair	M ³	Nil	Nil	Nil	Nil							Not Required
	Other activities(Whilw washing)	M ³	Nil	Nil	Nil	Nil							

No	Standard Of Work Item	Work	Unit Of Required in each Kilometer										Comments
	Name	Unit	1	2	3	4	5	6	7	8	9	10	
OM400	Vegetation												
	Grass Control												
OM401	(a) Roadside- General Tidy	Ha	Nil	Nil	Nil	Nil							Not Required
	(b) Clear near Safety signs, kilometer posts and roadside furniture	Ha	Nil	Nil	Nil	Nil							Not Required
OM402	Tree and Shrub Management	No	Nil	Nil	Nil	Nil							Not Required
	Cutting Of Branches Of Trees	No	Nil	Nil	Nil	Nil							Not Required
	Cutting Of Shrubs From Road Way	No	Nil	Nil	Nil	Nil							Not Required
	Other activities (Trimming of Grass)	M ²	Nil	Nil	Nil	Nil							Not Required
OM500	Safety Signage and Road												Not Required
OM501	Signs Maintenance	No	Nil	Nil	Nil	Nil							Not Required
OM502	Guard Stones	Lm	N.A	N.A	N.A	N.A							Not Required
OM503	Distance Stones	No	N.A	N.A	N.A	N.A							Not Required
OM504	Road Marking	M ²	Nil	Nil	Nil	Nil							Not Required
	Other activities												Not Required

Amir
20/4/22

Ridwan
20/4/22

Amir
20/4/22