

Estimate for Restoration work of Road from Bisfi To Singhiya for the year 2021-2022 in Bisfi Block

Length-7.703 KM

NO.	Item of Work							
1	Labour for lying dry graded jhama khoa or Stone filter under Brick pitching in slope or apron including including light ramming etc. all complete as per approved design, specification and direction of E/I (Brick Bats)							
	Nos	Length	Width	Height	Quantity	Unit	Rate	Amounts
0.00 to 0.25 0 km	1	3.00	1.60	0.150	0.720			
	1	7.50	2.00 1.8	0.300	4.500	4.05		
	1	23.00	3.75 2.8	0.300	25.875	19.32		
	1	13.00	1.50	0.300 0.250	5.850	4.875		
	1	12.00	1.50	0.300	5.400			
	1	17.00	1.50	0.150	3.825			
	1	11.00	3.00 2.6	0.300	9.900	8.58		
	1	14.00	2.00	0.300	8.400			
4.80	1	183.00	2.50 2.1	0.300	137.250	52.50		
					201.720	Cum	1939.93	

2 = 225.50 MTR

Add 12% GST

Add 1% L/Cess

Add Signorage Fee (142-688x1032x10%) =Rs

total

107.67 =Rs

=Rs

=Rs

=Rs

46959-25065 =

3913 2083 =

20818 11112 =

463012

70, 15-047/32 =

Phanishay
JE
4/1/2021

RWD
Bisfi

Amrit
4/1/21

AE
RWD
Bisfi

Amrit
4/1/21

EE
RWD
Benipatti

Damaged length = 225.50 MTR.

Restored Qty = 107.67 M³

verified and found correct as per site condition

Amrit



A2

Amrit
10/02/22
E.E

Name of Road : — Bteti to Singhiga.

Post facto T/S awarded for Rs. 247138.
(Rs. Two lac forty seven thousand one
hundred thirty-eight only.)

Reference letter no. 233 dated 21/2/22
of E.C. Darbhanga-2


Superintending Engineer
RWD Works Circle, Darbhanga


(4)

22

Inspection Report for Flood Damaged Work in the year 2021-22

Date of Inspection :- Name of PIU :- RWD (W) Div. Darbhanga-2
Name of Block / PIU :- ^{Inspected} Bisfi (RWD(W) Div. Benipatti
Name of Road :- Bisfi To Singhia
For Road :-

1. Damage Location/ Chainage :- 0 to 4.80
2. Damage Length :- 225.50 Metre.
3. Nature of Damage :- Pot patch

4. Details of Restoration Works :-

- i. Material being used in Restoration Works — Brick Bats
ii. Equipment's/ Tools being used in Restoration Works — Tractor/Roller
iii. Procedure taken up in Restoration Works — Section with Compaction
iv. Restored Length — 225.50 Metre.

Remarks :-

Work found Satisfactory ~~inspected~~

Signature of E.E.

Signature of JE/AE

[Signature]
19/02/2022
JE