

FDR

NH 57 Bishaul Path to Dhanuk Tol Bishaul

Shedule XLV Form No. 134.

Jhanjhanpur

DIVISION

Jhanjhanpur

SUB-DIVISION

3062

Measurement Book

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Jhanjhar

Name of Road :- NH-57 Bishan path to Dhawak to Bishan

A. For Road

1. Damage Location Chainage :- 420.5m, 525m
2. Damage Length :- 115.5m
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick bats
 - ii. Equipment's/Tools being used in Restoration works:- Grader - (2011)
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:- 115.5m

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

Signature of JE/AE/EE

[Handwritten Signature]
20/4/22

[Handwritten Signature]
20/4/22
ER

Signature
(Name of Inspection)

[Handwritten Signature]
20/4/22