

(20)

Length : 8.276 KM

Block : BENIPATTI District: MADHUBANI Length : 0.453 KM

400091.00

~~62584.40~~

5215.37

~~21470.76~~

~~610807.22~~

	5188	67.00
	521536.69	
T 12% Rs=	62584.40	62264.2
Less 1% Rs=	5215.37	5189.2
5) Rs=	21470.76	21284.2
Total Rs=	610807.22	
TO - RS - 607604.20		

20/11/21

20/11/21

८५/१५१
३०.११.७१

H₂
10-12-2021
J.C

July 2012
A'E

20/12/22
E.E

Name of Road: - Akauli chhotol house
of Guni thakar to Akauli chamer tol madhya
Wdyalga.

Post-facto T/S accorded for Rs. ~~607604.00~~ 607604.00.
(Rs. Six Lacs Seven thousand six hundred four
only.)

Reference letter no. 233 dated 21/2/22
of EE darbhanga-2

Superintending Engineer
RWD Works Circle, Darbhanga

Inspection Report for Flood Damaged Work in the year 2021-22

Date of Inspection :- 20.12.21 Name of PIU :- RWD (W) Div. Darrhanga - 2

Name of Block :- Benipathi
:- Akuli chofatal House of Guni Thakur to Akuli
Chamatal Madhya Vidyalya.

Name of Road :-

For Road :-

1. Damage Location/ Chainage :- 200, 400 Mtr.

2. Damage Length :- 164 Mtr

3. Nature of Damage :- Breaches due to flood.

4. Details of Restoration Works :-


i. Material being used in Restoration Works :- Brick bats, Eastwork & Bamboos

ii. Equipment's/ Tools being used in Restoration Works :- Tractor


iii. Procedure taken up in Restoration Works :- Felling, compaction & Bamboo piling.

iv. Restored Length :- 164 Mtr

Remarks :- work found satisfactory


20.12.21
Signature of JE/AE


20/12/2021


20/12/21
Signature of E.E