

Estimate for Restoration work of Road from Satlakha Bisfi Road to Raghepura for the year 2021-2022 in Bisfi Block
Length-4.800 KM

NO.	Item of Work							
1	Labour for lying dry graded jhama khoa or Stone filter under Brick pitching in slope or apron including including light ramming etc. all complete as per approved design, specification and direction of E/I (Brick Bats)							
Ch	Nos	Length	Width	Height	Quantity	Unit	Rate	Amount
to Km	4	1.00	1.00	0.15	0.60			
	1	3.00	3.00	0.15	1.35			
	1	4.00	3.00	0.15	1.80			
	6	1.00	1.00	0.15	0.90			
	1	6.00	1.00	0.15	0.90			
	1	10.00	2.50	0.15	3.75			
	1	2.00	3.50	0.15	1.05			
	5	1.00	1.00	0.15	0.75			
	1	10.00	2.00	0.15	3.00			
	1	15.00	2.50	0.15	5.63			
	3	1.50	1.50	0.15	1.01			
	1	5.00	3.00	0.15	2.25			
	1	2.00	3.00	0.15	0.90			
	1	1.00	1.00	0.15	0.15			
	1	2.00	3.50	0.30	2.10			
	1	15.00	2.60	0.15	5.85			
	1	2.00	3.00	0.15	0.90			
	1	4.00	2.50	0.15	1.50			
	1	6.00	2.50	0.30 0.2	4.50 3.0			
	1	2.00	1.50	0.20	0.60			
	1	3.00	1.50	0.20	0.90			

1	2.00	3.50					
1	5.00	3.50	0.15	1.05			
1	10.00	2.00	0.15	2.63			
1	3.00	2.00	0.15	3.00			
1	5.00	3.50	0.15	0.90			
1	8.00	2.00	0.15	2.63			
1	4.00	1.50	0.15	2.40			
1	1.00	1.00	0.15	0.90			
1	3.00	2.00	0.15	0.15			
1	3.00	2.00	0.15	0.90			
2	3.00	1.50	0.20 0.1	1.80 0.45			
1	10.00	3.50	0.15	5.25			
2	2.00	1.00	0.15	0.60			
1	6.00	3.00	0.15	2.70			
1	4.00	3.00	0.15	1.80			
1	5.00	1.50	0.15	1.13			
1	3.00	3.00	0.15	1.35			
1	3.00	1.50	0.15	0.68			
1	2.00	2.00	0.15	0.60			
1	4.00	2.00	0.15	1.20			
			72.04	Cum	1939.93	134224.00	
						139748	

Add 12% GST
 Add 1% L/Cess
 Add Signorage Fee (72.04x1032X10%)
 Total 69.19

=Rs
 =Rs
 =Rs
 =Rs

16770 161072
 1397 13422
 7434 71402
 165349
 10 Rs - 158813 =

Quality
 JE
 RWD
 Bisfi

4/12/21
 AE
 RWD
 Bisfi


4/12/21
 EE
 RWD
 Benipatti

Damaged 1cylinder = 173.50 MTR.
 Restored Qty = 69.19 M3
 verified and found current c/c per site condition
 10/10/22
 EE

Name of Road:- Sattakra Bisti road to
Raghepura.

Post facto T/P awarded for Rs. 158813.00
(Rs. one lac fifty eight thousand eight
hundred thirteen only).

Reference Letter no. 233 dated 21/2/22
of EE Darbhanga-2


Superintending Engineer
RWD Works Circle, Darbhanga

Inspection Report for Flood Damaged Work in the year 2021-22

Date of Inspection :- Name of PIU :- RWD (W) Div. Darbhanga-2

Name of Block / PIU :- .. Bisfi (RWD (W) Div Benilpatti)
 Name of Road :- Satlakha Bisfi Road to Raghehpura

For Road :- 0 to 0.4 Km

1. Damage Location/ Chainage :- 79.50 Metre.

2. Damage Length :-

3. Nature of Damage :- Pot patch

4. Details of Restoration Works :-

i. Material being used in Restoration Works - Rich Bats

ii. Equipment's/ Tools being used in Restoration Works - Tractor / Roller

iii. Procedure taken up in Restoration Works - Section wise compaction

iv. Restored Length - 79.50 Metre.

Remarks :- Work found satisfactory.

Signature of E.F. 19/02/22

Signature of JE/AE

Mr. [Signature] 19/02/22
 JE AE