

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Jhanjharpur

Name of Road :- NH-57 - Bishaul

A. For Road


1. Damage Location Chainage :- 315 M
2. Damage Length :- 0.102 Km
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:- Tractor & JCB.
 - iii. Procedure taken up in Restoration works:- 35.663 m³
 - iv. Restored Length:- 0.102 Km.

B. For Bridge


1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:- (S¹)


23/4/22

Signature of JE/AE/EE


23/4/22
RR


2014
Signature
(Name of Inspection)

NH 57-BISHAUL (P.P.R.)

Schedule XLV-Form No. 134

Jhan Jhanpur

DIVISION

Jhan Jhanpur

SUB-DIVISION

3058

MEASUREMENT BOOK

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
(1) Providing and filling brick batts & ditches and damaged embankment including cost of brick batts and labour charge as per E/S					
Qty brick T.M.B.P. - 1(1)					
35.663 m ³ @ 2004 = 26/m ³				1	71503=00
Add 12% O.S.T.				6	8580=00
Add 1% L.C.				6	715=00
Add 10% S.F.				6	3680=00
					3791=00
(35.663 x 1032) x 10%				T.B	84589=00
				B	84478=00
84522					
84522					
A.E.					

$\frac{4.416}{10.05}$
 10.05
 A.E.