

Name of work—
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement.
 (These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work—Construction of					
C.A. work from M.M.G.S.Y.					
road Bank at Khatthi					
Hajjanta W.D. M.M.G.S.Y.					
(se Length—1.800KM)					
Agency—Progressive Engin					
Pvt Ltd A. L. G. 3/97					
Harun Nader					
Agreement No. 21/8-13-D					
M.M.G.S.Y. 2018-19					
Date of work—01/12/2018					
Date of Completion—31/11/2019					
Date of Measurement—28/11/2019					
①	4	Bending Reference			8 Nos
		pillar			
②	5	cleaning and Grubbing			
		road land—10			
Qty		1700 x 4.00			0.6842
③	2	Dismantling of structure			
		limb of			
		2 x 3.00 x 600-300			2 x 1.5 = 3.10m
④	7	Dismantling of			

Continuation

Continuation

Name of block - Contact Road from

Bankaliya - bolohatti

Horizon to lake under MM.4.54

Length - 1.80 K.M.

Name of Agency - Progressive Englon

Art - Ltd. At L.I. 4.3/97

Muniman Nagar Konkandap

Paina 20

Agreement NO - 21/S.B.D (MM.4.54)

Se - 2018-2019

Date of block order - 01/12/2018

Date of Completion - 30/11/2019

Date of Measurement -

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of Corp</u>					
(1/4) Providing Reference biller as per stand and database					
do do do					
8 Nos vide P.N. (12)					
@ 18 = 1493 = 46 / NW 15948 = 00					
(2/5) Cleaning and Grubbing road land including uprooting wild Vegetation, grass					
do do do					
58.10 vide P.N. (12)					
@ 18 = 48 = 72 = 70 / 10					
33165 = 00					
(3/6) Dismantling of existing, concrete link culvert bridge					
do do do do					
3.10 M ³ vide P.N. (12)					
@ 18 = 460 = 29 / M ³ 1427 = 00					
(4/7) Dismantling brick existing structure link culvert					
do do do					
@ 18 = 18290 = 00					
55.10 M ³ vide P.N. (12)					
@ 331 = 95 / M ³ 58830 = 00					

Continuation