

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सिवान-2

पत्रांक.....1634 अनु०..... सिवान, दिनांक 31/08/2022

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, सिवान-2

सेवा में,

नोडल पदाधिकारी
बिहार ग्रामीण पथ नई अनुरक्षण नीति-2018
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:- योजना शीर्ष बिहार ग्रामीण पथ नई अनुरक्षण नीति-2018 के तहत पूर्ण कराये गये पथों के अनुरक्षण कार्य का आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि योजना शीर्ष बिहार ग्रामीण पथ नई अनुरक्षण नीति-2018 के अन्तर्गत पूर्ण कराये गये पथों का अनुरक्षण कार्य के भुगतान हेतु विवरणी विहित प्रपत्र में तैयार कर इस पत्र के साथ संलग्न किया जा रहा है।

अतः अनुरोध है कि प्रपत्र के अनुसार आवंटन उपलब्ध कराने की कृपा की जाए। ताकि संवेदक के अनुरक्षण की राशि ससमय भुगतान किया जा सके।


अनु०-यथोक्त।

विश्वासभाजन


30/8.22

कार्यपालक अभियंता

ग्रामीण कार्य विभाग, कार्य प्रमंडल,
सिवान-2


30-8-22

Maintenance Requisition Formate for Scheme Head- MR (3054) Under

Name of Works Division:- Siwan-2

Sl.no.	Road Details			Actual Date of Completion	AA Details		Agreement							
	Name of Roads	Batch No.	Project ID		Main Work Amount (in Lakh)	Maintenance Amount (in lakh)	Main Work Amount (in Lakh)	Agreement-1	Agreement-2	Agreement-3	Agreement-4	Agreement-5	Total Maintenance	Length (in Km)
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
1	Harpur - Bikaur	RM/SI/SIW /20/0009	31406602023	18-06-2021	123.72	60.644	123.665	4.45311	5.80375	15.55633	9.23219	18.21068	53.25606	5.9
Total -----					254.33200	117.82400	254.18400						109.01000	12.50

Bihar Rural Road Maintenance Policy-2018

Sl.no.	Actual Maintenance Expenditure						Current Maintenance Demand (in Lakhs)										Remarks
	1st. Year Maintenance	2nd. Year Maintenance	3rd. Year Maintenance	4th Year Maintenance	5th Year Maintenance	Total Maintenance Expenditure	Length as per Bump Report	IRI As per bump Report	1st QTR Maintenance	2nd QTR Maintenance	3rd QTR Maintenance	4th QTR Maintenance	5th QTR Maintenance	6th QTR Maintenance	7th QTR Maintenance	Total	
1.	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
1	0.00	0.00	0.00	0.00	0.00	0.00	5.9	3839	2-6628	-	-	-	-	-	-	2-6628	

12/01/22
p.c

[Signature]
Executive Engineer
R.W.D. Works Division
Siwan-2
20-8-22

STANDARD FORMAT FOR ROADS QUARTELY STATEMENT

PIU Name :-

1	Name of the Road	Haripur to Bikanur		
2	Batch No.	RM/ST/SIW/20/009		
3	Project ID	31406602023		
4	Total Length of Road (in Km)	5.9km		
5	Length of Road to Meet Required Service Level [Completed Length] (in km) [1]	5.9		
6	No. of Total Quarter (ie 3 Months as a unit) in 5 years	01		
7	Ordinary Maintenance Cost as per Schedule [Agreement Amount for Maintenance] (in Lakh)	53.25606		
8	Quartely Payment : 1/20 of Ordinary Maintenance Cost as per Schedule (in Lakh) [2]	2.66280		
Compliance Criteria	Standard Job Description	Non-Compliance		Reduction Payment [6]=[3] / [1] * [2] * [4]
		Length Non-Compliant [3]	Weighted Value for Payment Reduction (%) [4]	
I	PAVED ROADS (CARRIAGE WAY)		60%	0.00
II	SHOULDERS AND EMBANKMENTS		10%	0.00
III	CROSS DRAINAGE INCLUDING CULVERTS AND BRIDGES		15%	0.00
IV	SIGNAGE AND ROAD SAFETY		10%	0.00
V	VEGETATION		5%	0.00
TOTAL PAYMENT REDUCTION FOR THE QUARTER (in Lakh) [5]				0.00
TO BE PAID FOR THE QUARTER / DEMAND (in Lakh) [6]				2.66280

Date of inspection by E/I or his agent prepared by Contractor's self Control unit

Name and Designation of person inspecting road

(Signature)

Date

Signature of person inspecting road

30/8/22
A.E.

30.8.22

EXECUTIVE ENGINEER
RWD, WORKS DIVISION
SIWAN-2

Requisition Format for Scheme Head - MTR (3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division :- Siwan-2

Government of Bihar

OM01

Rural works Department

SUMMARY OF ORDINARY MAINTENANCE INSPECTION REPORT

Road From- Harpur - Bikaaur

Length of Road: 5.9 KM

Period : From.....

Inspector: A.E RWD Sub Division, Andar

To: Executive Engineer

RWD Works Division Siwan-2

Date:

Position: A.E

Standard Work item		Work	Units of work required in each kilometre										Comments
S No	Name	Units	1	2	3	4	5	6	7	8	9	10	
OM100 Sealed Pavement													
OM101	Pothole Patching	m2	Nil	Nil	Nil	Nil							No. Pothole found.
OM102	Surface Depression and Rut Patching	m2	Nil	Nil	Nil	Nil							No Surface Depression and Rut Patching found
OM103	Crack Sealing	Lm	Nil	Nil	Nil	Nil							No Crack Sealing found
Surface Treatment													
OM104	(a) Loss of Aggregate (Surface Ravelling)	m2	Nil	Nil	Nil	Nil							No Loss of Aggregate (Surface Ravelling) found
	(b) Bleeding/Flushing	m2	Nil	Nil	Nil	Nil							No Bleeding/Flushing Required
	(c) Crocodile Cracking	m2	Nil	Nil	Nil	Nil							No Crocodile Cracking found
OM105	Edge Repair	m2	Nil	Nil	Nil	Nil							No Edge Repair Required
OM106	Digouts	m2	N/A	N/A	N/A	N/A							
OM107	Concrete Pavement	m3	N/A	N/A	N/A	N/A							
Other activities													
OM200 Shoulder													
OM201	Unsealed Shoulder	No											No Edge Drop off Required
	(a) Edge Drop off	Lm	Nil	Nil	Nil	Nil							Defects rectified within stipulated time.
	(b) Roughness, Scouring or Potholes	Lm	Nil	Nil	Nil	Nil							No Holding water found
	(c) Holding Water	Lm	Nil	Nil	Nil	Nil							No Embankment Repair Required
OM202	Embankment Repair	No	Nil	Nil	Nil	Nil							Defects rectified within stipulated time.
	Other Activite (Raincut)		3%	1%	2%	Nil							
OM300 Drainage including culverts major													
OM301	Surface Drains & Verge	Lm	N/A	N/A	N/A	N/A							Not Required
OM302	Culvert Cleaning	Lm											Culvert maintain within stipulated time

OM303	Culvert and Pit repair	m2	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
	Other activities (White Washing)	m2	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
	OM 400 Vegetation																			
	Grass Contorol																			Not Required
	a) Roadside-General Tidy	Ha	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
OM401	b) Clear near Safety signs, kilometre posts and roadside furniture	Ha	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
	Tree and shrub management	No	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
	Cutting trees	No	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
OM402	Cutting Shrubs	No	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
	Other activities (Trimming of Grass)	M2	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
OM500	Safety Signage and Road																			Not Required
OM501	Signs Maintenance	No	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
OM502	Guard Stones	Lm	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not Applicable
OM503	Distance Stones	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not Applicable
OM504	Road Marking	m2	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
	Other activities																			

Bidder

Appendix


Executive Engineer, Rural Work Department, Work
Division, Siwan-2

8/29/12
ATG
30.08.12
A.T

Handwritten signature

Name of work : Harpur - Bikaar	
Name of customer : MITHAILESH KUMAR SINGH	
(R)Rural Road	
Good	Average
< 4000	4001 - 5000
	Poor
	> 5000

Date	Time	Test No	Distance(m)	Total Distance(m)	BUWP(cm)	Speed(Km/Hr)	Ull(m/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction	Remarks
19/06/22	10:15:52	52	100	100	28.0 cm	2.5 Km/Hr	2800.0 mm/Km	2784	3.77	Good	26.174926	N	84.226582	E	Normal
19/06/22	10:16:17	52	100	200	30.0 cm	14.5 Km/Hr	3000.0 mm/Km	2964	3.99	Good	26.175123	N	84.2278087	E	Normal
19/06/22	10:16:39	52	100	300	26.0 cm	15.5 Km/Hr	2800.0 mm/Km	2803	3.55	Good	26.1752253	N	84.226932	E	Normal
19/06/22	10:16:59	52	100	400	32.0 cm	18.1 Km/Hr	3200.0 mm/Km	3145	4.2	Good	26.1753759	N	84.2257013	E	Normal
19/06/22	10:17:22	52	100	500	22.0 cm	16.0 Km/Hr	2200.0 mm/Km	2241	3.11	Good	26.1750135	N	84.2247705	E	Normal
19/06/22	10:17:52	52	100	600	31.0 cm	12.0 Km/Hr	3100.0 mm/Km	3055	4.09	Good	26.1741457	N	84.2243357	E	Normal
19/06/22	10:18:16	52	100	700	32.0 cm	14.5 Km/Hr	3200.0 mm/Km	3145	4.2	Good	26.1740484	N	84.2234563	E	Normal
19/06/22	10:18:38	52	100	800	25.0 cm	16.2 Km/Hr	2500.0 mm/Km	2512	3.44	Good	26.1739284	N	84.2223873	E	Normal
19/06/22	10:19:00	52	100	900	29.0 cm	17.0 Km/Hr	2900.0 mm/Km	2874	3.88	Good	26.1738214	N	84.2213678	E	Normal
19/06/22	10:19:22	52	100	1000	26.0 cm	16.3 Km/Hr	2600.0 mm/Km	2803	3.55	Good	26.1737070	N	84.2204447	E	Normal
19/06/22	10:19:45	52	100	1100	31.0 cm	15.5 Km/Hr	3100.0 mm/Km	3055	4.09	Good	26.1736422	N	84.2193384	E	Normal
19/06/22	10:20:12	52	100	1200	33.0 cm	13.2 Km/Hr	3300.0 mm/Km	3238	4.31	Good	26.1735322	N	84.2184381	E	Normal
19/06/22	10:20:37	52	100	1300	32.0 cm	14.4 Km/Hr	3200.0 mm/Km	3145	4.2	Good	26.1735888	N	84.2174997	E	Normal
19/06/22	10:21:04	52	100	1400	30.0 cm	13.3 Km/Hr	3000.0 mm/Km	2964	3.99	Good	26.1737795	N	84.2165689	E	Normal
19/06/22	10:21:29	52	100	1500	35.0 cm	14.1 Km/Hr	3500.0 mm/Km	3418	4.52	Good	26.1742449	N	84.2157755	E	Normal
19/06/22	10:21:52	52	100	1600	22.0 cm	15.7 Km/Hr	2200.0 mm/Km	2241	3.11	Good	26.1750746	N	84.2161112	E	Normal
19/06/22	10:22:16	52	100	1700	33.0 cm	15.3 Km/Hr	3300.0 mm/Km	3238	4.31	Good	26.1759825	N	84.2163553	E	Normal
19/06/22	10:22:53	52	100	1800	35.0 cm	9.8 Km/Hr	3500.0 mm/Km	3418	4.52	Good	26.1769629	N	84.2163782	E	Normal
19/06/22	10:23:17	52	100	1900	28.0 cm	14.8 Km/Hr	2600.0 mm/Km	2803	3.55	Good	26.1778822	N	84.2163935	E	Normal
19/06/22	10:23:42	52	100	2000	37.0 cm	14.4 Km/Hr	3700.0 mm/Km	3597	4.74	Good	26.1781874	N	84.2159052	E	Normal
19/06/22	10:24:05	52	100	2100	31.0 cm	15.5 Km/Hr	3100.0 mm/Km	3055	4.09	Good	26.1782351	N	84.2145853	E	Normal


 30/08/22
 A.K.
 A.E.


 30/08/22

Name of work : Harpur - Bikaur

Name of customer : MITHILESH KUMAR SINGH

(R)Rural Road

Good

Average

Poor

< 4000

4001 - 5000

> 5000

19/06/22	10.24.29	52	100	2200	26.0 cm	15.1 Km/Hr	2600.0 mm/Km	2603	3.55	Good	26.1786909	N	84.2137537	E	Normal
19/06/22	10.24.59	52	100	2300	31.0 cm	12.0 Km/Hr	3100.0 mm/Km	3055	4.09	Good	26.1788225	N	84.2128077	E	Normal
19/06/22	10.25.25	52	100	2400	32.0 cm	13.9 Km/Hr	3200.0 mm/Km	3145	4.2	Good	26.1782236	N	84.2122278	E	Normal
19/06/22	10.25.51	52	100	2500	31.0 cm	13.7 Km/Hr	3100.0 mm/Km	3055	4.09	Good	26.1779222	N	84.2114725	E	Normal
19/06/22	10.26.17	52	100	2600	39.0 cm	14.1 Km/Hr	3900.0 mm/Km	3778	4.95	Good	26.1776781	N	84.2106943	E	Normal
19/06/22	10.26.37	52	100	2700	28.0 cm	17.8 Km/Hr	2800.0 mm/Km	2784	3.77	Good	26.1778326	N	84.2096872	E	Normal
19/06/22	10.27.13	52	100	2800	25.0 cm	10.4 Km/Hr	2500.0 mm/Km	2512	3.44	Good	26.1777143	N	84.2086725	E	Normal
19/06/22	10.27.52	52	100	2900	28.0 cm	9.0 Km/Hr	3800.0 mm/Km	3688	4.84	Good	26.1770353	N	84.2085657	E	Normal
19/06/22	10.28.20	52	100	3000	25.0 cm	12.7 Km/Hr	2500.0 mm/Km	2512	3.44	Good	26.1768274	N	84.2075663	E	Normal
19/06/22	10.28.46	52	100	3100	26.0 cm	14.1 Km/Hr	2600.0 mm/Km	2603	3.55	Good	26.1765718	N	84.2068033	E	Normal
19/06/22	10.29.09	52	100	3200	32.0 cm	15.3 Km/Hr	3200.0 mm/Km	3145	4.2	Good	26.1757250	N	84.2063456	E	Normal
19/06/22	10.29.31	52	100	3300	24.0 cm	16.5 Km/Hr	2400.0 mm/Km	2422	3.33	Good	26.1749773	N	84.2058573	E	Normal
19/06/22	10.29.53	52	100	3400	25.0 cm	16.6 Km/Hr	2500.0 mm/Km	2512	3.44	Good	26.1746473	N	84.2051249	E	Normal
19/06/22	10.30.15	52	100	3500	37.0 cm	15.8 Km/Hr	3700.0 mm/Km	3597	4.74	Good	26.1743574	N	84.2043314	E	Normal
19/06/22	10.30.37	52	100	3600	31.0 cm	18.0 Km/Hr	3100.0 mm/Km	3055	4.09	Good	26.1741457	N	84.2036829	E	Normal
19/06/22	10.31.03	52	100	3700	32.0 cm	14.5 Km/Hr	3200.0 mm/Km	3145	4.2	Good	26.1747618	N	84.2031585	E	Normal
19/06/22	10.31.24	52	100	3800	28.0 cm	16.5 Km/Hr	2800.0 mm/Km	2784	3.77	Good	26.1753054	N	84.2025690	E	Normal
19/06/22	10.31.46	52	100	3900	39.0 cm	16.2 Km/Hr	3900.0 mm/Km	3778	4.95	Good	26.1755304	N	84.2016916	E	Normal
19/06/22	10.32.07	52	100	4000	32.0 cm	18.0 Km/Hr	3200.0 mm/Km	3145	4.2	Good	26.1762991	N	84.2010126	E	Normal
19/06/22	10.32.27	52	100	4100	28.0 cm	17.4 Km/Hr	2800.0 mm/Km	2784	3.77	Good	26.1772184	N	84.2008142	E	Normal
19/06/22	10.33.03	52	100	4200	35.0 cm	10.4 Km/Hr	3500.0 mm/Km	3416	4.52	Good	26.1781588	N	84.2008142	E	Normal
19/06/22	10.33.39	52	100	4300	24.0 cm	10.0 Km/Hr	2400.0 mm/Km	2422	3.33	Good	26.1782122	N	84.1999063	E	Normal

AW
30/08/22
A.E

30.8.22

Name of work : Harpur - Bikaur

Name of customer : MITHILESH KUMAR SINGH

(R) Rural Road

Good

Average

Poor

< 4000

4001 - 5000

> 5000

19/06/22	10.34.16	52	100	4400	23.0 cm	9.6 Km/Hr	2800.0 mm/Km	2874	3.88	Good	26.1785898	N	84.1991739	E	Normal
19/06/22	10.36.18	52	100	4500	16.0 cm	2.9 Km/Hr	1600.0 mm/Km	1699	2.42	Good	26.1794233	N	84.1994791	E	Normal
19/06/22	10.36.53	52	100	4600	27.0 cm	10.3 Km/Hr	2700.0 mm/Km	2893	3.66	Good	26.1801882	N	84.1991892	E	Normal
19/06/22	10.37.17	52	100	4700	26.0 cm	14.5 Km/Hr	2600.0 mm/Km	2803	3.55	Good	26.1810751	N	84.1992884	E	Normal
19/06/22	10.37.48	52	100	4800	35.0 cm	11.8 Km/Hr	3500.0 mm/Km	3416	4.52	Good	26.1819181	N	84.1996393	E	Normal
19/06/22	10.38.15	52	100	4900	26.0 cm	13.3 Km/Hr	2600.0 mm/Km	2603	3.55	Good	26.1827898	N	84.1999979	E	Normal
19/06/22	10.38.41	52	100	5000	22.0 cm	13.7 Km/Hr	2200.0 mm/Km	2241	3.11	Good	26.1829309	N	84.2010126	E	Normal
19/06/22	10.39.07	52	100	5100	31.0 cm	13.7 Km/Hr	3100.0 mm/Km	3055	4.09	Good	26.1830416	N	84.2019052	E	Normal
19/06/22	10.39.27	52	100	5200	22.0 cm	17.4 Km/Hr	2200.0 mm/Km	2241	3.11	Good	26.1839437	N	84.2022333	E	Normal
19/06/22	10.39.48	52	100	5300	33.0 cm	17.8 Km/Hr	3300.0 mm/Km	3236	4.31	Good	26.1847754	N	84.2026377	E	Normal
19/06/22	10.40.10	52	100	5400	30.0 cm	16.5 Km/Hr	3000.0 mm/Km	2964	3.99	Good	26.1853437	N	84.2033396	E	Normal
19/06/22	10.40.32	52	100	5500	33.0 cm	16.0 Km/Hr	3300.0 mm/Km	3236	4.31	Good	26.1861219	N	84.2038584	E	Normal
19/06/22	10.41.00	52	100	5600	30.0 cm	13.1 Km/Hr	3000.0 mm/Km	2964	3.99	Good	26.1868906	N	84.2044153	E	Normal
19/06/22	10.41.45	52	100	5700	30.0 cm	16.5 Km/Hr	3000.0 mm/Km	2964	3.99	Good	26.1853437	N	84.2033396	E	Normal
19/06/22	10.42.32	52	100	5800	33.0 cm	16.0 Km/Hr	3300.0 mm/Km	3236	4.31	Good	26.1861219	N	84.2038584	E	Normal
19/06/22	10.42.56	52	100	5900	30.0 cm	13.1 Km/Hr	3000.0 mm/Km	2964	3.99	Good	26.1868906	N	84.2044153	E	Normal

19/6/22
A.E

30/08/22
A.E

30.8.22

4800

3925


3050

UIV mm/km

2175

1300

Name of Customer: MITHILESH KUMAR SINGH, Machine no: 19208, Road: Harpur - Bikaner, Date: 19-06-22, Section No: 52, Equation: $Y=0.904X+252.3$



19/6/22
g.e

Aug
30/08/22
A.C

90.8.22
g.e