

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सिवान-2

पत्रांक.....165631नु०..... सिवान, दिनांक.....01-08-23.....

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, सिवान-2

सेवा में,

सचिव-सह-प्राधिकृत पदाधिकारी
बिहार ग्रामीण पथ विकास एजेन्सी
भूमि विकास बैंक भवन
बुद्ध मार्ग, पटना।

विषय:- योजना शीर्ष नई अनुरक्षण निति 2018 MR/3054 अन्तर्गत पथों में मरम्मत हेतु
अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक प्रासंगिक पत्र के आलोक में कहना है कि योजना शीर्ष नई अनुरक्षण
निति 2018 MR/3054 अन्तर्गत संलग्न विहित प्रपत्र में 46.63326 लाख (छियालीस लाख
तिरेसठ हजार तीन सौ छबीस) रुपये मात्र आवंटन देने की कृपा की जाय।

अनु०-अधियाचना पत्र, Bump Integrator Equipment Report की छाया प्रति,
एकरारनामा की छाया प्रति,

विश्वासभाजन

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सिवान-2

1.08.23

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division :- RWD, WORKS DIVISION, SIWAN-2																		
S.N.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Amount Allocated (in Lakh)	Up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in Km)	Amount (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	MR-N-22-23siwan-203	T02 (SH) to Baiti	31406713019	1999.02.05-2022	1.500	78.800	46.68326	15.21464	17 MIBD of 2022-23/17.01.2023	25.09.23	01.08.2023	Good	25mm	5.031	0.00	0.00	46.63326	Complete
Total															0.000000	0.000000	46.63326	

प्रमाणित किया जाता है कि पृष्ठ में कराये गये कार्य के सभी अवयववार 100 प्रतिशत कार्य का दर्ज मापी का सत्यापन संबंधित कमीय अभियंता 50 प्रतिशत मापी का सत्यापन संबंधित सहायक अभियंता एवं 10 प्रतिशत मापी का सत्यापन अग्रोहस्ताक्षरी यथा कार्यपालक अभियंता द्वारा किया जा चुका है। कराया गया कार्य मानक एवं विशिष्टियों के अनुरूप है।

कमीय अभियंता
01/08/2023

सहायक अभियंता
01/08/2023

प्रमाणित करने वाले अभियंता
01/08/2023

कार्यपालक अभियंता
01/08/2023

FORM GFR 19-A
(See Government of India's Decision (I) below Rule-150)
Form of Utilisation Certificate up to 01st August 2023
NEW MAINTENANCE POLICY (2018)

Sl.No	Name of Scheme	Sanction No.& Date with Amount, (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural roads under NEW MAINTENANCE POLICY (2018)	24/19.03.2020 59/18.08.2020 78/29.10.2020 82/13.11.2020 86/11.12.2020 05/12.01.2021 17/26.02.2021 20/19.03.2021 26/15.04.2021 52/24.08.2021 58/27.10.2021 60/09.11.2021 64/06.12.2021 68/23.12.2021 02/03.01.2022 05/25.01.2022 10/21.02.2022 18/11.03.2022 49/27.04.2022 01/20.05.2022 22/08.08.2022 35/13.10.2022 32/03.03.2023 42/20.03.2023 63/13.04.2023 67/24.04.2023 72/10.05.2023 81/31.05.2023 92/28.06.2023 100/14.07.2023 102/21.07.2023	309.44834 40.85500 127.93990 129.95438 140.17554 246.86987 257.50061 46.15519 70.50399 58.39236 177.05420 87.58854 1.27421 167.06400 614.19943 279.43486 11.26696 726.24067 29.31956 62.42914 272.11117 168.58187 604.61409 1.38703 491.70500 105.00000 185.55188 97.83590 53.00489 162.35903 228.39216	Certified that out of Rs 6311.86885 lacs received during the years 2022-23 in favour of Ex. Engineer, RWD, Works Division, siwan-2 Bihar, a sum of Rs 6248.16493 Lacs has been utilized for the purpose of NEW MAINTENANCE POLICY-2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs 63.70392 lacs remaining unutilized at the end of the period under.
	Total :		6311.86885	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other codal formalities have been observed.

3. **Physical Progress achieved :-**


- Construction of Road works.
- Construction of CD works.

991
18/8/23
DIVISIONAL ACCOUNT OFFICER
RURAL WORKS DEPARTMENT
WORKS DIVISION, SIWAN-2

01/08/2023
EXECUTIVE ENGINEER
RURAL WORKS DEPARTMENT
WORKS DIVISION, SIWAN-2

1.8.23

Name of Customer: Genius Construction, Machine no: 19208, Road: T02 (SH) to Balli, Date: 31-07-23, Section No: 153, Equation: $Y=0.904X+252.3$



[Signature]
1/08/2023
JE

[Signature]
01/08/2023
JE

[Signature]
01/08/2023
Executive Engineer
Road Ward Department
Road Division Sivani-2

Name of work : T02 (SH) to Balli
 Name of customer : Genius Construction

(R) Rural Road		
Good	Average	Poor
< 4000	4001 - 5000	> 5000

Date	Time	Test No	Distance(m)	Total Distance(m)	BUNP(cm)	Speed(Km/Hr)	Ull(mm/Km)	Corrected Ull (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
31/07/23	11:27:11	153	100	100	22.0 cm	1.5 Km/Hr	2200.0 mm/Km	2241	3.11	Good	26.149815	N	84.3239298	E	Normal
31/07/23	11:27:40	153	100	200	34.0 cm	14.3 Km/Hr	3400.0 mm/Km	3326	4.42	Good	26.1501684	N	84.3229532	E	Normal
31/07/23	11:28:03	153	100	300	21.0 cm	12.8 Km/Hr	2100.0 mm/Km	2151	2.99	Good	26.1501398	N	84.3219080	E	Normal
31/07/23	11:28:25	153	100	400	26.0 cm	15.2 Km/Hr	2600.0 mm/Km	2603	3.55	Good	26.1502581	N	84.3209467	E	Normal
31/07/23	11:28:49	153	100	500	20.0 cm	11.3 Km/Hr	2000.0 mm/Km	2060	2.89	Good	26.1498632	N	84.3201838	E	Normal
31/07/23	11:29:08	153	100	600	21.0 cm	19.1 Km/Hr	2100.0 mm/Km	2151	2.99	Good	26.1497641	N	84.3191919	E	Normal
31/07/23	11:29:32	153	100	700	28.0 cm	13.2 Km/Hr	2800.0 mm/Km	2784	3.77	Good	26.1493902	N	84.3183603	E	Normal
31/07/23	11:30:05	153	100	800	22.0 cm	16.6 Km/Hr	2200.0 mm/Km	2241	3.11	Good	26.1496830	N	84.3162600	E	Normal
31/07/23	11:30:31	153	100	900	24.0 cm	12.4 Km/Hr	2400.0 mm/Km	2422	3.33	Good	26.1493511	N	84.3155041	E	Normal
31/07/23	11:30:56	153	100	1000	21.0 cm	13.7 Km/Hr	2100.0 mm/Km	2151	2.99	Good	26.1493201	N	84.3153370	E	Normal
31/07/23	11:31:22	153	100	1100	26.0 cm	17.3 Km/Hr	2600.0 mm/Km	2603	3.55	Good	26.1491770	N	84.3153111	E	Normal
31/07/23	11:31:47	153	100	1200	20.0 cm	14.7 Km/Hr	2000.0 mm/Km	2060	2.88	Good	26.1488711	N	84.3150412	E	Normal
31/07/23	11:32:11	153	100	1300	21.0 cm	17.0 Km/Hr	2100.0 mm/Km	2151	2.99	Good	26.1488412	N	84.3145250	E	Normal
31/07/23	11:32:38	153	100	1400	28.0 cm	14.2 Km/Hr	2800.0 mm/Km	2784	3.77	Good	26.1475490	N	84.3132301	E	Normal
31/07/23	11:33:06	153	100	1500	28.0 cm	15.2 Km/Hr	2800.0 mm/Km	2784	3.77	Good	26.1475490	N	84.3132301	E	Normal

01/08/2023
 SF

01/08/2023
 AE

01/08/2023