

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

पत्रांक.....942/337/
प्रेषक,

डिहरी / दिनांक 10/08/23

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी -सह-सचिव,
ब्राडा,
भूमि विकास बैंक भवन,
बुद्ध मार्ग, पटना।

विषय :- **MR New Maintenance policy-2018** में किये गये कार्य के विरुद्ध
आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि MR New Maintenance policy-2018 अर्न्तगत कराये गये कार्यों के विरुद्ध संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है। इस पथ में कोई भी ATR लंबित नहीं है। उक्त पथ का सभी डाटा की प्रविष्टि MIS पर अद्यतन है।

अनु :- यथोक्त।

विश्वासभाजन

M Kumar
10.08.23

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

1/11
10/08/23

FORM GFR 19 -A
(SEE GOVERNMENT of India's Decesion (I) below Rule - 150)
Form of Utilisation Certificate upto the Month of Aug. 2023
NEW MAINTENANCE POLICY 2018 MR (3054)

PIU - RWD DEHRI

S.No	Name of Scheme	Sanction No. & Date	Amount Received	Particulars
		With amount(in Rs. Lacs)	(In Rs. Lacs)	
1	Contruction of Rural Road under MR-3054	102 21.07.2023	4201.78902	Certificate that out of Rs. 4201.78902 Lacs received during the years in favour of Executive Engineer , RWD Dehri Bihar. Sum of Rs. 4079.52097 Lacs has been utilised for the purpose of MR (3054)-2018 Fund hences as given in the margin for which it was sanctioned and that the balance of Rs. 122.26805 Lacs remaining unutilized at the end of the period under.
TOTAL			4201.78902	

Certified that I have satisfied myself that the conditions on which the grand-in-aid

- 2 was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer / Supertending Engineer.
- Periodical inspection has been conducted by Executive Engineer / Supertending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

3 **Physical Progress achieved :-**

- Construction of Road works.
- Construction of CD works.

[Signature]
10/8/23

D.A.O
RWD (W) Div. Dehri

[Signature]
10.08.23
Executive Engineer
RWD (W) Div. Dehri

Office of the Executive Engineer, Rural Works Department, Works Division, Dehri

Requisition format Scheme Head MR (3054) under Bihar road Maintenance Policy-2018 (Rectification and Surface Renewal)

Sl No	Package No.	Name of Road	Project Id as per MIS	Administrative Approval (AA) Letter No. and Date	Administrative Approval (AA)		Agreement (in Lakh)		Agreement No. and Date	Date of Completion as per Agreement	Actual Date of Completion	Value of (I) (in mm/Km)	Thickness of Bitumin Layer (in mm)	Value of Bitumin Content in Percentage	Previous total amount (in Lakh)	Up to Date expenditure as per MIS (in Lakh)	Requisition against Work Done (in Lakh)	Remarks
					Length (in Km)	Amount (in lakh)	Initial Rectification with Surface Renewal (in Lakh)	Five Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/RO/DEH /22/0001	G.T. Road to Tendua Dushadi	10301002325	1413 / 08.09.2022	4.77	266.5	127.94114	51.94	19/06-03-2023	05-Dec-23	-	2596	25 MM	5%	108759	108759	14550	Complete
2	RM/RO/DEH /22/0006	Bharatula Pandeypur to Garalia	10301002324	1413/08-09-2022	1.962	136.668	73.61297	20.7855	17/06.03.2023	05.12.2023	-	2605	25 MM	5%	0	0	42350	Complete

नोट:-

विभागीय पत्राक-मु0310(मु) 3054-4-04/2020 पार्त 4, 5047 दिनांक 23/12/2021 के आलोक में प्रमाणित किया जाता है कि-

1. गुणवत्ता पूर्ण एवं विशिष्टियों के अनुरूप कार्य कराने के बाद MIB में दर्ज किया गया है।

2. समन्वित कार्य कमीय अभियान द्वारा कराया गया (100% जांचा गया) सहायक अभियन्ता द्वारा 50% तथा कार्यपालक अभियन्ता द्वारा 10% जांचा गया तथा MIS पर Upload किया गया।

10/08/23

D.A.O
RWD (W) Div. Dehri

10.08.23
EXECUTIVE ENGINEER
RWD, WORKS DIVISION,
DEHRI

Road Name- Bharkuria Pandeypur to Garaila

Contractor Name- Vikash Kumar Singh

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	TEGORY ROAD	Latitude	ongitude	Event
10/8/23	9:39:16	22	0.1	230	20.2	2300	2715	G	24.90274	84.09956	Normal
10/8/23	9:40:0	22	0.1	240	20.2	2400	2815	G	24.90225	84.09945	Normal
10/8/23	9:40:20	22	0.1	180	20.2	1800	2215	G	24.90084	84.09997	Normal
10/8/23	9:40:38	22	0.1	190	20.2	1900	2315	G	24.90003	84.09977	Normal
10/8/23	9:40:55	22	0.1	220	20.2	2200	2615	G	24.89944	84.09965	Normal
10/8/23	9:41:20	22	0.1	210	10.1	2100	2515	G	24.89828	84.09963	Normal
10/8/23	9:41:58	22	0.1	220	10.1	2200	2615	G	24.89732	84.09948	Normal
10/8/23	9:42:26	22	0.1	240	20.2	2400	2815	G	24.89656	84.09934	Speed Breaker
10/8/23	9:42:47	22	0.1	200	20.2	2000	2415	G	24.89560	84.09947	Normal
10/8/23	9:42:59	22	0.1	240	30.3	2400	2815	G	24.89451	84.09920	Normal
10/8/23	9:43:24	22	0.1	200	30.3	2000	2415	G	24.89393	84.09896	Normal
10/8/23	9:43:48	22	0.1	250	30.3	2500	2915	G	24.89321	84.09946	Normal
10/8/23	9:44:12	22	0.1	270	30.3	2700	3115	G	24.89284	84.10021	Speed Breaker
10/8/23	9:44:31	22	0.1	190	20.2	1900	2315	G	24.89231	84.10118	Normal
10/8/23	9:44:48	22	0.1	260	20.2	2600	3015	G	24.89218	84.10134	Normal
10/8/23	9:45:10	22	0.1	250	30.3	2500	2915	G	24.89108	84.10156	Speed Breaker
10/8/23	9:45:28	22	0.1	180	30.3	1800	2215	G	24.89053	84.10146	Normal
10/8/23	9:45:44	22	0.1	190	20.2	1900	2315	G	24.88946	84.10079	Normal
10/8/23	9:45:58	22	0.1	240	20.2	2400	2815	G	24.88745	84.10103	Normal
10/8/23	9:46:18	22	0.1	180	20.2	1800	2215	G	24.88685	84.09970	Normal

$$Y = 0 * X^2 + 1.000 * X + 415.2$$

$$X = 2900$$

$$Y = 3315$$

(R) RURAL ROAD

Good Average Poor

IRI Value

Average IRI-2605

10.08.23
J.E

10.08.23
AE

10.08.23
EE

Name of Customer : Vikash Singh
 Name of Work/Road : Bharkuna Pandeypur to Garalia
 Lab Job number : 22
 Date : 10-08-2023
 Section No. : 22

Test Date :	<u>10-08-2023</u>	Road Name :	<u>Bharkuna Pandeypur to Garalia</u>
Machine No. :	<u>412</u>	Road Type :	<u>(R) RURAL ROAD</u>
Start S No. :	<u>379</u>	Side :	<u>Left</u>
Start E No. :	<u>399</u>	Interval	
Weather :	<u>Normal</u>	UV Range :	<u>1215</u> To <u>4000</u> mm/km
Start Location :	<u>1027484 0935E</u>	Dist Range :	<u>0</u> To <u>21</u> • 1000 m
End Location :	<u>1026584 0937E</u>	Equation :	<u>0 * X^2 + 1000 * X + 415.2</u>


Print Generate Report and Graph

Redraw Graph

Map View

File : C:\Users\BRDA75\Desktop\2023\Bump Report\Yikash si Bharkuna Pandeypur to Garalia 1 962\Bharkuna

Name of Customer : Name of Work/Road : Lab Job number :



Shrey
10.08.23
J.F.

Adarsh
10/8/23
AE

MUHAMMAD
10.08.23
AE