



कार्यपालक अभियंता का कार्यालय

ग्रामीण कार्य विभाग, कार्य प्रमंडल मुंगेर



पत्रांक— १२। अनु०
मो०—8986915296

दिनांक— 10/08/2023
ई मेल — ee.reomunger@gmail.com

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, मुंगेर।

सेवा में,

नोडल पदाधिकारी,
नई अनुरक्षण नीति 2018" (3054-MR)
ग्रामीण कार्य विभाग, बिहार पटना।

विषय :— शीर्ष MR(3054) "नई अनुरक्षण नीति 2018" योजनान्तर्गत पथ के निर्माण में
संवेदक के विपत्र भुगतान हेतु राशि की अधियाचना के सम्बन्ध में।

महाशय,


उपर्युक्त विषय के संबंध में सूचित करना है कि शीर्ष MR(3054) "नई अनुरक्षण
नीति 2018" योजनान्तर्गत पथ:—


1. N.H-80 SE SINGHESHWAR TOLA HOTE HUVE SITAKUND DIH BATIYA TAK में
कृत कार्य के भुगतान हेतु आवंटन की अधियाचना विहित प्रपत्र में भर कर की
जाती है।

अतः अनुरोध है कि आवंटन उपलब्ध कराने की कृपा की जाय।

अनु०:—यथोक्त।

विश्वासभाजन


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल मुंगेर


08/08/2023

Requisition Formate for Scheme Head - MR(3054) under Bihar Rural Road Maintenance Policy - 2018 (Initial Rectification and Surface Renewal)

Name of Works Division :-Munger

Sl No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	Up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Years Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/MU/MUN /23/0003	N.H-80 SE SINGHESHWAR TOLA HOTE HUVE SITAKUND DH BATTVA TAK	20803708143	3410/ 16.09.2020	1.35	64.28	38.28398	16.91531	1-MIBD-2023-24	09-Mar-24		2586	25.00	5.00	0.00000	0.00000	38.28398	Surface Complete

Total = 38.28398

- 1 Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.
- 2 Up-to-date Physical Progress has been uploaded in MIS.

Divisional Accountant Officer
RWD Works Division Munger

Executive Engineer
RWD, Works Division, Munger

08/09/23

**EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION,
Munger**

FROM GFR 19 - A

(See Government of India's Decision (I) below Rule - 150)
Form of Utilisation Certificate upto the month of July-2023

Name of the Head :- MR (New Maintenance Policy 2018) Fund

Month:- July-2023

SI. No.	Name of Scheme	Sanctioned No./ Date	Amount Received (in Lacs Rs.)	Particulars
1	2	4	5	6
1	Construction of Rural Roads under (NEW Maintenance Policy 2018) Fund	Vide Up to Letter No.96 WE dt. 07.07.2023	3158.01853	Certified that out of Rs. 3222.73373 Lacs received during the year 2019-20 in favour of Executive Engineer R.W.D. Works Division, Munger, Bihar a sum of Rs 3178.35073 Lacs has been utilized for the purpose of MR (New Maintenance Policy 2018) Fund Schemes as given in the margin for which it was sanctioned and that the balance of Rs 44.38300 Lacs remaining un-utilized at the end of the period under.
	Total -		3158.01853	


- 2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose fo


Kind of Checks Exercised :-

- Works have been supervised by Executive Engineer/Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test checks conducted by the Assistant Engineer/ Executive Engineer.
- All other codal formatities have been observed.

3 **Physical Progress achieved :-**

- Construction of Road Works.
- Construction of CD. Works.


Sr. Divisional Accounts Officer
Rural Works Department
Works Division, Munger


Executive Engineer
Rural Works Department
Works Division, Munger

Name of work : N.H-80 SE SINGHESHWAR TOLA HOTE HUVE SITAKUND
DIH BATIYA TAK

Name of customer : Jitendra Kumar

(R)Rural Road


Good															Average															Poor														
< 4000															4001 - 5000															> 5000														
Date	Time	Test No	Distance(m)	Total Distance(m)	BUMF(cm)	Speed(Km/Hr)	Ultram(Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks																													
05/08/23	14:50:11	98	100	100	31.0 cm	1.6 Km/Hr	3100.0 mm/Km	3229	4.3	Good	25.346171	N	86.535541	E	Normal																													
05/08/23	14:50:43	98	100	200	32.0 cm	11.3 Km/Hr	3200.0 mm/Km	3326	4.42	Good	25.346652	N	86.535791	E	Normal																													
05/08/23	14:51:03	98	100	300	28.0 cm	17.8 Km/Hr	2900.0 mm/Km	3035	4.07	Good	25.347215	N	86.535981	E	Normal																													
05/08/23	14:51:22	98	100	400	36.0 cm	18.5 Km/Hr	3600.0 mm/Km	3713	4.87	Good	25.348569	N	86.536401	E	Breaker																													
05/08/23	14:51:42	98	100	500	31.0 cm	17.6 Km/Hr	3100.0 mm/Km	3229	4.3	Good	25.349437	N	86.536678	E	Normal																													
05/08/23	14:52:01	98	100	600	32.0 cm	19.8 Km/Hr	3200.0 mm/Km	3326	4.42	Good	25.350131	N	86.536759	E	Normal																													
05/08/23	14:52:18	98	100	700	35.0 cm	21.0 Km/Hr	3500.0 mm/Km	3616	4.76	Good	25.350855	N	86.536751	E	Breaker																													
05/08/23	14:52:36	98	100	800	31.0 cm	20.4 Km/Hr	3100.0 mm/Km	3229	4.3	Good	25.352057	N	86.536907	E	Normal																													
05/08/23	14:52:56	98	100	900	23.0 cm	17.6 Km/Hr	2500.0 mm/Km	2647	3.6	Good	25.353363	N	86.537205	E	Normal																													
05/08/23	14:53:15	98	100	1000	35.0 cm	19.2 Km/Hr	3500.0 mm/Km	3616	4.76	Good	25.354169	N	86.537289	E	Breaker																													
05/08/23	14:53:32	98	100	1100	22.0 cm	21.0 Km/Hr	2200.0 mm/Km	2357	3.25	Good	25.355063	N	86.537288	E	Normal																													
05/08/23	14:53:50	98	100	1200	24.0 cm	20.2 Km/Hr	2400.0 mm/Km	2550	3.49	Good	25.356091	N	86.537514	E	Normal																													
05/08/23	14:54:08	98	100	1300	30.0 cm	20.4 Km/Hr	3000.0 mm/Km	3132	4.19	Good	25.356629	N	86.537762	E	Normal																													
05/08/23	14:54:41	98	100	1400	35.0 cm	10.8 Km/Hr	3500.0 mm/Km	3616	4.76	Good	25.356138	N	86.537451	E	Breaker																													

08/08/23

08/08/23

Executive Engineer
RWD (W) Division
Munger

Name of Customer: Jitendra Kumar, Machine no: 19213, Road: N.H-80 SE SINGHESHWAR TOLA HOTE HUVE SITAKUND DIH BAITHA TAK, Date: 05-08-23, Section No: 98, Equation: $Y = 0.969 X + 224.9$




[Signature]
05/08/23

[Signature]
05/08/23

[Signature]
Executive Engineer
RWD (W) Division
Munger

Name of Customer: Jitendra Kumar , Machine no: 19213 , Road: N.H 80 SE SINGHESHWAR TOLA HOPE HUVE SITAKUND DIH BATIVA TAK , Date: 05-08-23 , Section No: 98 , Equation: $Y = 0.969 X + 224.9$



[Signature]
08/08/23
A/E

[Signature]
08/08/23
A/E

[Signature]
08/08/23
Executive Engineer
RWD (W) Division
Munger