

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल- बक्सर

पत्रांक-2023/बक्सर

दिनांक-18/08/23

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल- बक्सर

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण (BRRDA)
बुद्ध मार्ग, पटना।

विषय- शीर्ष 3054 (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) योजना अंतर्गत राशि की अधियाचना के सम्बन्ध में।


महाशय,

उपर्युक्त विषय के सम्बन्ध में कहना है कि योजना शीर्ष 3054 मरम्मत (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) अंतर्गत कराये गए कार्यों के भुगतान हेतु राशि की आवश्यकता है जिसे अधियाचना प्रपत्र के साथ सलग्न कर भेजा जा रहा है।

अतः श्रीमान से अनुरोध है कि सलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाए ताकि संवेदकों द्वारा कराये गए कार्य का भुगतान किया जा सके।

अनु०- यथोक्त

विश्वासभाजन


18/08/23

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

AK
18.08.23

FORM GFR 19-A
(SEE Government of India's Decision (I) below Rule-150)
Form of Utilisation Certificate upto the month of Dec 2018

MR (3054) New Maintenance Policy 2018

PIU - RWD (W), Div.- Buxar

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Constructi on of Rural Roads under MR (3054) Maintena nce	Lt. No.- 113, dt.-21.07.2023	9861.48177	Certified that out of Rs. 9861.48177lacs received during the years in favour of Ex. Engineer, RWD (W), Div.- Buxar Bihar, a sum of Rs 9843.25958 lacs been utilized for the purpose of MR (3054) New Maintenance Policy 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs 18.22219 lacs remaining unutilized at the end of the period under
Total -				

- 2 Certified that I have stisfied myself that the conditions on which the grans-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Supertending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Supertending Engineer.
- Construction materials have been tested
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

3 **Physical Progress achieved :-**

- Construction of Road works
- Construction of CD works

AK
18.08.23
Executive Engineer

R.W.D. (w) Div. Buxar

AK
18.08.23

Requisition Format for Scheme Head- MR (3054) under Bihar Rural Road Maintenance Policy- 2018 (Initial Rectification and Surface Renewal)

Name of Works Division- RWD, Works Division- Buxar

Sl No	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Agreement No. & Date	Date Of Completion as per Agreement	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (In Lakh)	up-to-date expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
					Length (in Km)	Amount (in Lakh)	Initial Rectification With Surface Renewal (in Lakh)	5 Years Routine Maintenance (in Lakh)									
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
2	RM/BU/BU X/22/0002	Dhanosi Sikhi Road - Kakanra	10402002034	Letter No 852& 18/02/2022	5.093	298.718	187.96113	48.71305	15/MBD/2022-23 & 25.01.2023	24.10.2023	171.4	25MM	5.01%	0	0	186.16112	

1. Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed
2. Up-to-date Physical Progress has been uploaded in MIS

Executive Engineer
RWD (W), Div.- Buxar


18.08.23
18.08.23
J.E.


कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर


का0आ0स...2024..... बक्सर/ दिनांक...18.08.23

कार्यालय आदेश


प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत Dhansoi Sikthi Road – Kakaria पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत, सहायक अभियंता द्वारा 50 प्रतिशत एवं कनीय अभियंता के द्वारा शतप्रतिशत किया गया है।


कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रशाखा राजपुर


सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल राजपुर


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

File : G:\shushil kumar mahuar\18081042.Xls. Section No. : 22. Eqn : $Y = 0 \cdot X^2 + 0.816 \cdot X + 249$
 Name of Customer : Shushil Kumar. Name of Work/ Road : Dhansoi Siki Road-Kakariya. Lab Job number :



Shushil
 18/08/23
 J.E

Shushil
 18/08/23
 AE

S
 18.08.23

Road Name:-Dhansoi Sikti Road-Kakriya Contractor Name:-Shushil Kumar

Shushil Kumar												
Date	Time	Section	No.	Length in km	Bumps in mm	Speed Rate	OR	IRI CATEGORY	Latitude	ongitude	Event	
18/8/23	8:41:0	22	0.1	180	10.1	1800	1717 G	25.47928	84.12722	Normal		
18/8/23	8:42:0	22	0.1	200	10.1	2000	1880 G	25.47928	84.12222	Normal		
18/8/23	8:43:0	22	0.1	250	10.1	2500	2288 G	25.36577	84.25555	Normal		
18/8/23	8:44:0	22	0.1	120	10.1	1200	1228 G	25.36665	84.2574	Normal		
18/8/23	8:45:16	22	0.1	220	10.1	2200	2044 G	25.36194	84.21968	Normal		
18/8/23	8:45:16	22	0.1	190	10.1	1900	1799 G	25.36217	84.21027	Normal		
18/8/23	8:46:0	22	0.1	170	20.2	1700	1636 G	25.36236	84.2	Normal		
18/8/23	8:46:27	22	0.1	160	10.1	1600	1554 G	25.36255	84.19007	Normal		
18/8/23	8:46:27	22	0.1	140	20.2	1400	1391 G	25.36274	84.18013	Normal		
18/8/23	8:46:27	22	0.1	170	20.2	1700	1636 G	25.36282	84.17003	Normal		
18/8/23	8:47:2	22	0.1	120	20.2	1200	1228 G	25.36296	84.1601	Normal		
18/8/23	8:47:2	22	0.1	170	30.3	1700	1636 G	25.36309	84.1503	Normal		
18/8/23	8:47:37	22	0.1	170	20.2	1700	1636 G	25.36323	84.14073	Normal		
18/8/23	8:47:37	22	0.1	190	20.2	1900	1799 G	25.36345	84.13063	Normal		
18/8/23	8:47:37	22	0.1	150	20.2	1500	1472 G	25.36375	84.12153	Normal		
18/8/23	8:48:0	22	0.1	140	30.3	1400	1391 G	25.36396	84.11195	Normal		
18/8/23	8:48:11	22	0.1	150	20.2	1500	1472 G	25.36412	84.1008	Normal		
18/8/23	8:48:11	22	0.1	120	20.2	1200	1228 G	25.36429	84.9175	Normal		
18/8/23	8:48:11	22	0.1	170	20.2	1700	1636 G	25.36451	84.8215	Normal		
18/8/23	8:49:0	22	0.1	250	20.2	2500	2288 G	25.36457	84.7373	Normal		
18/8/23	8:49:0	22	0.1	170	20.2	1700	1636 G	25.36506	84.648	Normal		
18/8/23	8:49:21	22	0.1	200	20.2	2000	1880 G	25.36552	84.5487	Normal		
18/8/23	8:49:21	22	0.1	170	20.2	1700	1636 G	25.36549	84.4628	Normal		
18/8/23	8:50:0	22	0.1	190	20.2	1900	1799 G	25.3657	84.3687	Normal		
18/8/23	8:50:0	22	0.1	240	20.2	2400	2207 G	25.36552	84.2743	Normal		
18/8/23	8:50:32	22	0.1	210	20.2	2100	1962 G	25.36558	84.178	Normal		
18/8/23	8:50:32	22	0.1	190	20.2	1900	1799 G	25.36604	84.1027	Normal		
18/8/23	8:51:0	22	0.1	130	20.2	1300	1309 G	25.36619	84.12	Normal		
18/8/23	8:51:7	22	0.1	140	20.2	1400	1391 G	25.36629	83.99904	Normal		
18/8/23	8:51:7	22	0.1	170	20.2	1700	1636 G	25.36625	83.99811	Normal		
18/8/23	8:51:42	22	0.1	180	20.2	1800	1717 G	25.36629	83.99709	Normal		
18/8/23	8:51:42	22	0.1	160	20.2	1600	1554 G	25.36649	83.99614	Normal		
18/8/23	8:52:0	22	0.1	190	20.2	1900	1799 G	25.36658	83.99508	Normal		
18/8/23	8:52:16	22	0.1	140	30.3	1400	1391 G	25.3667	83.99407	Normal		
18/8/23	8:52:16	22	0.1	210	20.2	2100	1962 G	25.36691	0.4	Normal		

$$Y = 0 * X^2 + 0.816 * X + 249$$

$$X = 1828$$

$$Y = 1740$$

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001

IRI Value=1714

Machine ID=415

18.8.23

18/8/23

18.08.23

Road Name:-Dhansoi Sikti Road-Kakriya Contractor Name:-Shushil Kumar

Date	Time	Section	Length	Bumps	Speed	OR	IRI\TEGORY	Latitude	ongitude	Event
No.		in km	in mm	Rate	mm/km	mm/km	ROAD			
18/8/23	8:52:0	22	0.1	220	20.2	2200	2044 G	25.36732	83.99224	Normal
18/8/23	8:53:0	22	0.1	140	30.3	1400	1391 G	25.3674	83.99116	Normal
18/8/23	8:53:0	22	0.1	180	30.3	1800	1717 G	25.36745	83.99024	Normal
18/8/23	8:53:0	22	0.1	230	20.2	2300	2125 G	25.673	0.07	Normal
18/8/23	8:53:27	22	0.1	190	30.3	1900	1799 G	25.36744	83.98832	Normal
18/8/23	8:53:0	22	0.1	170	20.2	1700	1636 G	25.3673	83.98715	Normal
18/8/23	8:54:0	22	0.1	200	20.2	2000	1880 G	25.3674	83.98623	Normal
18/8/23	8:54:0	22	0.1	190	20.2	1900	1799 G	25.36692	83.98529	Normal
18/8/23	8:54:0	22	0.1	170	20.2	1700	1636 G	25.36686	83.98431	Normal
18/8/23	8:54:35	22	0.1	160	20.2	1600	1554 G	25.36693	83.98345	Normal
18/8/23	8:55:0	22	0.1	220	20.2	2200	2044 G	25.36743	83.98296	Normal
18/8/23	8:55:15	22	0.1	160	20.2	1600	1554 G	25.36792	83.98306	Normal
18/8/23	8:55:15	22	0.1	170	20.2	1700	1636 G	25.36916	83.98333	Normal
18/8/23	8:56:0	22	0.1	200	10.1	2000	1880 G	25.36971	83.98288	Normal
18/8/23	8:56:23	22	0.1	260	10.1	2600	2370 G	25.36977	83.98187	Normal
18/8/23	8:58:43	22	0.093	170	0	1828	1740 G	25.37006	83.98091	Normal
		Length	5.093							

$$Y = 0 * X^2 + 0.816 * X + 249$$

18.8.23
J.E

18/8/23
AE

18.8.23