

$MAG_{SY}(SC)$

734

DIVISION

SUB-DIVISION

NO-2306

(555)

(These four lines should be repeated at the commencement of the measurements relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W:- Constn. of Road 2nd					
works with maintenance					
for Hari Pagak house to					
Prmhsy Road Near Mitulesh					
Raj under mmhsy.					
N/Agency:- Chandan Kumar Yadav					
vill- Balga Po- Barri Bhatta					
Sitamardi					
Agreement no:- 78-SBO dt 2013-20					

Date of start:- 6-03-20

Date of Completion:- 5/2/21

Work Done

(1 1/2) P/v & fixing of working benchmark

(a) working benchmark
Pillar

~~17 x 30 cm~~

~~17 x 0.030 km~~ = 0.51 km

17 x 30 m = 510 m

1 x 29 m = 29 m

539 m

HO mesquite.

Self-Test Form No. 124

Only ABSTRACT

Particulars	Details of actual measurements			Contents of area
	No.	L.	B.	
Payable amount	1.			3110 852 = 0
less previous payments				2738 129 = 0
Total p.				372 723 = 0
Item wise detailed vide				
T.M.E. page 26 to 32				
interms 1 to 12.				
14/2/23 5-E 20/2/23 A.B.				
14/2/23 5-E 20/2/23 A.B.				