

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, टिकारी।

पत्रांक:- 2372-अनु

/टिकारी, दिनांक:- 5-12-23

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, टिकारी।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण, पटना।

विषय-

3054/MR, New Maintenance Policy-2018 अंतर्गत आवंटित राशि का
उपयोगिता प्रमाण पत्र तथा आवंटन अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि इस प्रमंडल अंतर्गत 3054/MR,
New Maintenance Policy-2018 अंतर्गत L081 - Turi to Chirmichi Bigha (VR81) पथ में
चल रहे कार्यों के भुगतान हेतु उपयोगिता प्रमाण पत्र विहित प्रपत्र में संलग्न करते हुए
आग्रह है कि माँग पत्र के अनुसार योजना में रुपये 1,38,13,359.00 (एक करोड़ अड़तीस
लाख तेरह हजार तीन सौ उनसठ रुपये मात्र) का आवंटन उपलब्ध कराने की कृपा की
जाय।

अनु०- यथोक्त।

विश्वासभाजन

8/5/12/23

कार्यपालक अभियंता

ग्रामीण कार्य विभाग, कार्य प्रमंडल, टिकारी।

**OFFICE OF THE EXECUTIVE ENGINEER,
RURAL WORKS DEPARTMENT, WORKS DIVISION TEKARI.**

Requisition Format for Scheme Head:- MR (3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)																			
Name of Works Division:- Tekari																			
Sl. No.	Batch No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km ²)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allotted Amount (in Lakh)	Up to date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks	
					Length (in Km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)											
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
1	RM/GA/TK /23/0006	L081 - Turi to Chirmichi Bigha (VR81)	10502202085	Lt.1447 Dt. 28.02.2023	3.250	190.47400	138.13359	32.03231	09/MBD/3054/ MR/2023-24 Dt. 27.07.2023	26.04.2024	-	3118	25 mm	5.08%	0.00	0.00	138.13359	RI का ग्राफ संलग्न है।	
Total																		138.13359	
Amount in Word:- One Crore Thirty Eight Lakh Thirteen Thousand Three Hundred Fifty Nine Only.																			

05.12.23
D.A.O.,
RWD, Works Division, Tekari

05.12.23
Executive Engineer
RWD, Works Division, Tekari

FORM GFR 19 - A

(See Government of India's Decision (1) below Rule - 150)
Form of utilisation Certificate as on :- **05.12.2023**
RURAL ROAD MAINTENANCE POLICY-2018

PIU :- R.W.D. Tekari.

Sl. no.	Name of Scheme	Sanction No.& Date with Amount (in Lacs)	Amount Received in Lacs	Decrease (in Lacs)	Particulars
1	2	3	4	5	6
	RURAL ROAD MAINTENANCE POLICY-2018	As on 10 Feb -2023	4181.59446	0.00000	Certified that out of Rs.:-7074.62149 Lacs received in the Financial Years 2023-24 In favour of Executive Engineer RWD Works Division Tekari, Gaya Bihar out of which a sum of Rs.:- 0.00 Lacs has been Surrender and 6919.78610 Lacs has been Utilized for the purpose of RURAL ROAD MAINTENANCE POLICY-2018 as given in the margin for which it was sanctioned and that the balance of Rs.:- 154.83539 Lacs remainig unutilized at the end of the said period.
		Lt. No. 21 Dt. 20.02.2023	87.13840		
		Lt. No. 39 Dt. 17.03.2023	163.80773		
		Lt. No. 42 Dt. 20.03.2023	144.52085		
		Lt. No. 67 Dt. 27.04.2023	78.26116		
		Lt. No. 72 Dt. 10.05.2023	497.42348		
		Lt. No. 78 Dt. 24.05.2023	432.88875		
		Lt. No. 81 Dt. 31.05.2023	41.9025		
		Lt. No. 89 Dt. 21.05.2023	453.51967		
		Lt. No. 92 Dt. 28.06.2023	98.20800		
		Lt. No. 100 Dt. 14.07.2023	246.5669		
		Lt. No. 126 Dt. 18.09.2023	31.25591		
			119.66327		
			378.19600		
		Lt. No. 152 Dt. 16.11.2023	101.34705		
		Lt. No. 151Dt. 10.11.2023	14.97911		
		Lt. No. 163 Dt. 04.12.2023	3.34825		
		Total	7074.62149	0.00000	

Memo No. :-

- 2 Certified that I have satisfied my self that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of checks exercised :-

- Works have been supervised by Executive Engineer/Superintending Engineer
- Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- Construction material have been tested.
- Measurment have been recorded in the MBs and test check conducred by the Assistant.
- All other codal formalities hav been observed.

- 3 Physical progress achieved

- Construction of Road works.
- Construction of cd works.

D.A.O.

RURAL WORK DEPARTMENT
WORKS DIVISION TEKARI

EXECUTIVE ENGINEER
RURAL WORK DEPARTMENT
WORKS DIVISION TEKARI
5/12/23



सहायक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य अवर प्रमंडल, बेलागंज

दिनांक:- 05/12/2023

पत्रांक:- 172

जाँच प्रतिवेदन

प्रखण्ड का नाम	योजना का नाम	पथ की लम्बाई (कि०मी०)	S.D.B.C परत की मोटाई	बिटुमिन Content की मात्र	BUMP INTEGRATOR का Reading	अभियुक्ति
Belaganj	L081- Turi to Chirmichi Bigha (VR81)	3.200	25MM	5.08 %	Reading Attached	Satisfactory


सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल, बेलागंज

Report SDO



Scanned with OKEN Scanner

Name of work : L081 - Turi to Chirmichi Bigha (VR81)
Name of customer : M G Construction And CO

(R)Rural Road


Good	Average	Poor
< 4000	4001 - 5000	> 5000

Date	Time	Test No	Distance(m)	Total Distance(m)	BUMP(cm)	Speed(Km/Hr)	UI(mm/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
02-12-23	16:35:37	15	100	100	35.0 cm	15.0 Km/Hr	3500.0	3592	4.73	Good	25.001878	N	84.900804	E	Normal
02-12-23	16:35:53	15	100	200	36.0 cm	16.5 Km/Hr	3600.0	3685	4.84	Good	25.001878	N	84.899793	E	Normal
02-12-23	16:36:24	15	100	300	25.0 cm	17.1 Km/Hr	2500.0	2661	3.62	Good	25.002053	N	84.898893	E	Normal
02-12-23	16:36:44	15	100	400	31.0 cm	18.5 Km/Hr	3100.0	3220	4.29	Good	25.002222	N	84.897783	E	Normal
02-12-23	16:36:57	15	100	500	30.0 cm	15.6 Km/Hr	3000.0	3127	4.18	Good	25.001814	N	84.897015	E	Normal
02-12-23	16:37:23	15	100	600	30.0 cm	21.3 Km/Hr	3000.0	3127	4.18	Good	25.001637	N	84.896303	E	Normal
02-12-23	16:37:39	15	100	700	29.0 cm	22.5 Km/Hr	2900.0	3034	4.07	Good	25.0014	N	84.895139	E	Normal
02-12-23	16:37:54	15	100	800	25.0 cm	24.4 Km/Hr	2500.0	2661	3.62	Good	25.00133	N	84.894236	E	Normal
02-12-23	16:38:08	15	100	900	22.0 cm	26.4 Km/Hr	2200.0	2382	3.28	Good	25.002066	N	84.893856	E	Normal
02-12-23	16:38:21	15	100	1000	19.0 cm	27.2 Km/Hr	1900.0	2102	2.93	Good	25.002338	N	84.893129	E	Normal
02-12-23	16:38:46	15	100	1100	25.0 cm	23.9 Km/Hr	2500.0	2661	3.62	Good	25.003248	N	84.893030	E	Normal
02-12-23	16:39:09	15	100	1200	26.0 cm	16.2 Km/Hr	2600.0	2754	3.73	Good	25.004133	N	84.893138	E	Normal
02-12-23	16:39:24	15	100	1300	27.0 cm	22.6 Km/Hr	2700.0	2847	3.85	Good	25.004225	N	84.892125	E	Normal
02-12-23	16:39:59	15	100	1400	24.0 cm	24.9 Km/Hr	2400.0	2568	3.51	Good	25.004064	N	84.891205	E	Normal
02-12-23	16:40:15	15	100	1500	29.0 cm	22.7 Km/Hr	2900.0	3034	4.07	Good	25.004141	N	84.890414	E	Normal
02-12-23	16:40:39	15	100	1600	32.0 cm	24.6 Km/Hr	3200.0	3313	4.4	Good	25.004404	N	84.890137	E	Normal
02-12-23	16:40:56	15	100	1700	27.0 cm	24.1 Km/Hr	2700.0	2847	3.85	Good	25.005172	N	84.890724	E	Normal
02-12-23	16:41:12	15	100	1800	22.0 cm	24.7 Km/Hr	2200.0	2382	3.28	Good	25.005868	N	84.891002	E	Normal
02-12-23	16:41:33	15	100	1900	28.0 cm	25.7 Km/Hr	2800.0	2940	3.96	Good	25.006414	N	84.891709	E	Normal
02-12-23	16:41:57	15	100	2000	35.0 cm	20.0 Km/Hr	3500.0	3592	4.73	Good	25.006818	N	84.892366	E	Normal
02-12-23	16:42:15	15	100	2100	36.0 cm	24.5 Km/Hr	3600.0	3685	4.84	Good	25.006729	N	84.893291	E	Normal
02-12-23	16:42:39	15	100	2200	34.0 cm	24.9 Km/Hr	3400.0	3499	4.62	Good	25.007001	N	84.894298	E	Normal
02-12-23	16:42:59	15	100	2300	34.0 cm	24.6 Km/Hr	3400.0	3499	4.62	Good	25.007349	N	84.895128	E	Normal
02-12-23	16:43:11	15	100	2400	37.0 cm	23.4 Km/Hr	3700.0	3778	4.95	Good	25.007929	N	84.895637	E	Normal
02-12-23	16:43:35	15	100	2500	37.0 cm	24.7 Km/Hr	3700.0	3778	4.95	Good	25.008875	N	84.895322	E	Normal
02-12-23	16:43:59	15	100	2600	33.0 cm	19.2 Km/Hr	3300.0	3406	4.51	Good	25.009685	N	84.89528	E	Normal
02-12-23	16:44:19	15	100	2700	27.0 cm	21.3 Km/Hr	2700.0	2847	3.85	Good	25.010472	N	84.895356	E	Normal
02-12-23	16:44:37	15	100	2800	31.0 cm	22.0 Km/Hr	3100.0	3220	4.29	Good	25.010635	N	84.896178	E	Normal
02-12-23	16:45:04	15	100	2900	32.0 cm	21.6 Km/Hr	3200.0	3313	4.4	Good	25.011072	N	84.896862	E	Normal
02-12-23	16:45:34	15	100	3000	35.0 cm	12.6 Km/Hr	3500.0	3592	4.73	Good	25.010701	N	84.897914	E	Normal
02-12-23	16:45:57	15	100	3100	32.0 cm	15.8 Km/Hr	3200.0	3313	4.4	Good	25.01051	N	84.898717	E	Normal
02-12-23	16:46:29	15	100	3200	32.0 cm	24.6 Km/Hr	3200.0	3313	4.4	Good	25.010202	N	84.899755	E	Normal
Total			3200					3118							

04/12/23
J.E



Name of Customer: M G Construction And CO, Machine no: 19211, Road: 1081, Turi to Chiruchi Bigha (VRSD), Date: 04-12-23, Section No: 15, Equation: $Y=0.911X+333.6$



06/12/23
J.F.
S. 11/12/23
S. 11/12/23

