

3rd Apr 2011

14

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: Const. of Road from Konthu to Pirodhra Pakki					
Saddle under canopy (Gen)					
in Ekongar Sarai block					
Agency: M.D. Enterprises					
Ass: 87 SBD				19.20	
Date of start work: 9.3.19					
Date of completion: 8.3.20					
Item 1/	Poor Blowing Bitumen Coat with emulsion SS-1				
	33X	20.00	X 3.75	=	3712.50 M ²
				Total =	3712.50,
Item 2/	Poor Blowing Tack Coat with emulsion AS-1				
	33X	20.00	X 3.75	=	3712.50 M ²
				Total =	3712.50,
Item 3/	Poor, laying and compaction of 100mm (100mm) concrete surface (ones).				
	33X	20.00	X 3.75	=	3712.50 M ²
				Total =	3712.50,
Item 4/	Poor Blowing of hot applied thermoplastic paint - 100mm				
	2X 33X	20.00	X 0.10	=	198.00 M ²
				Total =	198.00,
Item 5/	Poor 120mm typical concrete base				

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area 837626
	No.	L.	B.	S.F. D.F.	
Qty = 201.90 M ² @ 2805.41 M ²					5669120 =
Item 5 (6) Port Blowing of work in					
vide item no. (3) work (12)					
Qty = 228.42 M ² @ 3662.45 M ²					1019703 =
Item 6 (7) Port Blowing of Port work					
vide item no. (1) work (14)					
Qty = 3712.50 M ² @ 49.54 M ²					183843
Item 7 (8) Port Blowing of Deck work					
vide item no. (2) work (14)					
Qty = 3712.50 M ² @ 16.73 M ²					621102
Item 8 (9) Port Blowing of Deck					
vide item no. (3) work (14)					
Qty = 3712.50 M ² @ 186.23 M ²					691527 =
Item 9 Port Blowing of applied					
thermo plastic paint					
vide item no. (4) work (14)					
Qty = 198.00 M ² @ 850.92 M ²					168482 =
Item 10 Port of hydraulic M/C					
See board vide item no. (5)					
work (15) Qty = 80 M ²					
@ 100 M ² @ 20048 =					20048 =
				Total =	4992459
(-) less 0.21 % below = (5) 10484					
				Total =	4981975
(-) less Previous Payment = (6) 385773					
				Total =	1124244

Continuation

2808

10/11/23

AE