

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, रोसड़ा

पत्रांक:- 2225/ 12 रोसड़ा, दिनांक:- 12 / 12 / 2023

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, रोसड़ा।

सेवामें,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय :- नई अनुक्षण नीति 2018 शीर्ष MR-3054 योजना अंतर्गत राशि की अधियाचना के संबंध में।


महाशय,

उपर्युक्त विषय के संबंध में कहना है कि शीर्ष-नई अनुक्षण नीति 2018 शीर्ष MR-3054 योजना मद अंतर्गत व्यय हेतु विहित प्रपत्र में अधियाचना पत्र संलग्न कर भेजी जा रही है।

अतः अनुरोध है कि संलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा किया जाय।

अनु0- यथोक्त।

विश्वासभाजन


12/12/23

कार्यपालक अभियंता,

ग्रामीण कार्य विभाग, कार्य प्रमंडल, रोसड़ा।


12/12/23

Requisition Formate for Scheme Head - MR(3054) under Bihar Rural Road Maintenance Policy - 2018 (Initial Rectification and Surface Renewal)

Name of Works Division :- Rosera

Sl No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) No & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)			Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	1st Year			
					Length (In km)	Amount of (In Lakh)	Initial Rectification with Surface Renewal (In Lakh)	5 Years Routine Maintenance (In Lakh)	9				1st Quarter	2nd Quarter	3rd Quarter	4th Quarter
	2	3	4	5	6	7	8	9		10	11	12	13	14	15	16
1	RM/SA/ROS/19/0009	MDR - Patori	32010302056	2166, 06.07.2019	1.550	30.31112	26.79800	14.07800		06(MBD)2019-20	3/3/2021	27/06/2021	0.70389			
2	RM/SA/ROS/19/0009	T03 - Nakuni	32010302031	2166, 06.07.2019	1.300	35.92835	31.37600	12.22600		06(MBD)2019-20	3/3/2021	27/06/2021	0.61130			
3	RM/SA/ROS/19/0009	Kurban-Baliyar-Rahibi-Bhagaut Road (2007-08)	32010301017	2166, 06.07.2019	2.900	98.84600	54.51900	27.65950		06(MBD)2019-20	3/3/2021	27/06/2021	1.38298			
4	RM/SA/ROS/19/0009	Utkramit middle school paroriya north-east parri paswan tola road	32010301030	2166, 06.07.2019	1.000	35.36979	19.55800	9.44292		06(MBD)2019-20	3/3/2021	27/06/2021	0.47215			
5	RM/SA/ROS/19/0009	BITHAN - JAGMOHRA	NEA22000554	2166, 06.07.2019	9.500	286.8581	150.70300	83.65006		05(MBD)2019-20	24/01/2021	15/02/2021	4.18250	4.18250	4.18250	0.0
Total													7.35282	4.18250	4.18250	0.0

- 1 Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.
- 2 Up-to-date Physical Progress has been uploaded in MIS.

Sapna Singh

**Divisional Account Officer
Works Division, Rosera**

Sapna Singh
**Executive Engineer
RWD (W) Division, Rosera**

(परिशिष्ट - 'H')

FORM GFR 19-A

(See Government of India's Decision (1) below Rule-150)
Form of utilization Certificate up to the month of Up to Dec. 23
Scheme **MR 3054 Maintenance**

PIU - Rosera

Sl no.	Name of Scheme	Section No. & Date with Amount (In Lacks)	Amount Received (In Lacks)	Particulars
1	Construction of Rural roads under Scheme MR 3054 Maintenance	BRRDA's Memo No. 165 dt. 7-12-23 Rs. 785308=	32329416=	Certified that out of Rs 32329416= lacks received during the years 23-24... in favor of EX. Engineer, RWD Bihar, 29031834= lacks has been utilized for the purpose of 3054 N.M.P. main Schemes as given in the margin for which it was sanctioned and that the balance of 4377532= lacks remaining unutilized at the end of the period under.

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.


Kinds of Checks exercised:-

- Works have been supervised by executive Engineer/Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other caudal formalities have been observed.

3. Physical Progress achieved:

- Construction of road works.
- Construction of CD works.


D.A.O.
Works Division,
Rural Works Department


Executive Engineer
Works Division,
Rural Works Department


3rd Quarter of 1 st Year									
Government of Bihar OM01					ORDINARY MAINTENANCE INSPECTION REPORT Form OM01				
Rural Works Department Road From : BITHAN - JAGMOHRA Length of Road:- 9.5 km Period:- From ... 14.08.2021 Inspector :- J.E., RWD Sub-Division Bithan, Works Section Rosear					To:- ... Executive Engineer RWD, Works Division Rosera (Samastipur) Position :- ... E.E.				
Form:- 15/02/2021					Date :- 14.08.2021				
No	Standard Work Item	Work Units	Unit of Work required in each Kilometre						Comments
	Name		1	2	3	4	5	6	
OM101	Pothole Patching	M ²	Nil	Nil	Nil				No pothole found
OM102	Surface Depression and Rut Patching	M ²	Nil	Nil	Nil				No Surface Depression and Rut Patching found
OM103	Crack Sealing	Lm	Nil	Nil	Nil				No Crack Sealing Found
OM104	Surface Treatment								
	(a) Loss of Aggregate (Surface Ravelling)	M ²	Nil	Nil	Nil				No Loss of Aggregate (Surface Ravelling) Found.
	(b) Bleeding/Flushing	M ²	Nil	Nil	Nil				No Bleeding / Flushing required.
OM105	(c) Crocodile Cracking	M ²	Nil	Nil	Nil				No Crocodile Cracking Found.
	Edge Repair	M ²	Nil	Nil	Nil				No Edge Repair Required.
	Digouts	M ²	N.A	N.A	N.A				
OM106	Concrete Pavement	M ³	N.A	N.A	N.A				
OM107	Other Activities								
OM 200	Shoulder								
OM 201	Unsealed Shoulder								
	(a) Edge Drop-off	Lm	Nil	Nil	Nil				No Edge Drop-off Required
	(b) Roughness, Scouring of Potholes	Lm	Nil	Nil	Nil				No Roughness, Scouring of Potholes Required.
OM 202	(c) Holding water	Lm	Nil	Nil	Nil				No Holding water found.
	Embankment Repair	M ³	Nil	Nil	Nil				No Embankment Repair Required.
	Other activities		N.A	N.A	N.A				
OM 300	Drainage including culverts major								
MO 301	Surface Drains & Verge	Lm	N.A	N.A	N.A				
MO 302	Culvert Cleaning	No	Nil	Nil	Nil				Not Required
MO 303	Culvert and Pit Repair	M ³	Nil	Nil	Nil				Not Required
	Other activities (White Washing)	M ²	Nil	Nil	Nil				Not Required

20/9/23
Bider

Appendix

J.E. RWD(w)

A.E. RWD

Executive Engineer, Works Division
Rosera (Samastipur)

20/9/23

Standard Work Item		Unit of Work required in each Kilometre										Comments
No	Name	Work Units	1	2	3	4	5	6	7	8	9	10
OM 400	Vegetation											
	Grass Control											
OM 401	(a) Roadside-General Tidy	Ha	Nil	Nil	Nil							Not Required
	(b) Clear near Safety signs, Kilometre posts and Roadside furniture	Ha	Nil	Nil	Nil							Not Required
OM 402	Tree and Shrub Management	No	100%	100%	100%							Cutting of Trees and shrubs within time period.
	(Cutting Trees)	No	100%	100%	100%							
	(Cutting Shrubs)	No	100%	100%	100%							Trimming of Grass within time period.
	Other activation (Trimming of Grass)	m ²	Nil	Nil	Nil							
OM 500	Safety Signage and Road											
	Signs Maintenance	No	Nil	Nil	Nil							Not Required
	Guard Stones	Lm	N.A	N.A	N.A							Not Required
	Distance Stones	No	N.A	N.A	N.A							Not Required
	Road Marking	m ²	Nil	Nil	Nil				Nil	Nil	Nil	Not Required
	Other Activities											

रमेश कुमार

(Signature of Contractor/Authorized Representative)

Date

Time

Place

12/9/23
J.E. RWD(w)

Note:- Enclose photographs with the report.

A.E.RWD

Executive Engineer, Works Division
Roseru (Samastipur)

12/9/23

12/9/23

STANDRAD FORMAT FOR ROADS QUARTERLY

PIU Name :- R.W.D Works Division Rosera

1	Name of the Road	BITHAN - JAGMOHRA		
2	Batch No.	RM/SA/ROS/19/0007		
3	Project Id	NEA22000554		
4	Total Length of Road (in Km)	9.5		
5	Length of Road to Meet Required Service Level	9.5		
6	No. of Total Quarter (ie3 Months as a unit in 5 years)	3rd Quarter		
7	Ordinary Maintenance Cost as per Schedule	83.65006		
8	Quarterly Payment : 1/20 of Ordinary Maintenance	4.18250		
Compliance Criteria	Standard Job Description	Non-Compliance		Reduction Payment [6]= [3]/[1]*[2]*[4]
		Length Non-Compliant [3]	Weighted Value for Payment Reduction (%) [4]	
I	PAVED ROADS (CARRIAGEWAY)	0	60%	0
II	SHOULDERS AND EMBANMENTS	0	10%	0
III	CROSS DRAINAGE INCLUDING CULVERTS AND BRIDGES	0	15%	0
IV	SIGNAGE AND ROAD SAFETY	0	10%	0
V	VEGATAION	0	5%	0
TOTAL PAYMENT REDUCTION FOR THE QUARTER (in				0
TO BE PAID FOR THE QUARTER / DEMAND (in Lakh [6]				4.18250

Date of inpection by E/I or his agent

Prepared by Contractor's Self Control Unit

12/9/23
A.E

Name and Designation of person inspection road

(Signature)

Date

Signature of person inspecting Road

Certify by E/I [signature] Date:-


Executive Engineer
R.W.D. (W) Division,
Rosera

12/9/23
E.E

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, रोसड़ा

Name of Road - BITHAN - JAGMOHRA
Name of Scheme - MR 3054 (New Maintenance Policy – 2018)
Name of Contractor/Agency- M/S Jain Construction
Length of Road - 9.5 km
Project ID - NEA22000554
Package No. - RM/SA/ROS/19/0007
Name of Block - Bithan

Certified that all item
wise 100% Measurement
has been checked by me



Junior Engineer RWD
Work Section Rosera
Works Division, **Bithan**

Certified that all item
wise 50% Measurement
has been checked by me




Assistant Engineer RWD
Work Section Rosera
Works Division, **Bithan**

Certified that all item
wise 10% Measurement
has been checked by me



Executive Engineer
RWD Works Division,
Rosera

Name of Customer: M/S Jain Construction, , Machine no: 19209 , Road: BITHAN - JAGMOHRA , Date: 12-09-23 , Section No: 14 , Equation: $Y=0.926X+90.9$



Signature
12/9/23

Signature
12/9/23
A.E

Signature
12/9/23

Name of work : BITHAN - JAGMOHRA

Name of customer : M/S Jain Construction,

(R)Rural Road

Good	Average	Poor
< 4000	4001 - 5000	> 5000

Date	Time	Test No	Distance(m)	Total Distance(m)	BUMP(cm)	Speed(Km/Hr)	UI(mm/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
12/09/23	15:44:06	14	100	100	36.0 cm	15.7 Km/Hr	3600.0 mm/Km	3425	4.53	Good	25.717758	N	86.362077	E	Normal
12/09/23	15:44:21	14	100	200	35.0 cm	22.7 Km/Hr	3500.0 mm/Km	3332	4.42	Good	25.717758	N	86.362077	E	Normal
12/09/23	15:44:34	14	100	300	31.0 cm	28.5 Km/Hr	3100.0 mm/Km	2962	3.98	Good	25.716990	N	86.362016	E	Normal
12/09/23	15:44:47	14	100	400	37.0 cm	27.0 Km/Hr	3700.0 mm/Km	3517	4.64	Good	25.715321	N	86.360945	E	Normal
12/09/23	15:45:01	14	100	500	39.0 cm	27.0 Km/Hr	3900.0 mm/Km	3702	4.86	Good	25.714470	N	86.360664	E	Normal
12/09/23	15:45:13	14	100	600	37.0 cm	30.0 Km/Hr	3700.0 mm/Km	3517	4.64	Good	25.714465	N	86.360251	E	Normal
12/09/23	15:45:24	14	100	700	33.0 cm	31.3 Km/Hr	3300.0 mm/Km	3147	4.2	Good	25.714465	N	86.360251	E	Normal
12/09/23	15:45:35	14	100	800	36.0 cm	32.7 Km/Hr	3600.0 mm/Km	3425	4.53	Good	25.714465	N	86.360251	E	Normal
12/09/23	15:45:45	14	100	900	31.0 cm	36.7 Km/Hr	3100.0 mm/Km	2962	3.98	Good	25.713510	N	86.359294	E	Normal
12/09/23	15:45:58	14	100	1000	33.0 cm	27.9 Km/Hr	3300.0 mm/Km	3147	4.2	Good	25.713510	N	86.359294	E	Normal
12/09/23	15:46:14	14	100	1100	37.0 cm	22.2 Km/Hr	3700.0 mm/Km	3517	4.64	Good	25.713510	N	86.359294	E	Normal
12/09/23	15:46:27	14	100	1200	34.0 cm	28.5 Km/Hr	3400.0 mm/Km	3239	4.31	Good	25.713510	N	86.359294	E	Normal
12/09/23	15:46:41	14	100	1300	37.0 cm	25.4 Km/Hr	3700.0 mm/Km	3517	4.64	Good	25.713510	N	86.354144	E	Normal
12/09/23	15:46:58	14	100	1400	24.0 cm	21.1 Km/Hr	2400.0 mm/Km	2313	3.19	Good	25.715362	N	86.354144	E	Normal
12/09/23	15:47:17	14	100	1500	35.0 cm	19.2 Km/Hr	3500.0 mm/Km	3332	4.42	Good	25.715362	N	86.354144	E	Normal
12/09/23	15:47:41	14	100	1600	36.0 cm	14.5 Km/Hr	3600.0 mm/Km	3425	4.53	Good	25.715362	N	86.354144	E	Normal
12/09/23	15:48:10	14	100	1700	31.0 cm	12.8 Km/Hr	3100.0 mm/Km	2962	3.98	Good	25.715362	N	86.354144	E	Normal
12/09/23	15:48:34	14	100	1800	34.0 cm	14.1 Km/Hr	3400.0 mm/Km	3239	4.31	Good	25.715362	N	86.347419	E	Normal
12/09/23	15:48:48	14	100	1900	22.0 cm	24.4 Km/Hr	2200.0 mm/Km	2128	2.96	Good	25.715071	N	86.345471	E	Normal
12/09/23	15:49:02	14	100	2000	24.0 cm	28.0 Km/Hr	2400.0 mm/Km	2313	3.19	Good	25.715071	N	86.345471	E	Normal
12/09/23	15:49:15	14	100	2100	33.0 cm	26.4 Km/Hr	3300.0 mm/Km	3147	4.2	Good	25.715071	N	86.345471	E	Normal

12/09/23

15:49:15

15:49:15

Name of work : BITHAN - JAGMOHRA

Name of customer : M/S Jain Construction,

(R)Rural Road

Good	Average		Poor
< 4000	4001 - 5000		> 5000

12/09/23	15:49:33	14	100	2200	34.0 cm	19.8 Km/Hr	3400.0 mm/Km	3239	4.31	Good	25.715071	N	86.345471	E	Normal
12/09/23	15:49:50	14	100	2300	38.0 cm	20.9 Km/Hr	3800.0 mm/Km	3610	4.75	Good	25.715071	N	86.345471	E	Normal
12/09/23	15:50:05	14	100	2400	39.0 cm	24.9 Km/Hr	3900.0 mm/Km	3702	4.86	Good	25.715071	N	86.345471	E	Normal
12/09/23	15:50:21	14	100	2500	31.0 cm	21.8 Km/Hr	3100.0 mm/Km	2962	3.98	Good	25.715940	N	86.342158	E	Normal
12/09/23	15:50:40	14	100	2600	39.0 cm	19.0 Km/Hr	3900.0 mm/Km	3702	4.86	Good	25.715940	N	86.342158	E	Normal
12/09/23	15:51:01	14	100	2700	36.0 cm	17.1 Km/Hr	3600.0 mm/Km	3425	4.53	Good	25.715940	N	86.342158	E	Normal
12/09/23	15:51:18	14	100	2800	33.0 cm	20.9 Km/Hr	3300.0 mm/Km	3147	4.2	Good	25.715940	N	86.342158	E	Normal
12/09/23	15:51:32	14	100	2900	34.0 cm	25.4 Km/Hr	3400.0 mm/Km	3239	4.31	Good	25.715940	N	86.342158	E	Normal
12/09/23	15:51:45	14	100	3000	30.0 cm	28.2 Km/Hr	3000.0 mm/Km	2869	3.87	Good	25.715940	N	86.342158	E	Normal
12/09/23	15:51:59	14	100	3100	20.0 cm	25.7 Km/Hr	2000.0 mm/Km	1943	2.73	Good	25.715940	N	86.342158	E	Normal
12/09/23	15:52:12	14	100	3200	33.0 cm	27.9 Km/Hr	3300.0 mm/Km	3147	4.2	Good	25.715940	N	86.342158	E	Normal
12/09/23	15:52:25	14	100	3300	32.0 cm	27.7 Km/Hr	3200.0 mm/Km	3054	4.09	Good	25.715940	N	86.342158	E	Normal
12/09/23	15:52:37	14	100	3400	31.0 cm	29.4 Km/Hr	3100.0 mm/Km	2962	3.98	Good	25.715594	N	86.2202158	E	Normal
12/09/23	15:52:50	14	100	3500	39.0 cm	29.1 Km/Hr	3900.0 mm/Km	3702	4.86	Good	25.715594	N	86.2202158	E	Normal
12/09/23	15:53:04	14	100	3600	32.0 cm	24.9 Km/Hr	3200.0 mm/Km	3054	4.09	Good	25.715958	N	86.2288065	E	Normal
12/09/23	15:53:17	14	100	3700	29.0 cm	27.2 Km/Hr	2900.0 mm/Km	2776	3.76	Good	25.715376	N	86.2303553	E	Normal
12/09/23	15:53:32	14	100	3800	22.0 cm	23.6 Km/Hr	2200.0 mm/Km	2128	2.96	Good	25.715376	N	86.2303553	E	Normal
12/09/23	15:53:48	14	100	3900	34.0 cm	22.7 Km/Hr	3400.0 mm/Km	3239	4.31	Good	25.714579	N	86.2311335	E	Normal
12/09/23	15:54:10	14	100	4000	30.0 cm	17.1 Km/Hr	3000.0 mm/Km	2869	3.87	Good	25.714579	N	86.2311335	E	Normal
12/09/23	15:54:32	14	100	4100	30.0 cm	16.3 Km/Hr	3000.0 mm/Km	2869	3.87	Good	25.714579	N	86.2311335	E	Normal
12/09/23	15:54:55	14	100	4200	34.0 cm	15.6 Km/Hr	3400.0 mm/Km	3239	4.31	Good	25.714579	N	86.2311335	E	Normal
12/09/23	15:55:22	14	100	4300	35.0 cm	13.4 Km/Hr	3500.0 mm/Km	3332	4.42	Good	25.714579	N	86.2311335	E	Normal

12/12/23

12/9/23

12/11/23

Name of work : BITHAN - JAGMOHRA

Name of customer : M/S Jain Construction,

(R) Rural Road									
Good					Average				
< 4000					4001 - 5000				
					Poor				
					> 5000				

12/09/23	15:55:42	14	100	4400	32.0 cm	17.6 Km/Hr	3200.0 mm/Km	3054	4.09	Good	25.714579	N	86.2311335	E	Normal
12/09/23	15:55:58	14	100	4500	36.0 cm	21.8 Km/Hr	3600.0 mm/Km	3425	4.53	Good	25.714579	N	86.2311335	E	Normal
12/09/23	15:56:15	14	100	4600	32.0 cm	21.6 Km/Hr	3200.0 mm/Km	3054	4.09	Good	25.714579	N	86.2311335	E	Normal
12/09/23	15:56:31	14	100	4700	30.0 cm	22.9 Km/Hr	3000.0 mm/Km	2869	3.87	Good	25.714579	N	86.2311335	E	Normal
12/09/23	15:56:46	14	100	4800	38.0 cm	23.1 Km/Hr	3800.0 mm/Km	3610	4.75	Good	25.714579	N	86.2311335	E	Normal
12/09/23	15:57:01	14	100	4900	38.0 cm	24.0 Km/Hr	3800.0 mm/Km	3610	4.75	Good	25.714579	N	86.2311335	E	Normal
12/09/23	15:57:13	14	100	5000	37.0 cm	29.4 Km/Hr	3700.0 mm/Km	3517	4.64	Good	25.714579	N	86.2311335	E	Normal
12/09/23	15:57:31	14	100	5100	32.0 cm	20.4 Km/Hr	3200.0 mm/Km	3054	4.09	Good	25.714579	N	86.2311335	E	Normal
12/09/23	15:57:45	14	100	5200	29.0 cm	25.7 Km/Hr	2900.0 mm/Km	2776	3.76	Good	25.714579	N	86.2311335	E	Normal
12/09/23	15:57:51	14	100	5300	31.0 cm	36.7 Km/Hr	3100.0 mm/Km	2962	3.98	Good	25.712128	N	86.2146845	E	Normal
12/09/23	15:57:58	14	100	5400	33.0 cm	27.9 Km/Hr	3300.0 mm/Km	3147	4.2	Good	25.711571	N	86.2148142	E	Normal
12/09/23	15:58:14	14	100	5500	37.0 cm	22.2 Km/Hr	3700.0 mm/Km	3517	4.64	Good	25.711571	N	86.2148142	E	Normal
12/09/23	15:58:27	14	100	5600	34.0 cm	28.5 Km/Hr	3400.0 mm/Km	3239	4.31	Good	25.711571	N	86.2148142	E	Normal
12/09/23	15:58:41	14	100	5700	37.0 cm	25.4 Km/Hr	3700.0 mm/Km	3517	4.64	Good	25.711571	N	86.2148142	E	Normal
12/09/23	15:58:58	14	100	5800	24.0 cm	21.1 Km/Hr	2400.0 mm/Km	2313	3.19	Good	25.711571	N	86.2148142	E	Normal
12/09/23	15:59:17	14	100	5900	35.0 cm	19.2 Km/Hr	3500.0 mm/Km	3332	4.42	Good	25.711571	N	86.2148142	E	Normal
12/09/23	15:59:41	14	100	6000	36.0 cm	14.5 Km/Hr	3600.0 mm/Km	3425	4.53	Good	25.711571	N	86.2148142	E	Normal
12/09/23	16:01:10	14	100	6100	31.0 cm	12.8 Km/Hr	3100.0 mm/Km	2962	3.98	Good	25.711571	N	86.2148142	E	Normal
12/09/23	16:01:34	14	100	6200	34.0 cm	14.1 Km/Hr	3400.0 mm/Km	3239	4.31	Good	25.711571	N	86.2148142	E	Normal
12/09/23	16:01:48	14	100	6300	22.0 cm	24.4 Km/Hr	2200.0 mm/Km	2128	2.96	Good	25.725841	N	86.2191095	E	Normal
12/09/23	16:02:02	14	100	6400	24.0 cm	28.0 Km/Hr	2400.0 mm/Km	2313	3.19	Good	25.725594	N	86.2202158	E	Normal
12/09/23	16:02:15	14	100	6500	33.0 cm	26.4 Km/Hr	3300.0 mm/Km	3147	4.2	Good	25.725594	N	86.2202158	E	Normal

Handwritten signature and date 12/9/23

Handwritten signature and date 12/9/23

Handwritten signature and date 12/9/23

Name of work : BITHAN - JAGMOHRA															
Name of customer : M/S Jain Construction,															
(R)Rural Road															
Good					Average					Poor					
< 4000					4001 - 5000					> 5000					
12/09/23	16:01:33	14	100	6600	34.0 cm	19.8 Km/Hr	3400.0 mm/Km	3239	4.31	Good	25.725594	N	86.2202158	E	Normal
12/09/23	16:02:50	14	100	6700	38.0 cm	20.9 Km/Hr	3800.0 mm/Km	3610	4.75	Good	25.725594	N	86.2202158	E	Normal
12/09/23	16:03:05	14	100	6800	39.0 cm	24.9 Km/Hr	3900.0 mm/Km	3702	4.86	Good	25.725594	N	86.2202158	E	Normal
12/09/23	16:03:21	14	100	6900	31.0 cm	21.8 Km/Hr	3100.0 mm/Km	2962	3.98	Good	25.725594	N	86.2202158	E	Normal
12/09/23	16:03:40	14	100	7000	39.0 cm	19.0 Km/Hr	3900.0 mm/Km	3702	4.86	Good	25.725594	N	86.2202158	E	Normal
12/09/23	16:04:01	14	100	7100	36.0 cm	17.1 Km/Hr	3600.0 mm/Km	3425	4.53	Good	25.725594	N	86.2202158	E	Normal
12/09/23	16:04:18	14	100	7200	33.0 cm	20.9 Km/Hr	3300.0 mm/Km	3147	4.2	Good	25.725594	N	86.2202158	E	Normal
12/09/23	16:04:32	14	100	7300	34.0 cm	25.4 Km/Hr	3400.0 mm/Km	3239	4.31	Good	25.725594	N	86.2202158	E	Normal
12/09/23	16:04:45	14	100	7400	30.0 cm	28.2 Km/Hr	3000.0 mm/Km	2869	3.87	Good	25.725594	N	86.2202158	E	Normal
12/09/23	16:04:59	14	100	7500	20.0 cm	25.7 Km/Hr	2000.0 mm/Km	1943	2.73	Good	25.725594	N	86.2202158	E	Normal
12/09/23	16:05:12	14	100	7600	33.0 cm	27.9 Km/Hr	3300.0 mm/Km	3147	4.2	Good	25.725594	N	86.2202158	E	Normal
12/09/23	16:05:25	14	100	7700	32.0 cm	27.7 Km/Hr	3200.0 mm/Km	3054	4.09	Good	25.725594	N	86.2202158	E	Normal
12/09/23	16:05:37	14	100	7800	31.0 cm	29.4 Km/Hr	3100.0 mm/Km	2962	3.98	Good	25.725594	N	86.2202158	E	Normal
12/09/23	16:05:50	14	100	7900	39.0 cm	29.1 Km/Hr	3900.0 mm/Km	3702	4.86	Good	25.725594	N	86.2202158	E	Normal
12/09/23	16:06:04	14	100	8000	32.0 cm	24.9 Km/Hr	3200.0 mm/Km	3054	4.09	Good	25.705958	N	86.2288065	E	Normal
12/09/23	16:06:17	14	100	8100	29.0 cm	27.2 Km/Hr	2900.0 mm/Km	2776	3.76	Good	25.705376	N	86.2303553	E	Normal
12/09/23	16:06:32	14	100	8200	22.0 cm	23.6 Km/Hr	2200.0 mm/Km	2128	2.96	Good	25.705376	N	86.2303553	E	Normal
12/09/23	16:06:48	14	100	8300	34.0 cm	22.7 Km/Hr	3400.0 mm/Km	3239	4.31	Good	25.704579	N	86.2311335	E	Normal
12/09/23	16:07:10	14	100	8400	30.0 cm	17.1 Km/Hr	3000.0 mm/Km	2869	3.87	Good	25.704579	N	86.2311335	E	Normal
12/09/23	16:07:32	14	100	8500	30.0 cm	16.3 Km/Hr	3000.0 mm/Km	2869	3.87	Good	25.704579	N	86.2311335	E	Normal
12/09/23	16:07:55	14	100	8600	34.0 cm	15.6 Km/Hr	3400.0 mm/Km	3239	4.31	Good	25.704579	N	86.2311335	E	Normal
12/09/23	16:08:22	14	100	8700	35.0 cm	13.4 Km/Hr	3500.0 mm/Km	3332	4.42	Good	25.704579	N	86.2311335	E	Normal

Am 01/12/23
ce

12/19/23
A.D.

12/16/23

Name of work : BITHAN - JAGMOHRA

Name of customer : M/S Jain Construction,

(R)Rural Road

Good					Average					Poor					
< 4000					4001 - 5000					> 5000					
12/09/23	16:08:42	14	100	8800	32.0 cm	17.6 Km/Hr	3200.0 mm/Km	3054	4.09	Good	25.704579	N	86.2311335	E	Normal
12/09/23	16:08:58	14	100	8900	36.0 cm	21.8 Km/Hr	3600.0 mm/Km	3425	4.53	Good	25.704579	N	86.2311335	E	Normal
12/09/23	16:09:15	14	100	9000	32.0 cm	21.6 Km/Hr	3200.0 mm/Km	3054	4.09	Good	25.704579	N	86.2311335	E	Normal
12/09/23	16:09:31	14	100	9100	30.0 cm	22.9 Km/Hr	3000.0 mm/Km	2869	3.87	Good	25.704579	N	86.2311335	E	Normal
12/09/23	16:09:46	14	100	9200	38.0 cm	23.1 Km/Hr	3800.0 mm/Km	3610	4.75	Good	25.704579	N	86.2311335	E	Normal
12/09/23	16:10:01	14	100	9300	38.0 cm	24.0 Km/Hr	3800.0 mm/Km	3610	4.75	Good	25.704579	N	86.2311335	E	Normal
12/09/23	16:10:13	14	100	9400	37.0 cm	29.4 Km/Hr	3700.0 mm/Km	3517	4.64	Good	25.704579	N	86.2311335	E	Normal

12/09/23
A.E

12/09/23
A.E

12/09/23
A.E

Name of work : BITHAN - JAGMOHRA													
Name of customer : M/S Jain Construction,													
(R)Rural Road													
Good				Average				Poor					
< 4000				4001 - 5000				> 5000					
12/09/23	16:08:42	14	100	8800	32.0 cm	17.6 Km/Hr	3200.0 mm/Km	3054	4.09	Good	25.704579	N	86.2311335
12/09/23	16:08:58	14	100	8900	36.0 cm	21.8 Km/Hr	3600.0 mm/Km	3425	4.53	Good	25.704579	N	86.2311335
12/09/23	16:09:15	14	100	9000	32.0 cm	21.6 Km/Hr	3200.0 mm/Km	3054	4.09	Good	25.704579	N	86.2311335
12/09/23	16:09:31	14	100	9100	30.0 cm	22.9 Km/Hr	3000.0 mm/Km	2869	3.87	Good	25.704579	N	86.2311335
12/09/23	16:09:46	14	100	9200	38.0 cm	23.1 Km/Hr	3800.0 mm/Km	3610	4.75	Good	25.704579	N	86.2311335
12/09/23	16:10:01	14	100	9300	38.0 cm	24.0 Km/Hr	3800.0 mm/Km	3610	4.75	Good	25.704579	N	86.2311335
12/09/23	16:10:13	14	100	9400	37.0 cm	29.4 Km/Hr	3700.0 mm/Km	3517	4.64	Good	25.704579	N	86.2311335
												E	Normal
												E	Normal
												E	Normal
												E	Normal
												E	Normal
												E	Normal

Am 01/12/23

12/13/23
A.E

12/19/23
882