

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-2

पत्रांक: 307 अनु०
प्रेषक,

मुज०/दिनांक: 07/02/23

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल मुजफ्फरपुर, पूर्वी-2

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
बिहार ग्रामीण पथ विकास अभिकरण,
बिहार, पटना।

विषय: बिहार ग्रामीण पथ अनुरक्षण नीति- 2018 अनुरक्षण के तहत स्वीकृत योजनाओं के विरुद्ध
आवंटन की माँग करने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में वित्तीय वर्ष 2019-20 एवं 2022-23 नई अनुरक्षण
नीति अंतर्गत वित्तीय वर्ष 2022-23 में अनुरक्षण मद में व्यय हेतु संलग्न विवरणी के अनुसार 26.00000
(छब्बीस लाख रू० मात्र) का आवंटन उपलब्ध कराने की कृपा की जाये ताकि किये गये अनुरक्षण कार्यों
का भुगतान किया जा सके।

अनु०:- यथोक्त।

विश्वासभाजन



कार्यपालक अभियंता
ग्रामीण कार्य विभाग, कार्य प्रमंडल,
मुजफ्फरपुर पूर्वी-2

FORM GFR 19-A
Form of utilisation Certification up to month of Jun-2022
MR3054(CFMS)
RWD, Works Division, Muzaffarpur East-II

SL. NO.	Name of Scheme	Sanction No & Date with Amount (In Rs.)	Amount Received (In Rs.)	Particulars
1.	Construction of Rural Road under MR3054 (CFMS)	Secretary cum Empowered officer B.R.R.D.A Letter No.- Dated	Opening Balance- Rs. 33,40,91,008.00	Certified that out of Rs. 33,40,91,008.00 of grant in aid received during the Year 2021-2022 in favour of Executive Engineer R.W.D. Works Division, Muzaffarpur East-II. A sum of Rs. 32,90,98,891.00 has been utilized for the purpose of MR3054 (CFMS) schemes as given in the margin for which it was sanctioned and that the balance of Rs. 49,92,117.00 remaining unutilized at the end of the period under.
			Rs. + 0.00	
			Rs. 33,40,91,008.00 Rs. - 32,90,98,891.00 Rs. 49,92,117.00	
		Total	Rs. 33,40,91,008.00	


2. Certified that I have satisfied that the conditions on which the grants-in aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- I. Works have been supervised by Executive Engineer/ Superintending Engineer.
- II. Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- III. Construction material has been tested.
- IV. Measurements have been recorded in the MBS and test check conducted by the Assistant Engineer/Executive Engineer.
- V. All other codal formalities have been observed.

3. Physical progress achieved:

- i. Construction of Road Works.
- ii. Construction of CD Works.


 Executive Engineer
 RWD, Works Division
 Muzaffarpur East-2

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division :- Muzaaffarpur East-II

S. N.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) No. & Date	Administrative Approval (AA)			Agreement Amount (in Lakh)			Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allotted Amount (in Lakh)	Up-to-date expenditures per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in Km)	Amount (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5Year Routine Maintenance (in Lakh)	8	9										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19		
1	RM/MU/M UZ/22/0022	Improvement of N.H.-28 Kanti Belsar road to Bishunpur Village road.	31507201037	2002 Date-02.05.2022	2.78	101.5000	76.06080	31.21647	NR(3054)/MID-34/2022-23	18-07-2023	Ongoing	2094.720	25	5.020	65.80000	65.80000	10.00000		surface Completed	
2	RM/MU/M UZ/22/0022	Morsand main road Bahadurpur	31507302012	2002 Date-02.05.2022	2.960	97.2900	70.92516	30.30096	NR(3054)/MID-34/2022-23	18-07-2023	Ongoing	2397.280	25	5.020	54.70000	54.70000	16.00000		surface Completed	
																	26.00000			


(Signature)
Executive Engineer
RWD Works Division
Muzaaffarpur East-II


कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-2

प्रमाण-पत्र

प्रमाणित किया जाता है कि Morsand main road - Bahadurpur, Project ID- 31507302012 का सभी अवयवों की जाँच शत प्रतिशत कनीय अभियंता द्वारा किया गया है। सहायक अभियंता, द्वारा सभी अवयवों की 50 प्रतिशत से अधिक जाँच किया गया है। अधोहस्ताक्षरी द्वारा 10 प्रतिशत अवयवों की जाँच की गई है।


28.11.2022
कनीय अभियंता


सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल, मीनापुर


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल मुज0 पूर्वी-2

Name of Road-Morsand main road - Bahadurpur graph
Contractor Name-Sanjeev Construction

Sanjeev Construction												
Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEG ORY	Latitude	Longitude	Event	
		No.	in km	in mm	Rate	mm/km	mm/km					
12/11/22	16: 22: 38	1	0.1	140	0	1400	1506	ROAD	26.22777	85.30145	Normal	$Y = 0 * X^2 + 0.998 * X + 109.5$
12/11/22	16: 23: 0	1	0.1	180	40.4	1800	1905	G	26.22854	85.3017	Normal	X = 2500
12/11/22	16: 23: 0	1	0.1	230	40.4	2300	2404	G	26.2294	85.30202	Normal	Y = 2604
12/11/22	16: 23: 13	1	0.1	100	40.4	1000	1107	G	26.23036	85.30239	Normal	
12/11/22	16: 23: 13	1	0.1	210	30.3	2100	2205	G	26.23117	85.30273	Normal	RURAL ROAD
12/11/22	16: 23: 13	1	0.1	250	40.4	2500	2604	G	26.23213	85.30303	Normal	Good
12/11/22	16: 23: 13	1	0.1	220	40.4	2200	2305	G	26.23299	85.3033	Normal	Average
12/11/22	16: 23: 49	1	0.1	240	40.4	2400	2504	G	26.23381	85.30362	Normal	4001-5000
12/11/22	16: 24: 0	1	0.1	250	40.4	2500	2604	G	26.2347	85.30399	Normal	>5001
12/11/22	16: 24: 20	1	0.1	200	40.4	2000	2105	G	26.23557	85.30436	Normal	
12/11/22	16: 24: 50	1	0.1	250	40.4	2500	2604	G	26.23638	85.30471	Normal	
12/11/22	16: 24: 24	1	0.1	300	40.4	3000	3103	G	26.23727	85.30505	Normal	
12/11/22	16: 24: 24	1	0.1	210	40.4	2100	2205	G	26.23815	85.30539	Normal	
12/11/22	16: 24: 24	1	0.1	290	20.2	2900	3003	G	26.23902	85.30564	Normal	
12/11/22	16: 24: 24	1	0.1	210	30.3	2100	2205	G	26.2399	85.30588	Normal	
12/11/22	16: 25: 0	1	0.1	260	10.1	2600	2704	G	26.2407	85.30577	Normal	
12/11/22	16: 25: 35	1	0.1	200	10.1	2000	2105	G	26.2415	85.30527	Normal	
12/11/22	16: 25: 35	1	0.1	280	20.2	2800	2903	G	26.24208	85.30461	Normal	
12/11/22	16: 26: 0	1	0.1	210	30.3	2100	2205	G	26.24276	85.30391	Normal	
12/11/22	16: 26: 10	1	0.1	250	30.3	2500	2604	G	26.24341	85.30322	Normal	
12/11/22	16: 26: 10	1	0.1	270	20.2	2700	2804	G	26.2441	85.30249	Normal	
12/11/22	16: 26: 45	1	0.1	200	30.3	2000	2105	G	26.24486	85.30192	Normal	
12/11/22	16: 26: 45	1	0.1	210	30.3	2100	2205	G	26.24574	85.30152	Normal	
12/11/22	16: 27: 0	1	0.1	290	20.2	2900	3003	G	26.24674	85.30118	Normal	
12/11/22	16: 27: 19	1	0.1	270	10.1	2700	2804	G	26.24779	85.30121	Curve	
12/11/22	16: 28: 0	1	0.1	200	10.1	2000	2105	G	26.24834	85.30199	Normal	
12/11/22	16: 28: 0	1	0.1	250	10.1	2500	2604	G	26.24904	85.30252	Normal	
12/11/22	16: 29: 20	1	0.1	100	10.1	2500	2604	G	26.24969	85.3033	Normal	
12/11/22	16: 29: 55	1	0.04									
						AVG=2397.28						

Sanjeev Construction
12.11.2022
JE

Sanjeev Construction

Sanjeev Construction


Name of Customer : SANJEEV CONSTRUCTION
 Name of Work/ Road : Morsand main road - Bahadurpur
 Lab Job number :
 Date : 12-11-2022
 Section No. : 1

Print Generate Report and Graph

Test Date : 12-11-2022
 Machine No : 376
 Road Name : Morsand main road - Bahadurpur
 Road Type : (P) RURAL ROAD
 Side :
 Interval :
 UV Range : 107 To 4000 mm/km
 Dist Range : 0 To 2.9
 Start Location :
 End Location :
 Equation : $Y = 0 \cdot X^2 + 0.998 \cdot X + 109.5$

Redraw Graph Map View

File : C:\Users\DELL\Desktop\Bump Report\12.11.2022\Morsand main road - Bahadurpur-2.96\12111629 (2).xls
 Name of Customer : SANJEEV CONSTRUCTION, Name of Work/ Road : Morsand main road - Bahadurpur, Lab Job



Sanjeev
12/11/22
(ATTN)

12/11/22
SE

12/11/22

12/11/22