कार्यपालक अभियंता का कार्यालय, 🕶 ग्रामीण कार्य विभाग, कार्य प्रमण्डल, आरा ।

पत्रांक 290 अन् 0

प्रेषक.

कार्यपालक अभियंता. ग्रामीण कार्य विभाग कार्य प्रमण्डल, आरा ।

सेवा में.

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव ग्रामीण कार्य विभाग बिहार, पटना।

विषय:— बिहार ग्रामीण पथ अनुरक्षण नीति-2018 के तहत पथों की अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में सूचित करना है कि बिहार ग्रामीण पथ अनुरक्षण नीति—2018 के तहत पथों के भुगतान हेतु संलग्न विवरणी के अनुसार रू0—218.64600-लाख रू० की आवश्यकता है।

अतः अनुरोध है कि यथाशीघ्र उक्त राशि को आवंटित करने की कृपा की जाय, जिससे संवेदक का भुगतान किया जा सकें।

अनु० यथोंक्त।

1419212023

कार्यपालक अभियंता. ग्रामीण कार्य विभाग कार्य प्रमुण्डल, आरा।

Requisition Format for Scheme Head - MR (3054) under Bihar Rural Road Maintenance Policy - 2018 (Initial Rectification and Surface Renewal)

2.1.	7		. T	-	J		-			No.	
Signed Hard Up-to date P				23 Ara/12	MR-N/22-			2		Package No.	·
 Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed. Up-to date Physical Progress has been uploaded in MIS. 	Total	Dera (VR65)	L065-T06 Road to Bal Ka	(VR50)	MR-N/22- L050-T06 Road to Hajari Tola	101a (VR33)	L053-L048 Road to Khalifa	3		Name of Road	
of recorded IRI is ded in MIS.			10401602167		10401602146		10401602149	4		Project ID as per MIS	
enclosed.				022	1551/29.03.2			5		Admistrative Approval (AA) Letter No. & Date	
			0.720		4.000		1.920	6		Length (In km)	Adm Appro
			24.011		147.479		71.489	7		Amount (In Lakh)	Admistrative Approval (AA)
			20.857		134.89559		62.89341	8	,	Initial Rectification with Surface Renewal (In Lakh)	Agreement Amount (In Lakh)
			5.37341		26.29096		14.06254	9		5 Years Routine Maintenance (In Lakh)	umount (In h)
			11/MR3054/MB D/2022-23		11/MR3054/MB D/2022-23		11/MR3054/MB D/2022-23	10		Agreement No. & Date	
			26-Jun-23		26-Jun-23		26-Jun-23			Date of Completion Actual Date of as per Agreement Completion	
D .					.		١	1.6	13	Actual Date of Completion	
risional A	-		3208	+	3025	1	3080	;	12	IRI (In mm/km)	,
Divisional Accounts Officer R.W.D.(W) Div. Ara	,		25mm	1	25mm	1	25mm		14	ot Bitumen Layer (in mm)	Thickness
ice Wywy	-		5.0	1	5.0		5.0		15	Content in Percenta ge	Value of Bitumen
. 3			0.00000		0.00000		0.00000		16	Alloted Amount (In Lakh)	_
			0.00000		0.00000		0.00000		17	expenditu re as per MIS (In Lakh)	Up-to- date
Executive Engineer Rural Works Department Works Division, Ara		218.64600	20.85700		134.89559		62.89341		18	expenditu against work re as per done (In MIS (In Lakh) Lakh)	Requisition
Non/W		,	Completed	Physically	Completed	2	Physically Completed		19	Remarks	
									nett.		

Rural Works Department
Works Division, Ara

FORM GFR 19-A

(See Government of India's Decision (1) below Rule-150)

Form of utilisation Certification up to month of Feb, 2023

MR Maintenance Policy-2018

R.W.D. Works Division-Ara (Bhojpur)

SI. No.	Name of Scheme	Sanction No & Date with Amount (In Rs. Lacs)	Amount Received (In Rs. Lacs)	Particulars
1.	Construction of Rural Road under MR Maint. Policy-2018	Letter No-04 we Date- 10.01.2023	649207995.00	Certified that out of Rs. 649207995.00 Lacs of grant in aid received during the Year 2022-23 in favour of Executive Engineer, RWD Bihar R.W.D. Ara. A sum of Rs. 630095178.00 Lacs has been utilized for the purpose of MR Maint. Policy- 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 19112817.00 Lacs remaining unutilized at the end of the period under.
		Total	649207995.00	

2. Certified that I have satisfied myself that the conditions on which the grants-in aidwas sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- Works have been supervised by Executive Engineer/ Superintending Engineer. I.
- Periodical inspection has been conducted by Executive Engineer/Superintending II. Engineer.
- Construction materials have been tested. III.
- Measurements have been recorded in the MBS and test check conducted by the IV. Assistant Engineer/Executive Engineer.
- All other codal formalities have been observed. V.
 - 3. Physical progress achieved:
 - i. Construction of Road Works.
 - ii. Construction of CD Works.

Rural Works Department Works Div-Ara

Executive Engineer Rural Works Department Works Div. Ara


Date	THE ROAD TO KHALIFA TOLA CO
ime	9401-660
Section	ROAD TO KI
Longth	HALIFA TOU
Bumps	CONTRA
Speed	CONTRACTOR NAME-SH
OR	
IRI TEG	N YADAV

13/ 02/ 23 13/ 02/ 23	8: 31: 29 8: 32: 40 8: 32: 40 8: 33: 15 8: 33: 15 8: 33: 15 8: 33: 15 8: 35: 15 8: 35: 15 8: 35: 15 8: 35: 15 8: 37: 15 8: 37: 15 8: 37: 15			In mm 270 3.1 270 3.1 280 3.1 280 3.1 300 3.1 300 3.1 290 3.1 270 0.1 270 0.1 270 0.1 270 0.1 280 0.1 280 0.1 280 0.1 280 0.1 310 0.1 310 0.1 320 0.1 320 0.1 320 0.1 320 0.1 320 0.1 320		Te mn 10.1 10.1 20.2 20.2 20.2 20.2 10.1 10.1 20.2 20.2 20.2 20.2 20.2 20.2 20.2 20.2 20.2 20.2 20.2			25.72047 84.57623 Normal 25.71951 84.57623 Normal 25.71951 84.57623 Normal 25.71845 84.57561 Normal 25.71692 84.57584 Normal 25.71692 84.57565 Curve 25.7162 84.57623 Normal 25.71474 84.57727 Normal 25.71285 84.57727 Normal 25.71285 84.57784 Curve 25.71285 84.57784 Normal 25.71031 84.57874 Normal 25.70961 84.5795 Normal 25.70878 84.57934 Normal 25.70878 84.5795 Normal 25.70695 84.57966 Normal	tormal X = 2800 tormal X = 2800 tormal Y = 2787 tormal Y = 2787 tormal Good Avera tormal <4000 4001 Normal Curve Normal Normal Normal Normal Normal Normal Normal Normal Normal Normal
13/02/23	8: 32: 4	şa		and .	290	10.1	2900	3056 G	25.71951 84.57623 N	
13/02/23	8: 32: 40	-	۵	5.0	010	10.1	3100			ormal
13/02/23	8: 33: 0	-	4	-	780	20.2	2800	2976 G		lormal
13/02/23	6:33:15		4	2	780	20.2	2900	3000 G	25.71692 84.57565 (
13/02/23	8:33:15	ja-vak	1	9	300	20.2	3000	3187 6		
13/02/23	8: 34: 40	-	4	0,1	010	10.1	2800	2975 G	25.7155 84.57686 1	vormal
13/02/23	8: 35: 0	-	2	0	290	20.2	2900	3654 G	25.71474 84.57727 1	Vormal
13/02/23	oc 35: 15		4	0	270	20.2	2800	2954 G	25.71379 84.57755	Vormal
13/02/23	00 03 14 15		4	0	250	20.2	2600		25.71285 84.57784	Curve
EC /CO /ET	8 36 0		4	0	290	10.1	2900	3897 G		Normal
EC /CO /E:			A .		260	io.	2600	2789 G	25.71109 84.57842	Normal
57 190 Jet		•		3 (ORE	70 7	2800	7976 G	25.71031 84.57874	Normal
13/02/23	0		2		300	30 3	3000	2000	25,70961 84,579	Curve
13/02/23	50	5	14	0,1	300	20.2	3000	3 C C		Normal
13/02/23	00	UT.	14	0.1	240	20.2	2400	7207 6		Normal
13/03/33	œ		14	0.1	260	10.1	2600	2732 G	25,70766 64,3793	
20 100 101	p :	9	14	0	280	10.1	2800	2984 G	25.70695 84.57966	NOLLIP
13/ 02/ 23	. 0	(2	780	20.2	3400	3546 G	25.70605 84.57984 Normal	Normal
13/02/23	3 8: 39: 0		-	2 :	3 0 0	20.2	3200	3359 G	25.7053 84.57996 Normal	Normal
13/02/23	3 8: 39: 15	5	14	0.1	320	2.0.2			35 70455 84 58011 Normal	Normal
to let	9 9	n	Ā	0	300	20.2	3000	315/6	25.70455 64.36013	
13/02/23	3 8: 39: 13	U	7			_	TATOTAL	61608		

3.6 W1 Bym) (8)

AVERAGE

3080



प्रमाण पत्र

शीर्ष:— 3054 एम0आर0 (बिहार ग्रामीण पथ अनुरक्षण 2018)

L053-L048 Road to Khalifa Tola (VR53)

- 1. मापी पुस्त पर इस आशय का प्रमाण पत्र दर्ज है कि कार्य गुणवत्ता पूर्ण कराया गया है।
- 2. कराये गये कार्यों के सभी अवयवों के अवयववार 100 प्रतिशत कार्य का दर्ज मापी का सत्यापन कनीय अभियंता, 50 प्रतिशत मापी का सत्यापन सहायक अभियंता एवं 10 प्रतिशत मापी का सत्यापन कार्यपालक अभियंता द्वारा किया गया है।

कार्य प्रशाखा, बड़हरा

सहायक अभिय कार्य अवर प्रमंडल, बड़हरा

ग्रामीण कार्य विभाग कार्य प्रमंडल, आरा