

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बांका-1

पत्रांक-

बांका /

दिनांक-

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल बांका-1

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण पटना।

विषय:- New Maintenance Policy 2018 (MR 3054) योजना अन्तर्गत आवंटन के संबंध में।

महाशय,

उपर्युक्त विषयक से संबंधित एम0आर0 योजना अन्तर्गत संवेदक द्वारा कराए गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचित राशि रूपया **60.50000** लाख का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0:-

1. अधियाचना प्रपत्र
2. IRI Report

विश्वासभाजन

६०/-

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल बांका-1

ज्ञापांक- 227(अनु) बांका,

दिनांक- 13-02-2023

प्रतिलिपि- मुख्य अभियंता-4, ग्रामीण कार्य विभाग, बिहार, पटना को सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।

13/2/23
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल बांका-1

FORM GFR 19-A

(See Government of India's Decision (I) below Rule- 150
Form of Utilization Certificate up to the month 13.02.2023
MR New Policy 2018


PIU – R.W.D. Works Division Banka-1

SL. No.	Name of Scheme	Sanction No. & Date with	Amount (in lacs Rs.)	Amount Received (in Lacs Rs.)	Particulars
1.	Construction of Rural Roads under MR New Policy 2018	CFMS Letter No – 10 WE, Dt- 27.01.2023		10235.40111	Certified that out of Rs. 10235.40111 Lacs received upto the years 2022-23 in favour of Ex. Engineer, RWD Bihar, Banka-1 a sum of Rs. 10127.97174 lacs has been utilized for the purpose of MR New Policy 2018 Schemes as given in the margin for 107.42937 Lacs remaining unutilized at the end of the period under.
	Total			10235.40111	

2. Certified that I have satisfied may self that the conditions on which the grants in aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

- Kinds of Checks exercised-
- Works have been supervised by Executive Engineer/Superintending Engineer
 - Periodical inspection has been conducted by Executive engineer/Superintending Engineer
 - Construction materials have been tested.
 - Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer / Executive Engineer
 - All other codal formalities have been observed.
3. Physical Progress achieved-
- Construction of Road Works
 - Construction of C.D. Works



13.02.2023
Sr. Divisional Accounts Officer
Work Division
Rural Works Department
Banka-1


13.02.2023
Executive Engineer
Works Division
Rural Works Department
Banka-1

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Name of Division : Banka-1

Sl. No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allotted Amount (in Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
					Length (in Km)	Amount (in Lac)	Initial Rectification with Surface Renewal	5 years Routine Maintenance										
1	MR-N/22-23 Banka-1/06	Belhar Sandipi Road To Dumariya	20703602021	1304 23.03.2022	1.680	104.823	80.79925	13.64477	20 MBD/2022-23 Dt. 19.09.2022	19-05-23	N.A	3007	25	5%	0.000	0.00000	60.50000	PCC & BT Completed
Grand Total -																		60.50000


 13/12/23
 Executive Engineer
 BWD, Works Division
 Banka-1


**Office of the Executive Engineer
Rural Works Department, Works Division, Banka-1**


Name of Road :- Belhar Sandipi Road To Dumariya.
Name of Scheme :- 3054 / MR (New maintenance Policy 2018)
Name of contractor/Agency:- Mahendra Kumar Yadav
Length of Road :- 1.680 km
Project ID :- 20703602021
Package No. :- MR-N/ 22-23 Banka-1/06
Batch No. :- RM/BA/BAN/22/0028
Name of Block :- Belhar


Certified that
100% Measurement
has been checked by me

Certified that
50% Measurement
has been checked by me

Certified that
10% Measurement
has been checked by me


10/02/23
Junior Engineer RWD
Work section Belhar
Works Division : Banka-1


10/02/23
Assitant Engineer RWD
Work Sub Division Belhar
Works Division : Banka-1


24-13/2/23
Executive Engineer,
Rural Works Department,
Works Division : Banka-1

BELHAR-SANDIPI ROAD - DUMARIYA

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event	
7/2/23	14:24:14	59	0.1	200	0	2000	2233	G	24.93543	86.58643	Normal	$Y = 0 \cdot X^2 + 0.866 \cdot X + 501.6$
7/2/23	14:33:2	59	0.1	180	10.1	1800	2060	G	24.9362	86.58662	Normal	$X = 3600$
7/2/23	14:33:38	59	0.1	210	10.1	2100	2320	G	24.93702	86.58631	Normal	$Y = 3619$
7/2/23	14:34:0	59	0.1	190	10.1	1900	2147	G	24.9378	86.58579	Normal	
7/2/23	14:39:31	59	0.1	170	10.1	1700	1973	G	24.93833	86.58562	Normal	RURAL ROAD
7/2/23	14:40:41	59	0.1	300	20.2	3000	3099	G	24.93963	86.58571	Normal	Good
7/2/23	14:41:16	59	0.1	290	20.2	2900	3012	G	24.94051	86.58591	Normal	Average
7/2/23	14:42:0	59	0.1	320	20.2	3200	3272	G	24.94118	86.58564	Normal	4001-5000
7/2/23	14:42:27	59	0.1	330	10.1	3300	3359	G	24.94202	86.58556	Normal	>5001
7/2/23	14:43:2	59	0.1	350	20.2	3500	3532	G	24.94291	86.58554	Normal	
7/2/23	14:44:48	59	0.1	380	20.2	3800	3792	G	24.94285	86.58557	Normal	
7/2/23	14:45:0	59	0.1	290	10.1	2900	3012	G	24.94198	86.58564	Normal	
7/2/23	14:45:23	59	0.1	320	10.1	3200	3272	G	24.94109	86.58561	Normal	
7/2/23	14:46:0	59	0.1	360	0	3600	3619	G	24.94039	86.58589	Normal	
7/2/23	14:46:34	59	0.1	380	10.1	3800	3792	G	24.93952	86.58562	Normal	
7/2/23	14:47:9	59	0.1	360	20.2	3600	3619	G	24.93862	86.58551	Normal	

Sum
10/02/23
A.E.

Abhishek
10/02/23
J.E.

Sum
10/02/23
A.E.

Name of Customer : Mahendra Kumar Yadav
Name of Work/ Road : E.SANDHIA ROAD - DUNDARHATA
Lab Job number : 59
Date : 2/7/2023
Section No. : 59


Test Date :	2/7/2023	Fluid Name :	SAHICHI ROAD - JUMPIA	
Machine No :	407	Road Type :	(R) RURAL ROAD	
Start S No :		Side :		Interval
Start E No :		UV Range :	973 To 5000	mm/Å.m
Weather :		Dist Range :	0 To 17	0.1 = 1000 m
Start Location :		Equation :	$Y = 0.77 \cdot X + 0.015$	
End Location :				

PrintGenerate Report and Graph

Redraw Graph Map View

Map View

File : J:\Mahendra yadav\BELHAR-SANDIPI ROAD - DUMARIYA\ Xis, Section No. 59, Eqn : $Y = 0^{\circ} X^2 + 0.855X$
 Name of Customer : Mahendra Kumar Yadav, Name of Work/ Road :BELHAR-SANDIPI ROAD - DUMARIYA, Lab



13/12/23

10/02/23
A.E.

10/02/23
Lec 19