

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, भभुआ

Email ID:- bhabua.rwd@gmail.com

Mob:- 8986915314

पत्रांक.....49 अनु.....

भभुआ/दिनांक.....13/01/23

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, भभुआ

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव/
नोडल पदाधिकारी
BRRDA तीसरी मंजिल
भूमि विकास बैंक भवन,
बुद्ध मार्ग, पटना।

विषय :- मुख्यमंत्री ग्राम सम्पर्क योजना (एस0सी0) मद के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि मुख्यमंत्री ग्राम सम्पर्क योजना (एस0सी0) मद के अंतर्गत पथ में कराये गये कार्यों के विरुद्ध संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जा रही है। अधियाचित पथ का सभी डाटा MIS पर अद्ययतन है एवं उक्त पथ में कोई भी ATR लंबित नहीं है।

अनु :- यथोक्त।

विश्वासभाजन

13/01/23
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, भभुआ
13/01/23

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to 13 Jan. 2022

Sl.No	Name of Scheme	Sanction No.& Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
1	Construction of Rural roads Under MMGSY (SC)	MMGSY (SC) Work, BRRDA PATNA	6217.13102	Certified that out of Rs. 6217.13102 lakh of grants-in-aid sanctioned up to the years 2022-23 In favor of EE,RWD works division Bhabhua a sum of Rs. 6217.13102 lacs has been utilized for the purpose of MMGSY (SC) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 0.00000 lakh remaining unutilized at the end of the period under report.
Total:			6217.13102	

2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- i. Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii. Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii. Construction materials have been tested.
- iv. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- v. All other caudal formalities have been observed.


3. Physical Progress achieved:-

- i. Construction of Road Works.
- ii. Construction of CD works.



D.A.O.
R.W.D, Works Division
Bhabhua


15/01/23

Executive Engineer
R.W.D, Works Division
Bhabhua

12/01/23

Name of Division:- Bhabhua (Kaimur)

Rural Works Department
MMGSV (SC) Allotment Requisition Format

Sr. No.	Year	Name Of Road	Name of Contractor (in English)	Administrative Sanction		Agreement Amount (in Lacs)		Allotment Received (in Lacs)	Total Expenditure as per MIS (in Lacs)	Value of Measurement (in Lacs)	Current Demand (in Lacs) (11-9)	Remarks
				Length (in km)	Amount (in Lacs)	Main Work	Maintenance					
1	2	3	4	5	6	7	8	9	10	11	12	13
1	2019-20	L069 to Katra	Siya Enterprises And Construction	0.850	64.08000	50.18635	3.37949	42.69839	42.69839	49.2599	6.56151	Complete
Total:				0.850	64.08000	50.18635	3.37949	42.69839	42.69839	49.25990	6.56151	

Sumit Kaul
Divisional Accounts Officer
Rural Work's Department
Works Division- Bhabhua (Kaimur)

13/01/23
Executive Engineer
Rural Work's Department
Works Division- Bhabhua (Kaimur)
13/01/23