

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>2nd Final Bill</u>					
Name of Work - Construction of Road from house of					
Ranjeet Rai To house of Noreesh Rai					
Agency - M/s Maa Construction.					
Agg. No. 68/44654(SU)/SBD/2021-22					
Date of Commencement - 24.05.2021					
Date of Completion - 23.02.2022					
Date of Actual Completion - 30.06.2022					
<u>Item of Work.</u>					
Measurement - Nil.					
<u>Sub</u> 16/12/22 J. T. 41 <u>Sub</u> 15-1-23 A. E					

<u>ABSTRACT COST.</u>	
J. No. 1 - Clearing & Graveling.	
Vide P. to 05 in T. 4 B.	
0.067 Ha ar - 52970 = 33 R - 3549 = 0	
J. No. 2 - Paving & fixing of rocky	
Benches on the P. 105	
Vide P. to 05 in T. 4 B.	
0.335 km ar - 12830 = 82 / km - 4298 = 0	
J. No. 03 - Excavation of R/W cut	
Vide P. to 05 in T. 4 B.	
25.134 ³ ar - 130 = 83 4/2 R - 3288 = 0	
J. No. 04 - Construction of culvert	
with excavation.	
Vide P. to 05 in T. 4 B.	
15.074 ³ ar - 96 = 75 1/4 R - 1458 = 0	
R - 12593 = 0	

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					Rs 12593=00
S.40.05 Construction of G.S.B.					
Gravel etc carpet					
Vide P.40.05 in P.403					
40.374 ³ Rs - 3353=60 4 ³ Rs - 135385=00					
S.40.06 - Paving and laying work					
Gravel etc - Complete					
Vide P.40.05 in T.7.13					
95.164 ³ Rs - 4522=67 4 ³ Rs - 430377=00					
S.40.07 - Construction of concrete					
Cement Concrete 430					
In Pavement etc etc					
Vide P.40.05 in P.403					
203.004 ³ Rs - 8102=36 4 ³ Rs - 1644779=00					
S.40.08 - Construction of subgrade					
and another stables.					
Vide P.40.06 in T.7.13					
161.214 ³ Rs - 183=34 4 ³ Rs - 29556=00					
S.40.09 - Construction of outcropment					
with app and soil 1000 4.					
Vide P.40.06 in T.7.13					
445.92 4 ³ Rs - 197=04 4 ³ Rs - 87864=00					
S.40.10 - Paving of road etc					
Vide P.40.06 in P.403					
167.504 ³ Rs - 552=26 4 ³ Rs - 92504=00					
					Rs - 2433058=00

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					R-2433058=0
S.No. 11. Poorly affixing Roof					
Marking Paint etc.					
Vide P.Fo. 06 in T.Y.B.					
67.00 Y ² R - 859 = 51 Y ² R - 57889=0					
S.No. 12. Poorly affixing km					
Post.					
Vide P.Fo. 06 in T.Y.B.					
01 No. Road - 2364 = 25 Back - 2364=0					
S.No. 13. Poorly affixing 2000					
meter Post.					
Vide P.Fo. 06 in T.Y.B.					
02 No. Road - 640 = 48 Back - 1281=0					
S.No. 14. Poorly affixing dam					
Board.					
Vide P.Fo. 07 in T.Y.B.					
01 No. Road - 10185 = 58 Back - 10186=0					
S.No. 15. Poorly affixing Pillar.					
Vide P.Fo. 07 in T.Y.B.					
12 No. Road - 527 = Back - 6324=0					
S.No. 16. Poorly affixing Traffic					
Sign Board.					
(1) 600 m. eg. Triangle.					
01 No. Road - 3514 = 61 Back - 3515=0					
					R-2514617=0

Continuation

Part

Details of actual measurement	Contents of area		
No.	L.	B.	D.
Rs 2514617=0			
4-10-16- Paving string 600			
on on Circles.			
Vide P. 40. 07 in T. 4 B.			
01 No 2R - 4694 = 92 Back 4695 = 4.			
Sub 17- Paving and fixing			
of typical 44554 sqm			
Bond with 2 logs.			
Vide P. 40. 07 in T. 4 B.			
03 No 2R - 10294 = 11 Back 30882 = 0			
4-10-16 (M) 600mm x 450mm.			

Vide P. No 07 in T. 4 B.			
01 No 2R - 4574 = 10 Back 4574 = 0			
4-10-16. Paving string 300mm.			
R.C.C. duct pipe.			
Vide P. 40. 07 in T. 4 B.			
05 No 2R - 956 = 62 Back 4783 = 0.			
R - 2559577 = 0			
Add 12 f. G. S. T. - R - 307146 = 0			
Add 1 f. below G. S. R - 25595 = 0			
Add 1-20 f. spring R - 30715 = 0			
R - 2923003 = 0			
Less 20 f. below - R - 584601 = 0			
R - 2338402 = 0			
Less 20 f. below - R - 1309528 = 0			
R - 1028874 = 0			

76/12/22
J.E. T...

Continuation

13-1-22
A.E.