

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, झंझारपुर ।

पत्रांक 14593^{EP} / दिनांक 18/07/2023

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, झंझारपुर ।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी
-सह- सचिव
ग्रामीण कार्य विभाग,
पटना।

विषय : शीर्ष 3054MR योजना अंतर्गत विहार ग्रामीण पथ अनुरक्षण नीति - 2018 के तहत स्वीकृत कार्यों के आवंटन की मांग के संबंध में।

प्रसंग : भवदीय पत्रांक मु०अ०-4 (मु०)-3054-04-251/2018 - 113 अनु पटना दिनांक 10.01.2020

महाशय,

उपरोक्त विषयक प्रासांगिक पत्र के आलोक में शीर्ष 3054 MR योजना अंतर्गत विहार ग्रामीण-पथ अनुरक्षण नीति - 2018 के तहत स्वीकृत कार्यों में कृत कार्य के भुगतान हेतु विहित प्रपत्र में अधियाचना तैयार कर आवश्यक कार्रवाई हेतु समर्पित की जा रही है।

अतः अनुरोध है कि आवंटन उपलब्ध कराने की कृपा की जाय।

अनु. - विहित प्रपत्र में अधियाचना प्रपत्र

बम्प इन्टिग्रेटर मशीन से लिया गया प्रतिवेदन

विश्वासभाजन

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग, कार्य प्रमंडल,

18/7/23 झंझारपुर

Form GFR 19- A
(See Government of India's Decision (I) below Rule - 150)
Form of Utilization Certificate upto the month July
New Maintenance Policy 2018

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (In lacs)	Amount Received (In lacs)	Particulars
1	1	96 enc/ Dt.07.07.2023	2903.98764	Certified that Rs:- 2903.98764 Lac received Till the date in favour of Executive Engineer, RWD Work Division Jhanjharpur. A sum of Rs 2877.57179 Lac has been utilized for the purpose of NEW_MR Scheme as given in the margin for which it was sanctioned and that the balance of Rs 26.41585 Lacs remaining.
		Total :	2903.98764	

Certified and verified myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.


Kinds of Checks exercised :-

- i Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii Construction material have been tested.
- iv Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- v All other codal formalities have been observed.

Physical Progress achieved :-

- i Construction of Road works.
- ii Construction of CD works



D.A.O.
RWD Works Division
Jhanjharpur


Executive Engineer
RWD works Division
Jhanjharpur

P.W.
18/7/23

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)
Name of Division :Jhanjharpur

Sl. No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)	Agreement Amount (in Lac)	Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (in Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
1	RM/MA/JHA/22/0011	1. KAMALA PASCHIMI TATBAND H GADIYA SE NARU AAR JANE WALI PATH KI MARRAM ATI(Jhanjharpur)	31909808085	1590/30.0 3.2022	Length (in Km) 0.386 Amount (in Lac) 30.83800	Initial Rectification with Surface Renewal (in lac) 27.35335 5 years Routine Maintenance (in lac) 2.48927	29XIBD/22-23DG-31.01.2023	30-01-2024	10.06.2023	3505.00	25mm	5.0%	0.00000	0.00000	27.33818	Completed
															27.33818	


D.A. Jha
RWD Works Division
Jhanjharpur


Executive Engineer
RWD Works Division
Jhanjharpur
18/11/23

Name of work : KAMALA PASCHIMI TATBANDH GADIYA SE NARUAAR JANE
WALI PATH KI MARIRAMATI(Jhanjharpur)

Name of customer : M/S Jaiubansh Kumar Singh

(R)Rural Road

Poor

Good

Average

> 5000

4001 - 5000

< 4000


Date	Time	Test No	Distance(m)	Total Distance(m)	BUMP(cm)	Speed(Km/Hr)	UI(mm/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
09/06/23	13:58:34	68	100	100	23.0 cm	10.7 Km/Hr	2300.0 mm/Km	2516	3.44	Good	26.2580882	N	86.2444551	E	Normal
09/06/23	14:00:01	68	100	200	24.0 cm	12.5 Km/Hr	2400.0 mm/Km	2618	3.57	Good	26.2575344	N	86.2437340	E	Normal
09/06/23	14:00:44	68	100	300	25.0 cm	12.3 Km/Hr	2500.0 mm/Km	2720	3.69	Good	26.2566292	N	86.2430207	E	Normal
09/06/23	14:01:21	68	100	400	22.0 cm	19.9 Km/Hr	2200.0 mm/Km	2413	3.32	Good	26.2552790	N	86.2433150	E	Normal

Wd 9/6/23

9/6/23

9/6/23

ubansh Kumar Singh , Machine no: 19198 , Road: KAMALA PASCHIMI TATBANDH GADIYA SE NARUAAR JANE WALI PATH KI MARRAMATI(Jhunjharpur) , Date: 09-06-23 , Section No: 68




09/7/23
ATTM

09/6/23

09/6/23

ref M/S Jadhavansh Kumar Singh, Machine no: 19198, Road: KAMALA PASCHIMI TATBANDH GADIYA SE NARUWAR JANE WALI PATH KI MATRAMATIJhanpur, Date: 09-06-23, Section No: 68, Equation: Y



18/6/23
ASLM

W
10/7/23