

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल दरभंगा-2

पत्रांक 1191 /

दिनांक 11/07/2023 /

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्र0, दरभंगा-2

सेवा में,

नोडल पदाधिकारी,
(3054-एम0आर0)
विश्वेश्वरैया भवन, पटना।

विषय:-

शीर्ष-3054 (नई अनुरक्षण नीति-2018) अन्तर्गत पूर्ण किये गये पथों में आवंटन माँग हेतु अधियाचना पत्र समर्पित करने के संबंध में।

महाशय,

उपर्युक्त विषयक के संबंध में गैर योजना मद शीर्ष-3054 (नई अनुरक्षण नीति-2018) अन्तर्गत पूर्ण किये गये पथ में आवंटन माँग हेतु राशि की अधियाचना विहित प्रपत्र तैयार कर समर्पित की जा रही है।

अतः श्रीमान् से अनुरोध है कि रु0 74.32993 लाख (कुल चौहत्तर लाख बत्तीस हजार नौ सौ तेरान्चे) मात्र रुपये का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0:- यथोक्त।

विश्वासभाजन

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग, कार्य प्र0, दरभंगा-2

Networks Division:- RWD Works Division Darbhanga-2

1. Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed.
2. Up to date Physical Progress has been uploaded in MIS

Executive Engineer
RWD Works Division Darbhang-2

06/07/23

FORM GFR 19-A

(See Government of India's Decision (1) below Rule- 150)

Form of Utilisation Certificate up to the month of July-2023

Head 3054 Account for M.R (New Maintenance Policy-2018) Yojna. Year 2023-24

PIU Darbhanga-2

Sl. No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Laes)	Amount Received (in Rs. Laes)	Particulars
1	Maintenance Account for Head 3054 Account for MR R (New Maintenance Policy- 2018) Yojna	Additional CEO-cum- Secretary Patna. Letter No-78 We Date- 24.05.2023	Rs. 1607.87862	Certified that out of Rs 1607.87862 laes received during the years 2023-24 in favour of Ex. Engineer RWD work division Darbhanga-2 a sum of Rs 1583.51624 laes has been utilized for the purpose of Maintenance Account for Head 3054 M.R (New Maintenance Policy-2018) Schemes as given in the margin for which it was sanctioned and that the balance of Rs 24.36238 laes remaining unutilized at the end of the period under.
	Total		1607.87862	


2. Certified that I have satisfied myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Constructions materials have tested.
- Measurements have been recorded in the MBs and test check conduction by the Assistant Engineer/ Executive Engineer
- All other codal formalities have been observed.


D. A. O.

R.W.D. Works Division
Darbhanga-2


Executive engineer,
R.W.D. Works Division
Darbhanga-2
06/07/23


कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमण्डल दरभंगा-2

प्रमाण-पत्र

विभागीय आदेशानुसार सत्यापित किया जाता है कि शीर्ष 3054 (नई अनुरक्षण नीति-2018) अन्तर्गत Madhopatti To Sundarpur तक पथ मरम्मत कार्य की जॉच 100 प्रतिशत संबंधित कनीय अभियंता, 50 प्रतिशत संबंधित सहायक अभियंता एवं 10 प्रतिशत कार्यपालक अभियंता द्वारा कर लिया गया है।

Ranbir
04/07/23
7.8

Ranbir
14/7/23
A.E.


कार्यपालक अभियंता,
ग्रामीण कार्य विभाग, कार्य प्र0, दरभंगा-2
06/07/23

NAME OF VILLAGE MADHOPATI TO SUNDARPUR

NAME OF ENGINEER ROHIT JAISWAL

(R/Rural Road

Grade	Average	Foot
4000	4001 - 5000	5000


Date	Time	Test No	Endurance	Total Distance	En. M/Person	Speed Km/Hr	Ultimate Km	Corrected U ₁ (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction	Remarks
18.06.23	14:13:52	55	100	100	26.0 cm	15.0 Km/Hr	2400.0 mm/Km	2896	0.55	Good	26.2341541	N	85.8565428	E	Normal
18.06.23	14:14:24	55	100	100	34.0 cm	12.2 Km/Hr	3400.0 mm/Km	2948	4.44	Good	26.233826	N	85.8550404	E	Normal
18.06.23	14:14:44	55	100	200	33.0 cm	17.8 Km/Hr	3300.0 mm/Km	3255	4.33	Good	26.2333048	N	85.8527959	E	Normal
18.06.23	14:15:05	55	100	300	35.0 cm	17.5 Km/Hr	3500.0 mm/Km	3441	4.55	Good	26.2313373	N	85.8514878	E	Normal
18.06.23	14:15:25	55	100	400	31.0 cm	17.8 Km/Hr	3100.0 mm/Km	2990	4.11	Good	26.2308651	N	85.8503763	E	Normal
18.06.23	14:15:47	55	100	500	23.0 cm	16.3 Km/Hr	2300.0 mm/Km	2728	3.21	Good	26.2312786	N	85.851994	E	Normal
18.06.23	14:16:06	55	100	600	25.0 cm	18.4 Km/Hr	2500.0 mm/Km	2614	3.44	Good	26.230842	N	85.850559	E	Normal
18.06.23	14:16:23	55	100	700	36.0 cm	21.8 Km/Hr	3600.0 mm/Km	3034	4.66	Good	26.231041	N	85.852923	E	Normal
18.06.23	14:16:38	55	100	800	26.0 cm	23.9 Km/Hr	2600.0 mm/Km	2792	3.78	Good	26.231056	N	85.853058	E	Normal
18.06.23	14:16:53	55	100	900	35.0 cm	23.4 Km/Hr	3500.0 mm/Km	3141	4.55	Good	26.231364	N	85.8528175	E	Normal
18.06.23	14:17:08	55	100	1000	32.0 cm	24.4 Km/Hr	3200.0 mm/Km	3163	4.22	Good	26.231568	N	85.8527405	E	Normal
18.06.23	14:17:22	55	100	1100	37.0 cm	25.2 Km/Hr	3700.0 mm/Km	2826	4.77	Good	26.231079	N	85.8527177	E	Normal
18.06.23	14:17:37	55	100	1200	34.0 cm	24.5 Km/Hr	3400.0 mm/Km	2848	4.44	Good	26.230882	N	85.8526841	E	Normal

18/06/23
J.E

18/06/23
J.E

Executive Engineer
R.W.D.(V) Division
Darbhanga-2

Name of Customer: ROHIT JAISWAL , Machine no: 19195, Road: MADHOPATTI TO SUNDARPUR , Date: 18/06/23 , Section No: 55 , Equation: $Y = 0.927 X + 196.3$



Bank
18/06/23
J.P.

Bank
18/06/23
J.P.

11/7/23
Executive Engineer
R.W.D.(A) Division
Parbhanga-2