



कार्यपालक अभियन्ता का कार्यालय
ग्रामीण कार्य विभाग , कार्य प्रमण्डल राजगीर (नालन्दा)
Email:- rwdrajgir@gmail.com, ee.rajgir@rwdbihar.in

पत्रांक... 663 (अड्डा)

राजगीर

दिनांक... 20.07.2023

प्रेषक,

कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल राजगीर।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
ग्रामीण कार्य विभाग,
पटना।

विषय:- नई अनुरक्षण नीति 2018 शीर्ष MR-3054 योजना मद अन्तर्गत व्यय हेतु आवंटन की माँग के संबंध में।

महाशय,

उपर्युक्त विषयक नई अनुरक्षण नीति 2018 शीर्ष MR-3054 योजना मद अन्तर्गत व्यय हेतु विहित प्रपत्र में अध्याचना पत्र संलग्न कर भेजी जा रही है।

अतः अनुरोध है कि संलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाय। ताकि कराये गये कार्यों का भुगतान किया जा सके। संबंधित संवेदक का इस प्रमण्डल में कोई ATR लम्बित नहीं है।

अनु०:- यथोक्त।

विश्वासभाजन

[Signature]
20/07/2023

कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल राजगीर
[Signature]
20/07/23

FORM GFR 19-A

(See Government of India's Decision(I) below Rule-150)

Utilisation Certificate upto the month of July- 2023

STATE - BIHAR

MR(3054) New Maintaince Policy 2018

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (In Rs. Lacs)	Amount Received (In Lacs)	Particulars
1	MR(3054) New Maintaince Policy 2018	Letter No.-96 Date- 07.07.2023	3571.95790	Certified that out of 3571.95790 Lacs of grants-in-aid sanctioned during the years 2020-21, 2021-22, 2022-2023 & 2023-24 in favour of E-in-C, RWD Bihar, Patna a sum of Rs 3491.38800 lacs has been utilized for the purpose of MR(3054) New Maintaince Policy 2018 as given in the margin for which it was sanctioned and the balance of Rs 80.56990 remaining unutilized at the end of the period under.
		Total	3571.95790	

Certified that I have satisfied my self that the conditions on which the grants-in-aid was sanctioned have been

- 2 duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.

Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer./

- Executive Engineer.
- All other codal formalities have been observed.


3 Physical Progress achieved :-

- Construction of Road Works
- Construction of CD works.




DAO

RWD, Works Division
Rajgir (Nalanda)



Executive Engineer
RWD, Works Division
Rajgir (Nalanda)






RWD. Works Division : Rajgir

- 1 Signed Hard Copy and Soft Copy (In Excel) of recorded IRI is enclosed.
- 2 Up-to-date Physical Progress has been uploaded in MIS

Executive Engineer
RWD (W) Division Rajgir
Amoal
११/१२

File : D:\Office\Allotment Requestion\Bump Report\18.07.2023 Global solution dk verma and pankaj
 Name of Customer : Pankaj Kumar. Name of Work/ Road : L029-T02 R.P PWD Rd to Bilari. Lab Job number :



Mkm
 10/07/23
 (J.E)

Devin
 19/7/2023

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
19/7/23	16:04:36	20	0.1	280	40.4	2800	3313	G	25.07386	85.621972	Normal
19/7/23	15:34:45	20	0.1	270	30.3	2700	3199	G	25.07335	85.624094	Normal
19/7/23	15:34:56	20	0.1	320	20.2	3200	3467	G	25.07345	85.624067	Curve
19/7/23	15:35:07	20	0.1	280	20.8	2800	3313	G	25.07325	85.624132	Normal
19/7/23	15:35:18	20	0.1	310	30.3	3100	3254	G	25.07250	85.623789	Normal
19/7/23	15:35:27	20	0.1	260	20.2	2600	3686	G	25.07220	85.623935	Speed Breaker
19/7/23	15:35:38	20	0.1	270	30.3	2700	3199	G	25.07009	85.624026	Normal
19/7/23	15:35:47	20	0.1	290	30.3	2900	3426	G	25.06940	85.623731	Normal
19/7/23	15:35:56	20	0.1	320	20.2	3200	3767	G	25.06851	85.62333	Speed Breaker
19/7/23	15:36:05	20	0.1	260	20.2	2600	3386	G	25.06625	85.623049	Normal
19/7/23	15:36:16	20	0.1	270	30.3	2700	3199	G	25.06758	85.622878	Normal
19/7/23	15:36:25	20	0.1	240	30.3	2400	2858	G	25.06732	85.622745	Normal
19/7/23	15:36:36	20	0.1	290	30.3	2900	3426	G	25.06485	85.622476	Normal
19/7/23	15:36:45	20	0.1	290	30.3	2900	3426	G	25.06476	85.622388	Normal
19/7/23	15:36:56	20	0.1	240	20.2	2400	2858	G	25.06405	85.622866	Normal
19/7/23	15:37:09	20	0.1	320	20.2	3200	3267	G	25.06420	85.621677	Curve
19/7/23	15:37:20	20	0.1	280	20.2	2800	3313	G	25.06612	85.62212	Normal
19/7/23	15:37:31	20	0.1	310	20.2	3100	3454	G	25.06124	85.621637	Normal

$$Y = 0 * X^2 + 1.136 * X + 132.5$$

$$X = 5507$$

$$Y = 6388$$

(R) RURAL ROAD

Good Average Poor
4000 4001-5000 >5001

Mdm
19/07/23
(J.E)

Qm
19/7/23

