

कार्यालय
कार्यपालक अभियंता, ग्रामीण कार्य विभाग
कार्य प्रमंडल, दलसिंहसराय, समस्तीपुर

पत्रांक 716/22 दलसिंहसराय / दिनांक 03/06/2023

प्रेषक, कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, दलसिंहसराय

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी,
सचिव –सह– प्राधिकृत पदाधिकारी, बिहार
ग्रामीण पथ विकास एजेंसी पटना।

विषय— **New Maintenance Policy 2018** योजनान्तर्गत पथ में आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में कहना है कि **New Maintenance Policy 2018** योजनान्तर्गत चल रहे पथ के निर्माणधीन कार्य के विरुद्ध चल रहे योजनाओं का भुगतान हेतु मो0-181.17326 लाख की आवश्यकता है। अधियाचना का निर्माण कार्य विशिष्टियों के अनुरूप है तथा कार्य संतोषप्रद है।

अतः अनुरोध है कि अधियाचना पत्र के आधार पर आवंटन हेतु मो0-181.17326 लाख उपलब्ध कराने की कृपा की जाय।

अनु0- 1) अधियाचना प्रपत्र।

2) 19ए फॉर्म।

विश्वासभाजन

03/06/23

कार्यपालक अभियंता

ग्रामीण कार्य विभाग

03/06/23
कार्य प्रमंडल, दलसिंहसराय

FROM GFR-19-A

(See Govt. of India's decision(i) below rule 150)

Form of Utilisation Certificate upto June.-2023

New Maintenance Policy 2018(MR New)

PIU;- RWD Works Division Dalsinghsarai

Sl No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lakh)	Amount Received (in Lakh)	Particulars
1	2	3	4	5
1	New Maintenance Policy 2018 (MR New)	3735.32146	3735.32146	Certified that out of Rs-3755.32146 Lakh received till date in favour of Executive Engineer, RWD Works Division Dalsinghsarai a Sum of Rs-3720.32060 Lakh has been utilized for the New Maintenance Policy 2018(MR New) Scheme as given in the margine for which it was Sanctioned and that the Balance of Rs-15.00086 1 Lakh remaining unutilized at the end of period under the time of completion
		3735.32146	3735.32146	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was

Kind of Checks Exercised:-

- (i) Workers have been supervised by Executive Engineer/ Superintending Engineer
- (ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- (iii) Construction materials have been tested
- (iv) Measurments have been recorded in the MB's and test check conducted by the
- (v) All other codal formalities have overserved

3. Physical Progress Achieved

- (i) Construction of Road Works
- (ii) Construction of CD Works


Sr.DAO 03/06/23

Rural Works Department,
Works Division Dalsinghsarai


Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

Rural Works Department, Works Division Dalsinghsarai

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)


Name of Division : PU(Dalsinghsarai)

Sl No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
					Length (in Km)	Amount (in Lac)	Initial Rectification with Surface Renewal (in lac)	5 years Routine Maintenance (in lac)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/SA/DAL/22/000	LO23-MDR TO3 to Mahiti (VR23)	32010402052	1424/26.03/22	4.980	265.34000	226.46658	51.76644	MIBD 06/32-24 15.05.2023	14.02.2024	-	3304	25mm	5.10%	0.00000	0.00000	181.17326	
TOTAL					4.980	265.340	226.467	51.766							0.00000	0.00000	181.17326	

- Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed
- Up-to date Physical Progress has been uploaded in MIS

Sr Divisional Account Officer
Rural Works Department,
Works Division Dalsinghsarai

Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai



03/06/2023
 Pte

03/06/23

Name of the work: L023-MDR T03 to Mahiti (VR23)

Date	Time	Test No	Distance (meter)	Total Distance (meter)	BUMP (cm)	Speed (Km/Hr)	UI (mm/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
03/06/2023	10:54:16	55	100	100	25.0 cm	11.7 Km/Hr	2500.0 mm/Kr	2397.5	3.298	Good	25.71002	N	85.979672	E	Normal
03/06/2023	10:54:41	55	100	200	27.0 cm	14.2 Km/Hr	2700.0 mm/Kr	2579.3	3.52	Good	25.70943	N	85.980579	E	Normal
03/06/2023	10:55:03	55	100	300	25.0 cm	16.0 Km/Hr	2500.0 mm/Kr	2397.5	3.298	Good	25.70934	N	85.981699	E	Normal
03/06/2023	10:55:21	55	100	400	23.0 cm	20.4 Km/Hr	2300.0 mm/Kr	2215.7	3.074	Good	25.70917	N	85.98286	E	Normal
03/06/2023	10:55:39	55	100	500	29.0 cm	19.6 Km/Hr	2900.0 mm/Kr	2761.1	3.741	Good	25.70903	N	85.983947	E	Normal
03/06/2023	10:55:54	55	100	600	26.0 cm	24.3 Km/Hr	2600.0 mm/Kr	2488.4	3.409	Good	25.70883	N	85.984841	E	Normal
03/06/2023	10:56:12	55	100	700	21.0 cm	19.8 Km/Hr	2100.0 mm/Kr	2033.9	2.847	Good	25.70856	N	85.985743	E	Normal
03/06/2023	10:56:32	55	100	800	24.0 cm	17.4 Km/Hr	2400.0 mm/Kr	2306.6	3.186	Good	25.70821	N	85.986709	E	Normal
03/06/2023	10:56:49	55	100	900	21.0 cm	21.1 Km/Hr	2100.0 mm/Kr	2033.9	2.847	Good	25.70905	N	85.987204	E	Normal
03/06/2023	10:57:56	55	100	1000	23.0 cm	17.9 Km/Hr	2300.0 mm/Kr	2215.7	3.074	Good	25.70911	N	85.98818	E	Normal
03/06/2023	10:58:21	55	100	1100	28.0 cm	14.2 Km/Hr	2800.0 mm/Kr	2670.2	3.631	Good	25.70908	N	85.98928	E	Normal
03/06/2023	10:58:54	55	100	1200	37.0 cm	11.3 Km/Hr	3700.0 mm/Kr	3488.3	3.609	Good	25.70963	N	85.990009	E	Normal
03/06/2023	10:59:21	55	100	1300	25.0 cm	13.0 Km/Hr	2500.0 mm/Kr	2397.5	3.298	Good	25.71051	N	85.990192	E	Normal
03/06/2023	10:59:49	55	100	1400	30.0 cm	12.8 Km/Hr	3000.0 mm/Kr	2852	3.851	Good	25.71149	N	85.990363	E	Normal
03/06/2023	11:00:19	55	100	1500	32.0 cm	12.0 Km/Hr	3200.0 mm/Kr	3033.8	3.069	Good	25.71845	N	85.990763	E	Normal
03/06/2023	11:00:50	55	100	1600	22.0 cm	11.9 Km/Hr	2200.0 mm/Kr	2124.8	2.961	Good	25.71221	N	85.990763	E	Normal
03/06/2023	11:01:27	55	100	1700	32.0 cm	11.9 Km/Hr	3200.0 mm/Kr	2145.8	1.236	Good	25.71243	N	85.991441	E	Normal
03/06/2023	11:01:53	55	100	1800	24.0 cm	13.5 Km/Hr	2400.0 mm/Kr	2306.6	3.186	Good	25.71288	N	85.992435	E	Normal
03/06/2023	11:02:20	55	100	1900	26.0 cm	13.7 Km/Hr	2600.0 mm/Kr	2488.4	3.409	Good	25.71307	N	85.993385	E	Normal
03/06/2023	11:02:49	55	100	2000	25.0 cm	12.4 Km/Hr	2500.0 mm/Kr	2397.5	3.298	Good	25.71358	N	85.994385	E	Normal
03/06/2023	11:03:36	55	100	2100	31.0 cm	17.6 Km/Hr	3100.0 mm/Kr	2942.9	3.44	Good	25.71365	N	85.994955	E	Normal
03/06/2023	11:04:16	55	100	2200	37.0 cm	18.9 Km/Hr	3700.0 mm/Kr	3488.3	3.609	Good	25.71888	N	85.99717	E	Normal
03/06/2023	11:04:50	55	100	2300	28.0 cm	10.8 Km/Hr	2800.0 mm/Kr	2670.2	3.631	Good	25.7193	N	85.996292	E	Normal
03/06/2023	11:11:27	55	100	2400	31.0 cm	10.8 Km/Hr	3100.0 mm/Kr	2942.9	3.236	Good	25.71968	N	85.995368	E	Normal
03/06/2023	11:11:59	55	100	2500	25.0 cm	11.3 Km/Hr	2500.0 mm/Kr	2397.5	3.298	Good	25.72014	N	85.994239	E	Normal
03/06/2023	11:12:41	55	100	2600	30.0 cm	18.4 Km/Hr	3000.0 mm/Kr	2852	3.851	Good	25.72035	N	85.993374	E	Normal
03/06/2023	11:13:36	55	100	2700	23.0 cm	16.7 Km/Hr	2300.0 mm/Kr	2215.7	3.074	Good	25.72051	N	85.992379	E	Normal
03/06/2023	11:14:20	55	100	2800	31.0 cm	18.0 Km/Hr	3100.0 mm/Kr	2942.9	3.456	Good	25.72072	N	85.99146	E	Normal
03/06/2023	11:14:51	55	100	2900	33.0 cm	12.0 Km/Hr	3300.0 mm/Kr	3124.7	3.178	Good	25.72084	N	85.990431	E	Normal
03/06/2023	11:15:27	55	100	3000	25.0 cm	19.9 Km/Hr	2500.0 mm/Kr	2397.5	3.298	Good	25.72063	N	85.989566	E	Normal
03/06/2023	11:15:57	55	100	3100	35.0 cm	11.7 Km/Hr	3500.0 mm/Kr	3306.5	3.394	Good	25.72045	N	85.98858	E	Normal
03/06/2023	11:16:28	55	100	3200	33.0 cm	11.5 Km/Hr	3300.0 mm/Kr	3124.7	3.178	Good	25.71994	N	85.987782	E	Normal

03/06/2023

03/06/2023

03/06/2023	11:17:03	55	100	3300	37.0 cm	10.4 Km/Hr	3700.0 mm/Kr	3488.3	3.609	Good	25.72025	N	85.986739	E	Normal
03/06/2023	11:17:34	55	100	3400	34.0 cm	11.5 Km/Hr	3400.0 mm/Kr	3215.6	3.286	Good	25.72059	N	85.985853	E	Normal
03/06/2023	11:18:04	55	100	3500	29.0 cm	11.8 Km/Hr	2900.0 mm/Kr	2761.1	3.741	Good	25.7209	N	85.985097	E	Normal
03/06/2023	11:18:27	55	100	3600	33.0 cm	15.2 Km/Hr	3300.0 mm/Kr	3124.7	3.178	Good	25.72105	N	85.984166	E	Normal
03/06/2023	11:18:50	55	100	3700	28.0 cm	16.2 Km/Hr	2800.0 mm/Kr	2670.2	3.631	Good	25.72183	N	85.983874	E	Normal
03/06/2023	11:19:10	55	100	3800	25.0 cm	17.5 Km/Hr	2500.0 mm/Kr	2397.5	3.298	Good	25.72278	N	85.983661	E	Normal
03/06/2023	11:19:31	55	100	3900	28.0 cm	17.2 Km/Hr	2800.0 mm/Kr	2670.2	3.631	Good	25.71204	N	85.992898	E	Normal
03/06/2023	11:20:03	55	100	4000	32.0 cm	16.5 Km/Hr	3200.0 mm/Kr	3033.8	3.069	Good	25.71111	N	85.992668	E	Normal
03/06/2023	11:20:53	55	100	4100	22.0 cm	13.1 Km/Hr	2200.0 mm/Kr	2124.8	2.961	Good	25.71026	N	85.992282	E	Normal
03/06/2023	11:21:11	55	100	4200	27.0 cm	10.5 Km/Hr	2700.0 mm/Kr	2579.3	3.52	Good	25.70855	N	85.991155	E	Normal
03/06/2023	11:21:59	55	100	4300	30.0 cm	11.6 Km/Hr	3000.0 mm/Kr	2852	3.851	Good	25.70928	N	85.991755	E	Normal
03/06/2023	11:22:06	55	100	4400	32.0 cm	16.5 Km/Hr	3200.0 mm/Kr	3033.8	3.069	Good	25.71007	N	85.992198	E	Normal
03/06/2023	11:22:49	55	100	4500	34.0 cm	11.9 Km/Hr	3400.0 mm/Kr	3215.6	3.286	Good	25.71095	N	85.992534	E	Normal
03/06/2023	11:23:00	55	100	4600	22.0 cm	16.5 Km/Hr	2200.0 mm/Kr	2124.8	2.961	Good	25.71178	N	85.992887	E	Normal
03/06/2023	11:23:40	55	100	4700	25.0 cm	15.1 Km/Hr	2500.0 mm/Kr	2397.5	3.298	Good	25.71265	N	85.992905	E	Normal
03/06/2023	11:24:09	55	100	4800	32.0 cm	10.0 Km/Hr	3200.0 mm/Kr	3033.8	3.069	Good	25.70923	N	85.985508	E	Normal
03/06/2023	11:24:59	55	100	4900	29.0 cm	10.0 Km/Hr	2900.0 mm/Kr	2761.1	3.741	Good	25.70977	N	85.985661	E	Normal
03/06/2023	11:25:02	55	100	5000	31.0 cm	10.0 Km/Hr	3100.0 mm/Kr	2942.9	3.556	Good	25.71461	N	85.987352	E	Normal

IRI Value 3304
Machine ID 19192

03/06/2023

03/06/2023