

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल- बक्सर

पत्रांक-.....007...../बक्सर

दिनांक-.....12/06/23.....

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल- बक्सर

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण (BRRDA)
बुद्ध मार्ग, पटना।

विषय- शीर्ष 3054 (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) योजना अंतर्गत राशि की अधियाचना के सम्बन्ध में।


महाशय,

उपर्युक्त विषयक प्रासंगिक पत्र के सम्बन्ध में कहना है कि योजना शीर्ष 3054 मरम्मत (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) अंतर्गत कराये गए कार्यों के भुगतान हेतु राशि की आवश्यकता है जिसे अधियाचना प्रपत्र के साथ सलग्न कर भेजा जा रहा है।


अतः श्रीमान से अनुरोध है कि सलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाए ताकि संवेदकों द्वारा कराये गए कार्य का भुगतान किया जा सके।

अनु०- यथोक्त

विश्वासभाजन


12.06.23

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर


12.06.23

FORM GFR 19-A

(SEE Government of India's Decision (I) below Rule-150)
Form of Utilisation Certificate upto the month of Dec 2018

MR (3054) New Maintenance Policy 2018**U - RWD (W), Div.- Buxar**

Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
Construction of Rural Roads under MR (3054) Maintenance	Lt. No.- 81, dt.-31.05.2023	8746.97990	Certified that out of Rs. 8746.97990 lacs received during the years in favour of Ex. Engineer, RWD (W), Div.- Buxar Bihar, a sum of Rs 8735.66720 lacs been utilized for the purpose of MR (3054) New Maintenance Policy 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs 11.31270 lacs remaining unutilized at the end of the period under

Total -

Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Supertending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Supertending Engineer.
- Construction materials have been tested
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

Physical Progress achieved :-

- Construction of Road works
- Construction of CD works

12/06/23
Executive Engineer

R.W.D. (w) Div. Buxar

Ak
12/06/23

Revision Format for Scheme Head- MR (3054) under Bihar Rural Road Maintenance Policy- 2018 (Initial Rectification and Surface Renewal)

Name of Works Division- RWD, Works Division- Buxar

Sl No	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Agreement No. & Date	Date Of Completion as per Agreement	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Amount Allotted (In Lakh)	Up-to-date expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
					Length (In KM)	Amount (In Lakh)	Initial Rectification With Surface Renewal (In Lakh)	5 Years Routine Maintenance (In Lakh)									
1	RM/BU/BU X/22/0009	Buxar Koehas Road to Sukarwalya Via Bechanpura	14191033877	Letter No 1486 & 8/09/2022	2.75	134.77	95.79892	34.58760	14/MBD/2022-23 & 23.01.2023	24/10/2023	1939	25 mm	5.00%	0.0000	0.0000	87.80810	
2	RM/BU/BU X/22/0011	Buxar Dhansoi Road To Parasi	14191033725	Letter No 1486 & 8/09/2022	3.202	175.50	108.10937	27.14730	02/MBD/2023-24 & 12.01.204.2023	19/10/2023	2308	25 mm	5.01%	0	0	108.08676	

- Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed
- Up-to-date Physical Progress has been uploaded in MIS

Executive Engineer
RWD (W), Div.- Buxar

12.06.23
AK
1210423


कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर


का0आ0स..... 008 बक्सर/ दिनांक 12/06/23

कार्यालय आदेश


प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत Buxar Dhansoi Road To Parasi पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत, 50% सहायक अभियंता एवं कनीय अभियंता के द्वारा शत प्रतिशत किया गया है।


कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रशाखा इटाही


सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रशाखा इटाही


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

File : G:\BHAGWAN DUBEY\2nd road\New folder\10061859.xls. Section No. : 80. Eqn : $Y = 0 \cdot X^2 + 0.816 \cdot X +$
 Name of Customer : Shree Bhagyan Dubey. Name of Work/ Road : Buxar Dhansoi Road To Parasi. Lab Job number



Handwritten signature
 10.06.23

Handwritten signature
 10.06.23

Handwritten signature
 12.06.23

Road Name:- Buxar Dhansoi Road To Parsai Contractor Name:-Shree Bhagwan Dubey

Date	Time	Section	No.	Length in km	Bumps in mm	Rate	Speed mm/km	OR	IRI CATEGORY	Latitude	ongitude	Event
10/6/23	18:25:2	80	0.1	180	10.1	1800	1717 G			25.43075	84.20353	Normal
10/6/23	18:26:0	80	0.1	110	10.1	1100	1146 G			25.43085	84.1936	Normal
10/6/23	18:26:13	80	0.1	110	10.1	1100	1146 G			25.43096	84.1835	Normal
10/6/23	18:27:23	80	0.1	120	10.1	1200	1228 G			25.43067	84.17592	Normal
10/6/23	18:27:23	80	0.1	120	10.1	1200	1228 G			25.42977	84.17525	Normal
10/6/23	18:28:0	80	0.1	100	10.1	1000	1064 G			25.42886	84.17473	Normal
10/6/23	18:28:0	80	0.1	130	20.2	1300	1309 G			25.42795	84.17473	Normal
10/6/23	18:28:34	80	0.1	170	20.2	1700	1636 G			25.42705	84.17322	Normal
10/6/23	18:29:9	80	0.1	180	10.1	1800	1717 G			25.4261	84.17137	Normal
10/6/23	18:29:44	80	0.1	300	10.1	3000	2696 G			25.42519	84.1702	Normal
10/6/23	18:30:20	80	0.1	260	10.1	2600	2370 G			25.42524	84.16093	Normal
10/6/23	18:30:55	80	0.1	220	10.1	2200	2044 G			25.42502	84.151	Normal
10/6/23	18:31:30	80	0.1	250	10.1	2500	2288 G			25.42502	84.14073	Normal
10/6/23	18:32:5	80	0.1	240	10.1	2400	2207 G			25.42504	84.13097	Normal
10/6/23	18:32:40	80	0.1	240	10.1	2400	2207 G			25.42506	84.12053	Normal
10/6/23	18:33:15	80	0.1	170	10.1	1700	1636 G			25.42534	84.11093	Normal
10/6/23	18:33:15	80	0.1	100	10.1	1000	1064 G			25.42561	84.1015	Normal
10/6/23	18:34:0	80	0.1	120	10.1	1200	1228 G			25.42582	84.9157	Normal
10/6/23	18:34:26	80	0.1	180	10.1	1800	1717 G			25.42587	84.8198	Normal
10/6/23	18:35:1	80	0.1	120	20.2	1200	1228 G			25.4259	84.7153	Normal
10/6/23	18:35:1	80	0.1	120	20.2	1200	1228 G			25.42647	84.675	Normal
10/6/23	18:35:1	80	0.1	140	20.2	1400	1391 G			25.42731	84.67	Normal
10/6/23	18:35:36	80	0.1	120	20.2	1200	1228 G			25.42752	84.569	Normal
10/6/23	18:36:12	80	0.1	110	10.1	1100	1146 G			25.4278	84.4713	Normal
10/6/23	18:37:0	80	0.1	150	10.1	1500	1472 G			25.4279	84.372	Normal
10/6/23	18:37:22	80	0.1	120	10.1	1200	1228 G			25.42815	84.276	Normal
10/6/23	18:37:22	80	0.1	130	10.1	1300	1309 G			25.42816	84.173	Normal
10/6/23	18:38:0	80	0.1	130	10.1	1300	1309 G			25.42846	84.958	Normal
10/6/23	18:45:1	80	0.1	250	10.1	2500	2288 G			25.42902	84.458	Normal
10/6/23	18:47:22	80	0.1	130	10.1	1300	1309 G			25.42982	84.1657	Normal
10/6/23	18:48:0	80	0.1	130	10.1	1300	1309 G			25.43046	84.15958	Normal
10/6/23	18:49:1	80	0.1	250	10.1	2500	2288 G			25.43068	84.15125	Normal

$$Y = 0 * X^2 + 0.816 * X + 249$$

$$X = 2500$$

$$Y = 2288$$

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001

IRI Value=2308

Machine ID=415

10.06.23

Prasad.

12.06.23