कार्यपालक अभियंता का कार्यालय, ग्रामीण कार्य विभाग, कार्य प्रमंडल बगहा-1

पत्रांक 1123

प्रेषक.

कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रमंडल, बगहा–1।

सेवा में.

अपर मुख्य कार्यपालक पदाधिकारी —सह—सचिव, नोडल पदाधिकारी, ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:— मुख्यमंत्री ग्राम सम्पर्क योजना (SC) अन्तर्गत चयनित पथों के लिए प्राप्त राशि का उपयोगिता प्रमाण-पत्र एवं अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि MMGSY(SC) योजना अन्तर्गत भुगतान हेतु अधियाचना विहित प्रपत्र में तैयार कर आवश्यक अग्रेतर कार्रवाई हेतु समर्पित किया जाता है। अधियाचना प्रपत्र के साथ उपयोगिता प्रमाण पत्र भी संलग्न है। साथ ही संवेदक का नाम प्राधिकार पत्र में जोड़ने की कृपा किया जाय।

अतः निर्वेदन है कि अंधियाचित राशि विमुक्त करने की कृपा की जाय ताकि कराये गये कार्य का भुगतान किया जा सके।

अनु0— 1. उपयोगिता प्रमाण-पत्र Form GFR 19A

2. अधियाचना पत्र

विश्वासभाजन

कार्यपालक जिसियंता, ग्रामीण कार्य विभाग, कार्य प्रमंडल, बगहा–1

*FORM GFR 19-A

(See Government of India's decision (I) below rule- 150) Form of Utilization certificate up to the month April - 2023

PIU:- E.E RWD(W)DIV-BAGAHA-1

SĽ.NO.	Name of Schemes	Sanction No.& Date with Amount (In Lacs)	Amount received (In Lacs)	Particulars
1	2	3	4	5
1	MMGSY(SC)	CFMS Bank	6398.69092 1423.64536	Certified that out of Rs. 7822.33628 Lacs of grants-in-aid sanctioned during the years 2021-22 to 2022-23 in favour of Executive Engineer R. W. D. Works Division, BAGAHA-1 a sum of Rs 7818.69293 Lacs
			·	has been utilized for the purpose of MMGSY(SC) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 3.64335 (CFMS)Lac remaining unutilized at the end of the period
		TOTAL	7822.33628	under report.

Certified that I have satisfied myself that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled, are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Divisional Accounts Officer RWD Works Division, Bagaha-1

Kinds of cheeks exercised:-

- i. Works has been supervised by Executive Engineer / Superintending Engineer.
- Periodic as inspection has been conducted by Executive Engineer / Superintending Engineer. ii.
- iii. Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer iv. / Executive Engineer.
- v. All other codal formalities have been observed.
- Physical Progress achieved:-
- i. Construction of Road Works.
- ii. Construction of CD Works.

R.W.D. Works Division, Bagaha-1

Executive Engil

S CamScanner

MMGSY (SC) Allotment Requisition Format Name of Division :- Rural Works Department, Works Division Bagaha-I. Rural Works Department

						PINI - HOISIAIG	I VOINS DOIL		200	Comme of Division :- Marat works Department, works Division Sugarnation				
S	2	Administr	rative Sanction	Agreement	Amount						9	MIS के अनुसार	किये गये 🍨	arkrantara anta
ž	rame of Road	Length	Amount of	Const. Work	Maint, Work	daint, Work Name of Contractor Agreement No.	Agreement No.	Agreement	Completion	कार्य का स्तर (E/W. GSB/Pcc	Completion	Completion अद्यतन मुगतान सम्पादित कार्य (लाख में)	सम्पादित गार्थ	(लाख मे)
~	2		THE PORTE	(in Lakn)	(in Lakh)							(लाख म)	का खेल साथ	
	2		2	4		5	9	7	8	6	10		12	13
_	Saurha To Bhvaneepur	2.200	202.290	183.59414	13.23183	Ujjain Engicon India Private	035BD/21_22	12 04 21	[1 04 22	Complete	10.04.22	10.04.22 167.86087 181.91229 14.05642	671618	14 05642

कराया गया कार्य संतोषग्रद है।

। अधियायना पूर्ण विशिष्टि के अनुरूप किये गये कार्यों के तिए किया जा रहा है जिसकी प्रविद्धि मापी पुस्त में कि जा चुकी है। इन कार्य में NQM, SQM की कोई प्रतिकुल टिप्पणी नहीं है। 2. मुगतान प्राधिकार प्राप्त होने पर 06 दिनों के अंदर विपत्रों का मुगतान कर उपयोगिता प्रमाण पत्र समर्पित कर दिया जाएगा। 3. कार्य स्थल पर नागरिक सूचना पट एवं स्थल प्रयोगशाला स्थापित किया गया है।

प्रपत्र QM-। एवं उपयोगिता प्रमाण पत्र (19A) संलग्न है।

पथ निर्माण के लिए पूर्ण लम्बाई उपलब्ध है जिसे संवेदक को Hand Over कर दिया गया है।

6. संवेदक को Mobilization एवं Machinery अग्रीम की आवश्यकता नहीं है तथा संवेदक द्वारा गाँग नहीं की गई है।

