

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, गया।

पत्रांक.....11.6.73/भया/दिनांक. 20-6-2023

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, गया।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी—
सह-सचिव, नोडल पदाधिकारी (3054)
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:—

शीर्ष 3054 (M/R) New Maintenance Policy 2018 योजनान्तर्गत निर्माण कार्य की राशि एवं संवेदक का नाम प्राधिकार पत्र में जोड़ने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि 3054 (M/R) New Maintenance Policy 2018 योजनान्तर्गत भुगतान हेतु अधियाचना विहित प्रपत्र में तैयार कर अग्रेतर कार्रवाई हेतु समर्पित किया जाता है तथा संवेदक का नाम प्राधिकार पत्र में जोड़ने की कृपा की जाय।

अतः निवेदन है कि अधियाचित राशि विमुक्त करने की कृपा की जाय ताकि कराये गए कार्य का भुगतान किया जा सके।

अनु०:— यथोक्त।

विश्वासभाजन

[Signature]
20/6/23

कार्यपालक अभियंता

ग्रामीण कार्य विभाग,

कार्य प्रमण्डल, गया।

20.6.23

20/6/23

Requisition Format for Scheme Head - MR(3054) under Bihar Road Maintenance Policy - 2018 (Initial Rectification and Surface Renewal)

Name of Works Division : Rural Works Department, Works Division, GAYA

Sl. No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval		Agreement Amount (in Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value Bitumen Content in Percentage	Previous Total Amount Alloted (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done. (in Lakh)	Remarks
					Length (in km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Years Routine Maintenance (in Lakh)										
1	RM/GA/GA Y/22/0002	Ametin Road - Nandina	10502102160	1565/03.05.2022	1.5	61.29	47.20125	16.52062	165/MR/M BD/2020-21, Date - 02/08/2022	01-May-23	-	3329.41	25 mm	5%	0.00000	0.00000	47.20125	Completed Enclosed RRI Result of Section No. 87
2	RM/GA/GAY/22/0001	Gaya Nawada Mazin Road to Kachharia Mahadain Tola Via Mithapur	10502104018	1565/03.05.2022	3.00	132.07	92.39760	34.40587	164/MR/M/B D/2022-23, Date- 02/08/2022	01-May-23	-	3262.36	25 mm	5%	0.00000	0.00000	92.39760	Completed Enclosed RRI Result of Section No. 65
Total =																	139.59885	

[Signature]
D.A.O
20/06/23
Rural Work Division-Gaya

[Signature]
20.06.2023
Executive Engineer
Rural Work Division-Gaya
30.6.23

FORM GFR -19 -A

(see Govt. of India's decision (i) below rule 150)

Form of Utilisation Certificate upto 20.06.2023

New Maintenance policy 2018 (MR3054) Maintenance

PIU:- R.W.D. Works, Division, ~~Patna~~ Gaya

Sl. No	Name of Scheme	Sanction No.& Date with amount (in Rs. Lakh)	Amount Received (in Rs. Lakh)	Particulars
1	2	3	4	5
1	Construction of Road Under New Maintenance policy 2018 (MR3054) Maintenance Scheme	8035.34520	8035.34520	Certified that out of Rs. 8035.34520 Lakh received till date in favour of Ex-Engineer, R.W.D. Works Division, Mahnar a sum of Rs. 7895.95706 has been utilized for the purpose of New Maintenance policy 2018 (MR3054) Maintenance Scheme as given in the margin for which it was sanctioned and that the balance of Rs. 139.38814 Lakh remaining unutilized at the end of the period under the time of completion.
		8035.34520	8035.34520	

- 2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the propose for which it was sanctioned.

Kind of Checks Exercised :-

- Workers have been supervised by Executive Engineer/ Superintending Engineer
- Periodical inspection has been conducted by Executive Engineer/Superintending Engineer
- Construction materials have been tested.
- Measurments have been recorded in the MB's and test check conducted by the Assistant Engineer/Executive Engineer.
- All other codal formalities have overserved

3 Physical Progress Achieved.


- Construction of Road Works
- Construction of CD Works.


20/6/23
Divisional Accounts Officer
Rural works Department
Works Division, Gaya


20/06/2023
Executive Engineer
Rural works Department
Works Division, Gaya
20.6.23

File : F:\19060743.Xls. Section No. : 65. Eqn : $Y = 0 \cdot X^2 + 1.136 \cdot X + 132.5$

Name of Customer : Sanjay Kumar. Name of Work/ Road : Gaya Nawada Main Road to Kaghariya Mahadali Tola



[Signature]
19/06/23
JE

[Signature]
19/06/23
JE

[Signature]
22/06/23
Executive Engineer
R.W.D. (W) Div., Gaya

Name of Road:- Gaya Nawada Main Road to Kaghariya Mahadalt Tola Via Mirkhapur Contractor Name:- Sanjay Kumar

Date	Time	Section	Length	Bumps	Speed	OR	IRI	ATEGORY	Latitude	Longitude	Event
19/6/23	6:50:0	65	0.1	310	0	3100	3654	G	24.786705	85.124965	Normal
19/6/23	6:50:6	65	0.1	300	20.2	3000	3540	G	24.785788	85.124998	Normal
19/6/23	6:50:6	65	0.1	300	40.4	3000	3540	G	24.78497	85.125337	Normal
19/6/23	6:50:6	65	0.1	260	40.4	2600	3086	G	24.78413	85.125572	Normal
19/6/23	6:50:41	65	0.1	250	30.3	2500	2972	G	24.78325	85.125823	Normal
19/6/23	6:51:0	65	0.1	260	40.4	2600	3086	G	24.782612	85.12638	Normal
19/6/23	6:51:17	65	0.1	280	40.4	2800	3313	G	24.782552	85.127272	Normal
19/6/23	6:51:17	65	0.1	250	40.4	2500	2972	G	24.782475	85.128315	Normal
19/6/23	6:51:52	65	0.1	300	20.2	3000	3540	G	24.782255	85.129292	Speed Breaker
19/6/23	6:52:0	65	0.1	300	20.2	3000	3540	G	24.781955	85.130168	Speed Breaker
19/6/23	6:52:26	65	0.1	220	40.4	2200	2631	G	24.78156	85.130975	Normal
19/6/23	6:53:1	65	0.1	320	30.3	3200	3767	G	24.780992	85.131447	Speed Breaker
19/6/23	6:54:0	65	0.1	320	30.3	3200	3767	G	24.78098	85.132423	Speed Breaker
19/6/23	6:54:12	65	0.1	310	30.3	3100	3654	G	24.781072	85.13	Normal
19/6/23	6:54:12	65	0.1	330	20.2	3300	3881	G	24.781035	85.134308	Normal
19/6/23	6:54:12	65	0.1	310	30.3	3100	3654	G	24.781082	85.135235	Normal
19/6/23	6:54:47	65	0.1	280	40.4	2800	3313	G	24.781028	85.136295	Curve
19/6/23	6:55:0	65	0.1	330	20.2	3300	3881	G	24.780527	85.13677	Normal
19/6/23	6:55:0	65	0.1	310	30.3	3100	3654	G	24.779635	85.136598	Normal
19/6/23	6:55:23	65	0.1	320	30.3	3200	3767	G	24.778758	85.136363	Normal
19/6/23	6:55:23	65	0.1	250	30.3	2500	2972	G	24.777862	85.136245	Curve
19/6/23	6:56:0	65	0.1	280	40.4	2800	3313	G	24.77688	85.136447	Normal
19/6/23	6:56:18	65	0.1	250	40.4	2500	2972	G	24.775982	35.136278	Normal
19/6/23	6:56:18	65	0.1	210	40.4	2100	2518	G	24.775222	85.135842	Culvert
19/6/23	6:56:18	65	0.1	260	40.4	2600	3086	G	24.774395	85.135353	Normal
19/6/23	6:56:53	65	0.1	220	40.4	2200	2631	G	24.773505	85.135202	Normal
19/6/23	6:57:0	65	0.1	230	40.4	2300	2745	G	24.772655	85.13502	Normal
19/6/23	6:57:28	65	0.1	270	40.4	2700	3199	G	24.771728	85.13503	Normal
19/6/23	6:58:4	65	0.1	260	40.4	2600	3086	G	24.770877	85.13512	Curve
19/6/23	6:58:50	65	0.085	150	10.1	1765	2137	G	24.771502	85.135	Normal
Average						3262.36					

19/6/23
19/6/23

19/6/23
19/6/23

19/6/23
19/6/23

19/6/23
19/6/23