

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, टिकारी।

पत्रांक:- 11923/नु०

/टिकारी, दिनांक:- 22/6/2023

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, टिकारी।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण, पटना।

विषय— 3054/MR, New Maintenance Policy-2018 अंतर्गत आवंटित राशि का उपयोगिता प्रमाण पत्र तथा आवंटन अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि इस प्रमण्डल अंतर्गत 3054/MR, New Maintenance Policy-2018 अंतर्गत const. of road from chainpur more to bikram bigha पथ में चल रहे कार्यों के भुगतान हेतु उपयोगिता प्रमाण पत्र विहित प्रपत्र में संलग्न करते हुए आग्रह है कि माँग पत्र के अनुसार योजना में रुपये 64,99,300.00 (चौसठ लाख निन्यानबे हजार तीन सौ रुपये) मात्र का आवंटन उपलब्ध कराने की कृपा की जाय।

अनु०— यथोक्त।

विश्वासभाजन

 22/6/23

कार्यपालक अभियंता
ग्रामीण कार्य विभाग, कार्य प्रमंडल, टिकारी।

 21/6/23

**OFFICE OF THE EXECUTIVE ENGINEER,
RURAL WORKS DEPARTMENT, WORKS DIVISION TEKARI.**

Requisition Format for Scheme Head:- MR (3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)																			
Name of Works Division:- Tekari																			
Sl. No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)			Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allotted Amount (in Lakh)	Up to date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in Km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)											
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
1	RM/GA/TTI K/22/0010	const. of road from chainpur more to bikram bigha	15221039800	Lt 998 Dt. 25.02.2022	1.65	81.57700	64.99300	16.52407	08 MBD/MR/2022-23 & 26.09.2022	25.06.2023	-	2919	25 mm	5.10%	0	0	64.99300	RI का ग्राम सलाना।	
			Total		1.400	37.01500	28.60200	13.02702									64.99300		
																			Amount in Word:-Sixty Four Lakh Ninety Nine Thousand Three Hundred Only.

Amount in Word:-Sixty Four Lakh Ninety Nine Thousand Three Hundred Only.

[Signature]
21/6/23

Sr. D.A.O.,
RWD, Works Division, Tekari

[Signature]
21/6/23

Executive Engineer
RWD, Works Division, Tekari
21/6/23

FORM GFR 19 - A

(See Government of India's Decision (1) below Rule - 150)

Form of utilisation Certificate as on :- **22.06.2023**

RURAL ROAD MAINTENANCE POLICY-2018

PIU :- R.W.D. Tekari.

Sl. no.	Name of Scheme	Sanction No.& Date with Amount (in Lacs)	Amount Received in Lacs	Decrease (in Lacs)	Particulars
1	2	3	4	5	6
	RURAL ROAD MAINTENANCE POLICY-2018	As on 10 Feb -2023	4181.59446	0.00000	Certified that out of Rs.:- 6081.05700 Lacs received in the Financial Years 2023-24 In favour of Executive Engineer RWD Works Division Tekari, Gaya Bihar out of which a sum of Rs.:- 0.00 Lacs has been Surrender and 5386.11158 Lacs has been Utilized for the purpose of RURAL ROAD MAINTENANCE POLICY-2018 as given in the margin for which it was sanctioned and that the balance of Rs.:- 694.94542 Lacs remainig unutilized at the end of the said period.
		Lt. No. 21 Dt. 20.02.2023	87.13840		
		Lt. No. 39 Dt. 17.03.2023	163.80773		
		Lt. No. 42 Dt. 20.03.2023	144.52085		
		Lt. No. 67 Dt. 27.04.2023	78.26116		
		Lt. No. 72 Dt. 10.05.2023	497.42348		
		Lt. No. 78 Dt. 24.05.2023	432.88875		
		Lt. No. 81 Dt. 31.05.2023	41.9025		
		Lt. No. 89 Dt. 21.05.2023	453.51967		
		Total	6081.05700	0.00000	

Memo No. :-

Dated :-

- 2 Certified that I have satisfied my self that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of checks exercised :-

- (i) Works have been supervised by Executive Engineer/Superintending Engineer
- (ii) Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- (iii) Construction material have been tested.
- (iv) Measurment have been recorded in the MBs and test check conducred by the Assistant.
- (v) All other codal formalities hav been observed.

- 3 Physical progress acchieved

- (i) Construction of Road works.
- (ii) Construction of cd works.

**EXECUTIVE ENGINEER
RURAL WORK DEPARTMENT
WORKS DIVISION TEKARI**


सहायक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य अवर प्रमंडल, बेलागंज।

पत्रांक:- 136

दिनांक:- 21/06/2023

जाँच प्रतिवेदन

प्रखण्ड का नाम	योजना का नाम	पथ की लम्बाई (कि०मी०)	S.D.B.C परत की मोटाई	बिटुमिन Content की मात्र	BUMP INTEGRATOR का Reading	अभियुक्ति
Belaganj	Const. of road from chainpur more to bikram bigha	1.650	25MM	5.10 %	Reading Attached	Satisfactory


सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल, बेलागंज

Name of work : const. of road from chainpur more to bikram bigha
Name of customer : Sanjay Kumar

(R)Rural Road			
Good		Poor	
< 4000		> 5000	
Average		4001 - 5000	

Date	Time	Test No	Distance (m)	Total Distance(m)	BUMP(cm)	Speed(Km/Hr)	UI(mm/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
21-06-23	16:37:37	120	100	100	35.0 cm	15.0 Km/Hr	3500.0	3592	4.73	Good	24.952683	N	84.972674	E	Normal
21-06-23	16:38:03	120	100	200	26.0 cm	16.5 Km/Hr	2600.0	2754	3.73	Good	24.953501	N	84.971908	E	Normal
21-06-23	16:38:24	120	100	300	25.0 cm	17.1 Km/Hr	2500.0	2661	3.62	Good	24.954159	N	84.97127	E	Normal
21-06-23	16:38:44	120	100	400	31.0 cm	18.5 Km/Hr	3100.0	3220	4.29	Good	24.954891	N	84.970773	E	Normal
21-06-23	16:39:07	120	100	500	30.0 cm	15.6 Km/Hr	3000.0	3127	4.18	Good	24.954861	N	84.969858	E	Normal
21-06-23	16:39:23	120	100	600	30.0 cm	21.3 Km/Hr	3000.0	3127	4.18	Good	24.95476	N	84.968902	E	Normal
21-06-23	16:39:39	120	100	700	29.0 cm	22.5 Km/Hr	2900.0	3034	4.07	Good	24.95475	N	84.967807	E	Normal
21-06-23	16:39:54	120	100	800	35.0 cm	24.4 Km/Hr	3500.0	3592	4.73	Good	24.954315	N	84.966979	E	Normal
21-06-23	16:40:08	120	100	900	22.0 cm	26.4 Km/Hr	2200.0	2382	3.28	Good	24.954271	N	84.966031	E	Normal
21-06-23	16:40:21	120	100	1000	19.0 cm	27.2 Km/Hr	1900.0	2102	2.93	Good	24.954396	N	84.965092	E	Normal
21-06-23	16:40:36	120	100	1100	25.0 cm	23.9 Km/Hr	2500.0	2661	3.62	Good	24.954602	N	84.96407	E	Normal
21-06-23	16:40:59	120	100	1200	26.0 cm	16.2 Km/Hr	2600.0	2754	3.73	Good	24.954763	N	84.963193	E	Normal
21-06-23	16:41:14	120	100	1300	27.0 cm	22.6 Km/Hr	2700.0	2847	3.85	Good	24.954791	N	84.962215	E	Normal
21-06-23	16:41:29	120	100	1400	24.0 cm	24.9 Km/Hr	2400.0	2568	3.51	Good	24.954951	N	84.961255	E	Normal
21-06-23	16:41:45	120	100	1500	29.0 cm	22.7 Km/Hr	2900.0	3034	4.07	Good	24.955054	N	84.960281	E	Normal
21-06-23	16:41:59	120	100	1600	32.0 cm	24.6 Km/Hr	3200.0	3313	4.4	Good	24.955043	N	84.959294	E	Normal
21-06-23	16:42:14	120	100	1700	27.0 cm	24.1 Km/Hr	2700.0	2847	3.85	Good	24.954903	N	84.958378	E	Normal
Total			1700	1700			Average	2919							


21/06/23
JE

21/06/23
AE

21/06/23
Executive Engineer
RWD, Works Division
Tekari, Gaya



Name of Customer: Sanjay Kumar , Machine no: 19211 , Road: const. of road from chainpur more to bikram bigha , Date: 22-06-23 , Section No: 120 , Equation: $Y=0.931X+333.6$



21/6/23
JE

21/06/23
AE

21/6/23
Executive Engineer
RWD, Works Division
Tekari, Gaya

