

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल- बक्सर

पत्रांक-...067.../बक्सर

दिनांक-...27/06/23...

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल- बक्सर

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण (BRRDA)
बुद्ध मार्ग, पटना।

विषय- शीर्ष 3054 (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) योजना अंतर्गत राशि की अधियाचना के सम्बन्ध में।

महाशय,

उपर्युक्त विषय के सम्बन्ध में कहना है कि योजना शीर्ष 3054 मरम्मत (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) अंतर्गत कराये गए कार्यों के भुगतान हेतु राशि की आवश्यकता है जिसे अधियाचना प्रपत्र के साथ सलंग्न कर भेजा जा रहा है।

अतः श्रीमान से अनुरोध है कि सलंग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाए ताकि संवेदकों द्वारा कराये गए कार्य का भुगतान किया जा सके।

अनु०- यथोक्त

विश्वासभाजन


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

27/06/23

FORM GFR 19-A
(SEE Government of India's Decision (I) below Rule-150)
Form of Utilisation Certificate upto the month of Dec 2018

MR (3054) New Maintenance Policy 2018

PIU - RWD (W), Div.- Buxar

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural Roads under MR (3054) Maintenance	Lt. No.- 89, dt.-21.06.2023	9059.73233	Certified that out of Rs. 9059.73233 lacs received during the years in favour of Ex. Engineer, RWD (W), Div.- Buxar Bihar, a sum of Rs 9048.41963 lacs been utilized for the purpose of MR (3054) New Maintenance Policy 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs 11.31270 lacs remaining unutilized at the end of the period under
Total -				

- 2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Supertending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Supertending Engineer.
- Construction materials have been tested
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

3 Physical Progress achieved :-

- Construction of Road works
- Construction of CD works

23-06-23
Executive Engineer

R.W.D. (w) Div. Buxar

AK
27/06/23

quisition Format for Scheme Head- MR (3054) under Bihar Rural Road Maintenance Policy- 2018 (Initial Rectification and Surface Renewal)

Sl No	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Agreement No. & Date	Date Of Completion as per Agreement	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (In Lakh)	up-to-date expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
					Length (In KM)	Amount (In Lakh)	Initial Rectification With Surface Renewal (In Lakh)	5 Years Routine Maintenance (In Lakh)									
1	RM/BU/BU X/22/0015	T05 - NAGPURA	10401902094	Letter No 1486 & 8/09/2022	2.460	140.339	80.16858	22.35705	03/MBD/2023-24 & 12.04.2023	12.01.2024	2076	25MM	5.00%	0	0	80.10502	
2	RM/BU/BU X/22/0015	Simari - Balihar High School	NEA220002103	Letter No 1486 & 8/09/2022	2.800	134.365	76.42548	19.8898	03/MBD/2023-24 & 12.04.2023	12.01.2024	2046	25MM	5.01%	0	0	76.41873	
3	RM/BU/BU X/22/0009	Buxar Kochas Road to Sukarwalya Via Bechhanpurva	14191032877	Letter No 1486 & 8/09/2022	2.750	134.77	95.79892	34.5876	14/MBD/2022-23&25.01.2023	24.10.2024	1939	25MM	5.00%	87.8081	87.8081	7.54030	

- Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed
- Up-to-date Physical Progress has been uploaded in MIS

Executive Engineer
RWD (W), Div.- Buxar

27.06.23


27/06/23


कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर

का0आ0स.....968..... बक्सर/ दिनांक.....27/06/23


कार्यालय आदेश

प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत Simri-Balihar High School पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत एवं कनीय अभियंता के द्वारा शत प्रतिशत किया गया है।


कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रशाखा सिमरी


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

File : G:\BISHNU SANKAR OJHA\New folder (2)\26061905 (1).Xls. Section No. : 88. Eqn : $Y = 0 \cdot X^2 + 0.816 \cdot X +$
 Name of Customer : Bishnu Shankar Ojha. Name of Work/ Road : Simri Balihar High School. Lab Job number :



Handwritten signature and date: 23/06/23

Handwritten signature and date: 23/06/23

Road Name:- Simri-Balihar High School Contractor Name:-Bishnu Shankar Ojha

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR	IRI CATEGORY	Latitude	ongitude	Event
26/6/23	17:39:27	88	0.1	300	0	3000	2696 G	25.62536	84.88855	Normal
26/6/23	17:40:2	88	0.1	200	10.1	2000	1880 G	25.62579	84.89763	Normal
26/6/23	17:40:2	88	0.1	250	10.1	2500	2288 G	25.62599	84.90757	Normal
26/6/23	17:41:0	88	0.1	240	10.1	2400	2207 G	25.6263	84.91648	Speed Breaker
26/6/23	17:41:12	88	0.1	210	10.1	2100	1962 G	25.62658	84.92558	Speed Brea (R) RURAL ROAD
26/6/23	17:41:48	88	0.1	270	10.1	2700	2452 G	25.6271	84.934	Speed Brea Good
26/6/23	17:42:0	88	0.1	230	10.1	2300	2125 G	25.62766	84.9414	Normal
26/6/23	17:42:57	88	0.1	240	10.1	2400	2207 G	25.62827	84.94848	Normal
26/6/23	17:43:33	88	0.1	270	10.1	2700	2452 G	25.62858	84.9579	Speed Breaker
26/6/23	17:53:0	88	0.1	260	10.1	2600	2370 G	25.62879	84.968	Normal
26/6/23	17:54:43	88	0.1	210	10.1	2100	1962 G	25.62922	84.97608	Normal
26/6/23	17:55:18	88	0.1	210	10.1	2100	1962 G	25.63013	84.9776	Normal
26/6/23	17:56:0	88	0.1	290	10.1	2900	2615 G	25.63102	84.97862	Normal
26/6/23	17:57:4	88	0.1	150	10.1	1500	1472 G	25.63185	84.98248	Normal
26/6/23	17:57:4	88	0.1	170	10.1	1700	1636 G	25.63248	84.98905	Normal
26/6/23	17:57:39	88	0.1	150	20.2	1500	1472 G	25.6334	84.98988	Normal
26/6/23	17:58:0	88	0.1	240	20.2	2400	2207 G	25.6343	84.99123	Normal
26/6/23	17:58:15	88	0.1	130	20.2	1300	1309 G	25.63518	84.99493	Normal
26/6/23	17:58:15	88	0.1	180	20.2	1800	1717 G	25.63594	84.10003	Normal
26/6/23	17:58:50	88	0.1	210	20.2	2100	1962 G	25.63674	84.10056	Normal
26/6/23	17:59:0	88	0.1	190	20.2	1900	1799 G	25.63759	84.10086	Normal
26/6/23	17:59:25	88	0.1	170	20.2	1700	1636 G	25.63848	84.10079	Normal
26/6/23	18:0:36	88	0.1	270	10.1	2700	2452 G	25.63883	84.10017	Normal
26/6/23	18:39:0	88	0.1	290	10.1	2900	2615 G	25.64031	84.99672	Speed Breaker
26/6/23	18:40:0	88	0.1	250	10.1	2500	2288 G	25.64115	84.99225	Speed Breaker
26/6/23	18:41:1	88	0.1	200	10.1	2000	1880 G	25.64199	84.98795	Normal
26/6/23	18:41:1	88	0.1	180	10.1	1800	1717 G	25.64283	84.98265	Normal
26/6/23	18:42:0	88	0.1	210	10.1	2100	1962 G	25.64378	84.9777	Normal

$$Y = 0 * X^2 + 0.816 * X + 249$$

$$X = 2100$$

$$Y = 1962$$

Average Poor

4001-5000 >5001

Machine ID=415

IRI Value=2046

Machine ID=415

23.06.23

23.06.23