

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, झंझारपुर ।

पत्रांक 12953450 / दिनांक 26/06/2023

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, झंझारपुर ।

सेवा में,

अपर मुख्य कार्यपालक महाधिकारी
--सह-- सचिव
ग्रामीण कार्य विभाग,
पटना ।

विषय :

शीर्ष 3054MR योजना अंतर्गत बिहार ग्रामीण पथ अनुसंधान नीति - 2018 के तहत स्वीकृत
कार्यों के आवंटन की मांग के संबंध में।

प्रांत :

मध्यम पत्रांक मु०आ०-4 (मु०)-3054-C4-251/2018 - 113 अनु पटना दिनांक
10.01.2020

महोदय,

उपरोक्त विषयक प्रारंभिक पत्र के आलोक में शीर्ष 3054 MR योजना अंतर्गत बिहार ग्रामीण पथ
अनुसंधान नीति - 2018 के तहत स्वीकृत कार्यों में कृत कार्य के भुगतान हेतु विहित प्रपत्र में अधिसूचना
तैयार कर आवश्यक कार्रवाई हेतु संनर्गित की जा रही है।

अतः अनुरोध है कि आवंटन उपलब्ध कराने की कृपा की जाय।

अनु. - विहित प्रपत्र में अधिसूचना प्रपत्र

समय इन्स्टिट्यूट नशीन से लिया गया प्रतिवेदन

दिनांक 26/06/23
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग, कार्य प्रमंडल,
झंझारपुर

Form GFR 19- A
(See Government of India's Decision (I) below Rule - 150)
Form of Utilization Certificate upto the month June
New Maintenance Policy 2018

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in lacs)	Amount Received (in lacs)	Particulars
1	1	89 enc/ Dt.21.06.2023	2352.60553	Certified that Rs:- 2352.60553 Lac received Till the date in favour of Executive Engineer, RWD Work Division Jhanjharpur. A sum of Rs.2130.61989 Lac has been utilized for the purpose of NEW_MR Scheme as given in the margin for which it was sanctioned and that the balance of Rs 221.98564 Lacs remaining .
		Total :	2352.60553	

Certified and verified myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kinds of Checks exercised :-

- i Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii Construction material have been tested.
- iv Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- v All other codal formalities have been observed.

Physical Progress achieved :-

- i Construction of Road works.
- ii Construction of CD works


D.A.O
RWD Works Division
Jhanjharpur


Executive Engineer
RWD works Division
Jhanjharpur
Recd 26/6/23

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)
Name of Division :Jhanjharpur

Sl No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Length (In Km)	Amount (in Lac)	Initial Rectification with Surface Renewal (in lac)	5 years Routine Maintenance (in lac)	Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (In lac)	Remarks
1	RN/MIA/JHA/22/0012	Bhagwatipur rudrapur barsaam gram in path.	31909804005	1590/30.0 3.2022	2.500	189.04000	168.86276	23.16197	19SRD/22-23DC-01-11-2022	31-10-2023	-	3388.00	25mm	5.0%	0.00000	0.00000	157.30278	Surface Completed


D.A.O.

RWD Works Division
Jhanjharpur


Executive Engineer
RWD Works Division
Jhanjharpur

Name of work : Bhagwatipur Rudrapur Barsaam Gramin Path

Name of customer : Arbind Kumar Sharma

(R)Rural Road

Good	Average	Poor
< 4000	4001 - 5000	> 5000

Date	Time	Test No	Distance(m)	Total Distance(m)	BUMP(cm)	Speed(Km/Hr)	UI(mm/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
20/06/23	14:59:52	70	100	100	23.0 cm	8.5 Km/Hr	2300.0 mm/Km	2516	3.44	Good	26.3461854	N	86.3274896	E	Normal
20/06/23	15:00:15	70	100	200	21.0 cm	15.6 Km/Hr	2100.0 mm/Km	2311	3.19	Good	26.3462801	N	86.3255192	E	Normal
20/06/23	15:00:59	70	100	300	22.0 cm	10.2 Km/Hr	2200.0 mm/Km	2413	3.32	Good	26.3464452	N	86.3250427	E	Normal
20/06/23	15:01:21	70	100	400	23.0 cm	11.4 Km/Hr	2300.0 mm/Km	2516	3.44	Good	26.3465125	N	86.3244470	E	Normal
20/06/23	15:01:59	70	100	500	24.0 cm	13.7 Km/Hr	2400.0 mm/Km	2618	3.57	Good	26.3464192	N	86.3235280	E	Normal
20/06/23	15:03:09	70	100	600	22.0 cm	8.1 Km/Hr	2200.0 mm/Km	2413	3.32	Good	26.3466507	N	86.3224631	E	Normal
20/06/23	15:03:43	70	100	700	21.0 cm	12.6 Km/Hr	2100.0 mm/Km	2311	3.19	Good	26.3468552	N	86.3215282	E	Normal
20/06/23	15:04:17	70	100	800	24.0 cm	13.6 Km/Hr	2400.0 mm/Km	2618	3.57	Good	26.3475089	N	86.3206811	E	Normal
20/06/23	15:04:43	70	100	900	24.0 cm	11.4 Km/Hr	2400.0 mm/Km	2618	3.57	Good	26.3481740	N	86.3199622	E	Normal
20/06/23	15:05:04	70	100	1000	23.0 cm	11.8 Km/Hr	2300.0 mm/Km	2516	3.44	Good	26.3486552	N	86.3191148	E	Normal
20/06/23	15:05:28	70	100	1100	25.0 cm	15.5 Km/Hr	2500.0 mm/Km	2720	3.69	Good	26.3489382	N	86.3182428	E	Normal
20/06/23	15:06:04	70	100	1200	22.0 cm	11.7 Km/Hr	2200.0 mm/Km	2413	3.32	Good	26.3492186	N	86.3121805	E	Normal
20/06/23	15:06:33	70	100	1300	24.0 cm	14.8 Km/Hr	2400.0 mm/Km	2618	3.57	Good	26.3497750	N	86.3157216	E	Normal
20/06/23	15:07:11	70	100	1400	21.0 cm	13.6 Km/Hr	2100.0 mm/Km	2311	3.19	Good	26.3501621	N	86.3141749	E	Normal
20/06/23	15:07:34	70	100	1500	23.0 cm	14.8 Km/Hr	2300.0 mm/Km	2516	3.44	Good	26.3501725	N	86.3141857	E	Normal
20/06/23	15:08:11	70	100	1600	22.0 cm	10.4 Km/Hr	2200.0 mm/Km	2413	3.32	Good	26.3507913	N	86.3123071	E	Normal
20/06/23	15:08:34	70	100	1700	21.0 cm	15.9 Km/Hr	2100.0 mm/Km	2311	3.19	Good	26.3512801	N	86.3104247	E	Normal
20/06/23	15:09:11	70	100	1800	23.0 cm	10.6 Km/Hr	2300.0 mm/Km	2516	3.44	Good	26.3517825	N	86.3096585	E	Normal
20/06/23	15:09:33	70	100	1900	22.0 cm	12.5 Km/Hr	2200.0 mm/Km	2413	3.32	Good	26.3527138	N	86.3094788	E	Normal
20/06/23	15:09:55	70	100	2000	21.0 cm	13.4 Km/Hr	2100.0 mm/Km	2311	3.19	Good	26.3535531	N	86.3093275	E	Normal
20/06/23	15:10:32	70	100	2100	25.0 cm	11.7 Km/Hr	2500.0 mm/Km	2720	3.69	Good	26.3502801	N	86.3122206	E	Normal

Handwritten signature

Name of work : Bhagwatipur Rudrapur Barsaam Gramin Path

Name of customer : Arbind Kumar Sharma

(R)Rural Road

Good Average Poor

< 4000 4001 - 5000 > 5000

Date	15 11 01	70	100	2300	24.0 cm	15.6 Km/hr	2400.0 mm/Km	2618	3.57	Good	26 3501062	N	86 3142747	E	Normal
20/06/23	15 11 44	70	100	2300	21.0 cm	18.7 Km/hr	2100.0 mm/Km	2311	3.19	Good	26 3490551	N	86 3174331	E	Normal
23/06/23	15 12 05	70	100	2400	23.0 cm	17.4 Km/hr	2300.0 mm/Km	2516	3.44	Good	26 3465570	N	86 3218673	E	Normal
20/06/23	15 12 44	70	100	2500	21.0 cm	18.7 Km/hr	2100.0 mm/Km	2311	3.19	Good	26 3456709	N	86 3217062	E	Normal
20/06/23	15 13 05	70	100	2600	23.0 cm	14.6 Km/hr	2300.0 mm/Km	2516	3.44	Good	26 3450660	N	86 3209354	E	Normal
20/06/23	15 13 54	70	100	2700	21.0 cm	18.5 Km/hr	2100.0 mm/Km	2311	3.19	Good	26 3437091	N	86 3185553	E	Normal
20/06/23	15 14 12	70	100	2800	23.0 cm	12.3 Km/hr	2300.0 mm/Km	2516	3.44	Good	26 3433064	N	86 3176744	E	Normal


22/6/23
A I T M

20/6/23
20/6/23

20/06/2023
AE


22/6/23
BR

Name of Customer: Arbind Kumar Sharma , Machine no: 19198 , Road: Bhagwatiapur Rudrapur Baranasi Gramin Path , Date: 20-06-23 , Section No: 70 , Equation: $Y=1.0216X+165.9$



Recd
 25/11/23
 AITM

Name of Customer: Arbind Kumar Sharma , Machine no: 19193 , Road: Bhagwatipur Rudrapur Barasahi Gramin Path , Date: 20-06-23 , Section No: 70 , Equation: $Y=1.0216X+165.9$



[Signature]
20/6/23

[Signature]
20/06/2023
AT

[Signature]
20/06/23

AITM