

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, भभुआ ।

Email ID:- bhabua.rwd@gmail.com

Mob:- 8986915314

पत्रांक.....10813130

भभुआ /दिनांक.....26/06/2023

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, भभुआ ।

सेवा में,

नोडल पदाधिकारी (MR 3054)
ग्रामीण कार्य विभाग
पटना, बिहार

विषय :- नई अनुरक्षण नीति-2018MR (3054)योजना के अंतर्गत पथ में कराये गये
त्रैमासिक अनुरक्षण कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुरक्षण नीति-2018 MR
(3054)योजना के अंतर्गत पथ में कराये गये त्रैमासिक अनुरक्षण कार्य के लिए संवेदक को
भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की
जाती है।

अनु :- यथोक्त।

विश्वासभाजन

26/06/23
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, भभुआ ।
26/6/23

Requisition format for Scheme Head- 5 Year Maintenance of MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal

Name of Division-Bhabhua															
Sl No.	Package No.	Name of Road	Project ID as per MIS	Administrative		Administrative		Agreement Amount (in Lacs)			Agreement No. and Date	Date of Completion as per agreement	Actual Date of Completion	Requisitioned Amount of 5 year Maintenance (in Lacs)	Remarks
				Sanction	Letter No.	Approval(AA)	Amount (in Lacs)	Initial Rectification with Surface Renewal	5 Years Routine Maintenance						
1	2	3	4	5	6	7	8	9	10	11	12	13	14		
1	RM/K.A/BH/A/19/0004	Ramgarh - Bhakhar Devi	10301402024	1832	24.06.2019	10.200	295.325	194.685	75.24199	MBRD-16/2019-20	23-Jun-20	27-Jun-20	18.81050	1-5 Quarter	
2	RM/K.A/BH/A/19/0004	Tawai - Hattia Durgawati Road	10301402031	1832	24.06.2019	2.860	106.704	72.224	21.20045	MBRD-16/2019-20	23-Jun-20	27-Jun-20	5.30010	1-5 Quarter	
3	RM/K.A/BH/A/19/0004	From Sandharveer primary school to Sonno village	10301501023	1832	24.06.2019	1.000	32.3354	20.438	8.12449	MBRD-16/2019-20	23-Jun-20	27-Jun-20	2.03110	1-5 Quarter	
4	RM/K.A/BH/A/19/0005	Dokhri - Bahuara	10301402010	1832	24.06.2019	2.200	78.6107	52.804	14.15396	MBRD-20/2019-20	23-Jun-20	22-Jun-20	3.53850	1-5 Quarter	
5	RM/K.A/BH/A/19/0005	Majhui - Lohra	10301402020	1832	24.06.2019	2.030	75.225	50.319	17.83064	MBRD-20/2019-20	23-Jun-20	22-Jun-20	4.45765	1-5 Quarter	
6	RM/K.A/BH/A/19/0005	Salampur - Chapaur	10301402025	1832	24.06.2019	9.277	252.0633	192.615	67.3101	MBRD-20/2019-20	23-Jun-20	22-Jun-20	16.82750	1-5 Quarter	
7	RM/K.A/BH/A/19/0013	Dihra - Lakhanpur	10301402009	3354	1.08.2019	3.430	112.1107	80.461	21.66495	MBRD-28/2019-20	05-Nov-20	02-Feb-21	3.24975	1-3 Quarter	
8	RM/K.A/BH/A/19/0013	Aukhara Sangharveer Road Link Shahpur to Bhaisahat (via Majhui) Road	10109028	3354	1.08.2019	3.200	105.8396	69.27	20.78746	MBRD-28/2019-20	05-Nov-20	18-Dec-20	3.11811	1-3 Quarter	
9	RM/K.A/BH/A/19/0013	Bhaisahat Chand PWD Road (T34) to Sirbit	13141032417	3354	1.08.2019	1.300	53.5423	31.358	10.61971	MBRD-28/2019-20	05-Nov-20	18-Dec-20	1.59297	1-3 Quarter	
10	RM/K.A/BH/A/19/0013	Aukhara Madhura Road to Madhura Vill	13141032418	3354	1.08.2019	1.600	106.255	77.715	10.52011	MBRD-28/2019-20	05-Nov-20	02-Feb-21	1.57803	1-3 Quarter	

Sl No.	Package No.	Name of Road	Project ID as per MIS	Administrative		Administrative		Agreement Amount (in Lacs)		Agreement No. and Date	Date of Completion as per agreement	Actual Date of Completion	Requisition of 5 year Maintenance Amount (in Lacs)	Remarks	
				Sanction	Letter No.	Date	Length (in Km)	Amount (in Lacs)	Initial Rectification with Surface Renewal						5 Years Routine Maintenance
1	2	3	4			5	6	7	8	9	10	11	12	13	14
11	RM/K.A/BHA/19/0013	Hazra Pul Nauratia Road to Masoi	13141032423	3354	1 08 2019	1 300	33 9159	20 865	8 31591	MBD-28/2019-20	05-Nov-20	18-Dec-20	1 24740	1-3 Quarter	
12	RM/K.A/BHA/19/0003	Itathi - Bare Road	10301502014	3354	1 08 2019	1 300	58 336	43 279	9 6843	MBD-25/2019-20	30-Jun-20	25-Sep-20	1 93688	1-4 Quarter	
13	RM/K.A/BHA/19/0003	Pachgavan - Bhabhua Road Kudra	10301502027	3354	1 08 2019	1 297	53 7893	38 78	10 7513	MBD-25/2019-20	30-Jun-20	14-Jan-21	1 61268	1-3 Quarter	
14	RM/K.A/BHA/19/0003	BHABHUA-MOHANIA ROAD TO DIHRA VILLAGE	10109640	3354	1 08 2019	0 950	34 124	25 252	8 86534	MBD-25/2019-20	30-Jun-20	14-Jan-21	1 35981	1-3 Quarter	
15	RM/K.A/BHA/19/0003	Bezari Kohari Canal Path to Dardith	13141032518	3354	1 08 2019	2 300	101 997	81 916	18 39661	MBD-25/2019-20	30-Jun-20	05-Jan-21	2 75949	1-3 Quarter	
16	RM/K.A/BHA/19/0003	Bhabhua Kudra Road to Meer	13141032788	3354	1 08 2019	2 000	95 9396	65 046	16 14935	MBD-25/2019-20	30-Jun-20	14-Jan-21	2 42241	1-3 Quarter	
		Total											71.84288		

Sunil Kumar
 Divisional Accounts Officer
 Rural Works Department,
 Works Division, Bhabhua
 (Kaimur)

Sunil Kumar
 Executive Engineer
 Rural Works Department
 Works Division, Bhabhua
 (Kaimur)

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to date

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
1	Maintenance of Rural roads Under MR (New Maintenance Policy-2018 MR (3054) BRRDA PATNA)	New Maintenance Policy-2018 MR (3054) BRRDA PATNA	367.82929	Certified that out of Rs. 367.82929 lakh of grants-in-aid sanctioned during the years 2023-24 In favor of EE, RWD works division Bhabhua a sum of Rs. 352.50784 lakh has been utilized for the purpose of Maintenance of New Maintenance Policy-2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 15.32145 lakh remaining unutilized at the end of the period under report.
	Total:		367.82929	


2. Certified that I have satisfied my self that the cosnditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.


Kind of Checks exercised:-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other caudal formalities have been observed.

3. Physical Progress achieved:-

- Construction of Road Works.
- Construction of CD works.


26/01/23
Divisional Accounts Officer
R.W.D, works Division
Bhabhua.


26/01/23
Executive Engineer
R.W.D, works Division
Bhabhua

STANDARD FORMAT FOR ROADS QUARTERLY STATEMENT

PIU Name :- RWD, Works Division, Bhabhua

Quarter:- 5

Quarter:-

1	Name of the Road	Ramgarh - Bakhari Devi		
2	Batch No./Package No.	RM/KA/BHA/19/0004		
3	Project ID	10301402024		
4	Total Lenth of Road (in KM)	10.200		
5	Length of Road to Meet Required Service Level [Completed length](in Km) [1]	10.200		
6	No. of Total Quarter (ie 3 Months as a unit) in 5 years	20		
7	Ordinary Maintenance Cost as per Schedule [Agreement Amount for Maintenance] (in Lakh)	75.242		
8	Quarterly Payment : 1/20 of Ordinary Maintenance Cost as per Schedule (in Lakh) [2]	3.76210		
Compliance Criteria	Standard Job Description	Non-Compliance		Reduction Payment [6]=[3]/[1]*[2]*[4]
		Length Non-Compliant [3]	Weighted Value for Payment Reduction (%) [4]	
I	PAVED ROADS (CARRIAGEWAY)	-	60%	-
II	SHOULDERS AND EMBANMENTS	-	10%	-
III	CROSS DRAINAGE INCLUDING CULVERTS AND BRIDGES	-	15%	-
IV	SIGNAGE AND ROAD SAFETY	-	10%	-
V	VEGATION	-	5%	-
TOTAL PAYMENT REDUCTION FOR THE QUARTER (IN Lakh) [5]				0.00
TO BE PAID FOR THE QUARTER/DEMAND (in Lakh) [6]				3.76210

Date of inspection by E/I or his agent

Prepare by Contractor's self Control unit

Handwritten signature
24/6/23

Name and Designation of person inspecting road

Date

(Signature)

Signature of person inspecting road

Handwritten signature
24/6/23
AZ

Certify by E/I [signature] Date:-

Handwritten signature
24/06/23
Executive Engineer
Rural Works Department
Works Division, Bhabhua

Requisition Formnet for Scheme Head-MR-(3054) Under Bihar Rurak Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

RWD, Works Division:- Bhabhua

Government Of Bihar OM01

Rural Works Department

Quarter:- 5

SUMMARY OF ORDINARY MAINTENANCE INSPECTION REPORT


Road From:- Ramgarh - Bakhari Devi
(Package No.-RM/KA/BHA/19/0004
Length of Road:-10.2 KM

To,
Executive Engineer
RWD (w) Div. Bhabhua

Inspector :- JE RWD Sub Division Chainpur

Position :-J.E.

No	Standard Of Work Item	Work Unit	Unit Of Required in each Kilometer										Comments
			1	2	3	4	5	6	7	8	9	10	
OM100	Sealed payment												Comments
OM101	Pothole Patching	m ²	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	No Pot Hole found.
OM102	Surface Depression and Rut patching	m ³	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Surface Depression & Rut Patching found.
OM103	Crack Sealing	Lm	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	No Crack Sealing found
	Surface Treatment												
OM104	(a) Loss of Aggregate (Surface Ravelling)	m ²	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	No Loss of Aggregates (Surface Ravelling) Found
	(b) Bleeding / Flushing	m ²	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	No Loss of Aggregates (Surface Ravelling) Found
	© Crocodile Cracking	m ²	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	No Bleeding / Flushing found.
105	Edge Repair	m ²	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	No Crocodile Cracking Found
106	Digouts	m ²	NA	NA	NA	NA	NA	Nil	Nil	Nil	Nil	Nil	No Edge Repair Required
107	Concrete pavement	m ³	NA	NA	NA	NA	NA	Nil	Nil	Nil	Nil	Nil	
	Other activities												
OM200	Shoulder												
	Unsealed Shoulder												
OM201	(a) Edge Drop-off	Lm	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	No Edge Drop-Off Required
	(b) Roughness, Scouring or Potholes	Lm	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
	(c) Holding water	Lm	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	No Holding water Found.
OM202	Embankment Repair	m ³	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
	Other activities (Rain Cuts)		Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
OM300	Drainage including culverts major												
OM301	Surface Drains & Verge	Lm	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	Not Required
OM302	Culvert Cleaning	No	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
OM303	Culvert and pit Repair	m ³	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
	Other activities(With/washing)	m ²	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required


 24/6/23
 AE
 24/6/23

standard Of Work Item		Work	Unit OF Required in each Kilometer										Comments
No	Name	Unit	1	2	3	4	5	6	7	8	9	10	
OM400	Vegetation												
	Grass Control												
OM401	(a) Roadside- General Tidy	Ha	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
	(b) Clear near Safety signs, kilometer posts and roadside furniture	Ha	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
OM402	Tree and Shrub Management	Ha	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
	Cutting Of Branches Of Trees	No	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
	Cutting Of Shrubs From Road Way	No	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
	Other activities (Trimming of Grass)	m ²	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
OM500	Safety Signage and Road												
OM501	Signs Maintenance	No	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NIL	Not Required
OM502	Guard Stones	Lm	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	Not Required
OM503	Distance Stones	No	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	Not Required
OM504	Road Marking	No	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
	Other activities												Not Required

Bidder

Appendix

Executive Engineer
Rural works Department
Works Division, Bhabhua

Name of Customer :	M/s. Bhendra Kumar Singh
Name of Work/Road :	Ramgath to Bakhan Devi
Lab Job number :	45
Date :	04-06-2023
Section No. :	45


Print Generate Report and Graph

Test Date :	04-06-2023	Road Name :	Ramgath to Bakhan Devi
Machine No. :	412	Road Type :	(R) RURAL ROAD
Start S No. :		Side :	
Start E No. :		Interval :	
Weather :		UV Range :	1745 To 5000 mm/km
Start Location :		Dist Range :	0 To 10.3 0.1 * 1000 m
End Location :		Equation :	$Y = 0 * X^2 + 1.136 * X + 132.5$

Redraw Graph

Map View

File : C:\Users\BRRDAS1\OneDrive\Desktop\stjmr\formate rwg main\BIJENDRA\Ramgath to Bakhan Devi.xls.
Name of Customer : Name of Work/Road : Lab Job number :



Distance * 1000 m

01/06/23 14/06/23
24.6.23 24/06/23

Road Name - Ramgarh to Bakhari Devi

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
4/6/23	8:15:28	45	0.1	260	30.3	2600	3086	G	25.050534	83.416212	Normal
4/6/23	8:15:59	45	0.1	310	30.3	3100	3654	G	25.050153	83.415572	Normal
4/6/23	8:16:30	45	0.1	310	30.3	3100	3654	G	25.04958	83.414662	Normal
4/6/23	8:16:51	45	0.1	300	30.3	3000	3540	G	25.049115	83.41382	Normal
4/6/23	8:17:22	45	0.1	230	40.4	2300	2745	G	25.048672	83.412978	Normal
4/6/23	8:17:53	45	0.1	310	30.3	3100	3654	G	25.048052	83.411918	Normal
4/6/23	8:18:24	45	0.1	250	40.4	2500	2972	G	25.048052	83.411213	Normal
4/6/23	8:18:55	45	0.1	230	40.4	2300	2745	G	25.047518	83.410925	Normal
4/6/23	8:19:26	45	0.1	280	30.3	2800	3313	G	25.047122	83.41012	Curve
4/6/23	8:19:57	45	0.1	290	30.3	2900	3426	G	25.047151	83.41613	Normal
4/6/23	8:20:28	45	0.1	310	30.3	3100	3654	G	25.046053	83.40838	Normal
4/6/23	8:20:59	45	0.1	250	40.4	2500	2972	G	25.046361	83.408864	Normal
4/6/23	8:21:30	45	0.1	310	30.3	3100	3654	G	25.045047	83.406601	Normal
4/6/23	8:21:51	45	0.1	250	40.4	2500	2972	G	25.044399	83.405494	Normal
4/6/23	8:22:19	45	0.1	310	30.3	3100	3654	G	25.046053	83.40835	Normal
4/6/23	8:22:53	45	0.1	290	30.3	2900	3426	G	25.046086	83.40867	Normal
4/6/23	8:23:24	45	0.1	310	30.3	3100	3654	G	25.046053	83.40838	Curve
4/6/23	8:23:55	45	0.1	250	40.4	2500	2972	G	25.043683	83.404372	Normal
4/6/23	8:24:36	45	0.1	310	30.3	3100	3654	G	25.043069	83.403383	Normal
4/6/23	8:24:57	45	0.1	290	30.3	2900	3426	G	25.043037	83.403282	Normal
4/6/23	8:25:28	45	0.1	300	30.3	3000	3540	G	25.042719	83.402804	Normal
4/6/23	8:25:59	45	0.1	280	30.3	2800	3313	G	25.041944	83.401576	Normal
4/6/23	8:26:20	45	0.1	290	30.3	2900	3426	G	25.041192	83.400498	Normal
4/6/23	8:26:51	45	0.1	300	30.3	3000	3540	G	25.040703	83.399741	Normal
4/6/23	8:27:22	45	0.1	280	30.3	2800	3313	G	25.040138	83.39884	Curve
4/6/23	8:27:53	45	0.1	310	30.3	3100	3654	G	25.039812	83.398081	Normal
4/6/23	8:28:24	45	0.1	260	30.3	2600	3086	G	25.039421	83.397174	Normal
4/6/23	8:28:55	45	0.1	270	30.3	2700	3199	G	25.038947	83.396134	Normal
4/6/23	8:29:26	45	0.1	250	40.4	2500	2972	G	25.03846	83.394692	Normal
4/6/23	8:29:56	45	0.1	280	30.3	2800	3313	G	25.038076	83.393591	Normal
4/6/23	8:30:18	45	0.1	290	30.3	2900	3426	G	25.037581	83.393498	Normal
4/6/23	8:30:59	45	0.1	280	30.3	2800	3313	G	25.036763	83.393617	Normal
4/6/23	8:31:20	45	0.1	270	30.3	2700	3199	G	25.036167	83.393148	Normal
4/6/23	8:31:51	45	0.1	280	30.3	2800	3313	G	25.035912	83.39172	Normal
4/6/23	8:32:22	45	0.1	290	30.3	2900	3426	G	25.035554	83.391728	Normal

$$Y = 0 * X^2 + 1.136 * X + 132.5$$

$$X = 2500$$

$$Y = 2972$$

(R) RURAL ROAD
 Good Average Poor
 <4000 4001-5000 >5001


Total IRI	3374.11
Average	3374.11

24/6/23
 24/6/23
 24/6/23
 24/6/23

4/6/23	8:32:53	45	0.1	250	40.4	2500	2972 G	25.035244	83.391536	Normal
4/6/23	8:33:24	45	0.1	270	30.3	2700	3199 G	25.034577	83.391526	Normal
4/6/23	8:33:55	45	0.1	280	30.3	2800	3313 G	25.033646	83.391514	Normal
4/6/23	8:34:26	45	0.1	250	40.4	2500	2972 G	25.033084	83.39172	Normal
4/6/23	8:34:57	45	0.1	280	30.3	2800	3313 G	25.032011	83.391964	Normal
4/6/23	8:35:28	45	0.1	310	30.3	3100	3654 G	25.031081	83.39206	Normal
4/6/23	8:35:59	45	0.1	300	30.3	3000	3540 G	25.030274	83.392093	Normal
4/6/23	8:36:30	45	0.1	310	30.3	3100	3654 G	25.029331	83.392104	Curve
4/6/23	8:36:51	45	0.1	280	30.3	2800	3313 G	25.028282	83.392074	Normal
4/6/23	8:37:32	45	0.1	290	30.3	2900	3426 G	25.02741	83.391798	Normal
4/6/23	8:37:53	45	0.1	300	30.3	3000	3540 G	25.02708	83.390607	Normal
4/6/23	8:38:24	45	0.1	310	30.3	3100	3654 G	25.026252	83.389054	Normal
4/6/23	8:38:55	45	0.1	300	30.3	3000	3540 G	25.025694	83.388271	Normal
4/6/23	8:39:36	45	0.1	250	40.4	2500	2972 G	25.025241	83.387804	Normal
4/6/23	8:39:58	45	0.1	290	30.3	2900	3426 G	25.0243316	83.387281	Normal
4/6/23	8:40:18	45	0.1	280	30.3	2800	3313 G	25.023408	83.387366	Normal
4/6/23	8:40:59	45	0.1	290	30.3	2900	3426 G	25.022468	83.387728	Normal
4/6/23	8:41:20	45	0.1	300	30.3	3000	3540 G	25.022158	83.388633	Normal
4/6/23	8:41:51	45	0.1	280	30.3	2800	3313 G	25.021593	83.38951	Normal
4/6/23	8:42:22	45	0.1	250	40.4	2500	2972 G	25.020614	83.389902	Normal
4/6/23	8:42:53	45	0.1	310	30.3	3100	3654 G	25.019956	83.390047	Curve
4/6/23	8:43:24	45	0.1	300	30.3	3000	3540 G	25.019538	83.390002	Normal
4/6/23	8:43:55	45	0.1	290	30.3	2900	3426 G	25.018696	83.389879	Normal
4/6/23	8:44:26	45	0.1	280	30.3	2800	3313 G	25.017742	83.389601	Normal
4/6/23	8:44:57	45	0.1	260	40.4	2600	3086 G	25.017203	83.388802	Normal
4/6/23	8:45:28	45	0.1	250	40.4	2500	2972 G	25.016672	83.388344	Normal
4/6/23	8:45:59	45	0.1	290	30.3	2900	3426 G	25.016365	83.388072	Normal
4/6/23	8:46:30	45	0.1	310	30.3	3100	3654 G	25.016312	83.388048	Normal
4/6/23	8:46:51	45	0.1	300	30.3	3000	3540 G	25.015935	83.387648	Normal
4/6/23	8:47:32	45	0.1	290	30.3	2900	3426 G	25.015583	83.387221	Normal
4/6/23	8:47:53	45	0.1	300	30.3	3000	3540 G	25.015342	83.386862	Curve
4/6/23	8:48:24	45	0.1	310	30.3	3100	3654 G	25.015059	83.386543	Normal
4/6/23	8:48:53	45	0.1	300	30.3	3000	3540 G	25.014557	83.385824	Normal
4/6/23	8:49:36	45	0.1	290	30.3	2900	3426 G	25.014227	83.385045	Normal
4/6/23	8:49:57	45	0.1	260	40.4	2600	3086 G	25.013672	83.384496	Normal
4/6/23	8:50:28	45	0.1	300	30.3	3000	3540 G	25.013041	83.384282	Normal
4/6/23	8:50:59	45	0.1	310	30.3	3100	3654 G	25.012718	83.383697	Normal
4/6/23	8:51:23	45	0.1	300	30.3	3000	3540 G	25.011804	83.383627	Normal


 24/6/23
 24.6.23
 14/06/23

4/6/23	8:51:54	45	0.1	310	30.3	3100	3654	G	25.011283	83.38312	Normal
4/6/23	8:52:25	45	0.1	250	40.4	2500	2972	G	25.011061	83.382057	Normal
4/6/23	8:52:56	45	0.1	290	30.3	2900	3426	G	25.010792	83.380769	Normal
4/6/23	8:53:27	45	0.1	310	30.3	3100	3654	G	25.010755	83.37941	Normal
4/6/23	8:53:58	45	0.1	300	30.3	3000	3540	G	25.010718	83.379111	Curve
4/6/23	8:54:29	45	0.1	310	30.3	3100	3654	G	25.010721	83.377937	Normal
4/6/23	8:54:50	45	0.1	250	40.4	2500	2972	G	25.010383	83.377111	Normal
4/6/23	8:55:31	45	0.1	290	30.3	2900	3426	G	25.010034	83.36438	Normal
4/6/23	8:55:52	45	0.1	280	30.3	2800	3313	G	25.009396	83.375501	Normal
4/6/23	8:56:33	45	0.1	250	30.3	2500	2972	G	25.008617	83.374176	Normal
4/6/23	8:56:54	45	0.1	310	30.3	3100	3654	G	25.008226	83.37443	Normal
4/6/23	8:57:35	45	0.1	260	40.4	2600	3086	G	25.009187	83.373528	Normal
4/6/23	8:57:56	45	0.1	290	30.3	2900	3426	G	25.009062	83.372227	Normal
4/6/23	8:58:27	45	0.1	260	30.3	2600	3086	G	25.008938	83.371292	Curve
4/6/23	8:58:58	45	0.1	310	30.3	3100	3654	G	25.009266	83.370837	Normal
4/6/23	8:59:29	45	0.1	280	30.3	2800	3313	G	25.009382	83.370178	Normal
4/6/23	8:59:56	45	0.1	290	30.3	2900	3426	G	25.009431	83.369488	Normal
4/6/23	9:1:28	45	0.1	300	30.3	3000	3540	G	25.009476	83.368757	Normal
4/6/23	9:1:59	45	0.1	290	30.3	2900	3426	G	25.009134	83.368445	Normal
4/6/23	9:2:30	45	0.1	310	30.3	3100	3654	G	25.008562	83.36826	Normal
4/6/23	9:2:51	45	0.1	290	30.3	2900	3426	G	25.008616	83.367401	Normal
4/6/23	9:3:32	45	0.1	280	30.3	2800	3313	G	25.008697	83.367075	Normal
4/6/23	9:3:53	45	0.1	300	30.3	3000	3540	G	25.008717	83.366438	Normal
4/6/23	9:4:34	45	0.1	290	30.3	2900	3426	G	25.008566	83.366374	Normal
4/6/23	9:4:53	45	0.1	310	30.3	3100	3654	G	25.008277	83.366382	Normal
4/6/23	9:5:36	45	0.1	280	30.3	2800	3313	G	25.007497	83.366417	Normal
4/6/23	9:5:57	45	0.1	290	30.3	2900	3426	G	25.006968	83.366445	Normal
4/6/23	9:6:38	45	0.1	280	30.3	2800	3313	G	25.006186	83.366311	Normal
4/6/23	9:6:57	45	0.1	250	0	2500	2972	G	25.005096	83.366281	Normal


 24/6/23
 AC


 24/6/23