

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, भभुआ ।

Email ID:- bhabua.rwd@gmail.com

Mob:- 8986915314

पत्रांक.....10813130

भभुआ /दिनांक.....26/06/2023

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, भभुआ ।

सेवा में,

नोडल पदाधिकारी (MR 3054)
ग्रामीण कार्य विभाग
पटना, बिहार

विषय :- नई अनुरक्षण नीति-2018MR (3054)योजना के अंतर्गत पथ में कराये गये
त्रैमासिक अनुरक्षण कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुरक्षण नीति-2018 MR
(3054)योजना के अंतर्गत पथ में कराये गये त्रैमासिक अनुरक्षण कार्य के लिए संवेदक को
भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की
जाती है।

अनु :- यथोक्त।

विश्वासभाजन

26/06/23
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, भभुआ ।
26/6/23

Requisition format for Scheme Head- 5 Year Maintenance of MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal

Sl No.	Name of Division-Bhabhua	Package No.	Name of Road	Project ID as per MIS	Administrative		Administrative		Agreement Amount (in Lacs)		Agreement No. and Date	Date of Completion as per agreement	Actual Date of Completion	Requisition Amount of 5 year Maintenance (in Lacs)	Remarks
					Letter No.	Date	Length (in Km)	Amount (in Lacs)	Initial Rectification with Surface Renewal	5 Years Routine Maintenance					
1		2	3	4		5	6	7	8	9	10	11	12	13	14
1	RM/K.A/BH/A/19/0004		Ramgarh - Bakhari Devi	10301402024	1832	24.06.2019	10.200	295.325	194.685	75.24199	MRBD-16/2019-20	23-Jun-20	27-Jun-20	18.81050	1-5 Quarter
2	RM/K.A/BH/A/19/0004		Tiwari - Hazra Durgawati Road	10301402031	1832	24.06.2019	2.860	106.704	72.224	21.20045	MRBD-16/2019-20	23-Jun-20	27-Jun-20	5.30010	1-5 Quarter
3	RM/K.A/BH/A/19/0004		From Sandharveer primary school to Sonuo village	10301501023	1832	24.06.2019	1.000	32.3354	20.438	8.12449	MRBD-16/2019-20	23-Jun-20	27-Jun-20	2.03110	1-5 Quarter
4	RM/K.A/BH/A/19/0005		Dadher - Bahura	10301402010	1832	24.06.2019	2.200	78.6107	52.804	14.15396	MRBD-20/2019-20	23-Jun-20	22-Jun-20	3.53850	1-5 Quarter
5	RM/K.A/BH/A/19/0005		Majhri - Laktra	10301402020	1832	24.06.2019	2.030	75.225	50.319	17.83064	MRBD-20/2019-20	23-Jun-20	22-Jun-20	4.45765	1-5 Quarter
6	RM/K.A/BH/A/19/0005		Salempur - Chaupur	10301402025	1832	24.06.2019	9.277	252.0633	192.615	67.3101	MRBD-20/2019-20	23-Jun-20	22-Jun-20	16.82750	1-5 Quarter
7	RM/K.A/BH/A/19/0013		Dihra - Lakhanpur	10301402009	3354	1.08.2019	3.430	112.1107	80.461	21.66495	MRBD-28/2019-20	05-Nov-20	02-Feb-21	3.24975	1-3 Quarter
8	RM/K.A/BH/A/19/0013		Aukhara Sangharveer Road Link Shahpur to Bhaisahar (via Majhri) Road	101099028	3354	1.08.2019	3.200	105.8396	69.27	20.78746	MRBD-28/2019-20	05-Nov-20	18-Dec-20	3.11811	1-3 Quarter
9	RM/K.A/BH/A/19/0013		Bhaisahar Chaud PWD Road (TD4) to Sirbit	13141032417	3354	1.08.2019	1.300	53.5423	31.358	10.61971	MRBD-28/2019-20	05-Nov-20	18-Dec-20	1.59297	1-3 Quarter
10	RM/K.A/BH/A/19/0013		Aukhara Madhura Road to Madhura Vill	13141032418	3354	1.08.2019	1.600	106.255	77.715	10.52011	MRBD-28/2019-20	05-Nov-20	02-Feb-21	1.57803	1-3 Quarter

Sl No.	Package No.	Name of Road	Project ID as per MIS	Administrative		Administrative		Agreement Amount (in Lacs)			Agreement No. and Date	Date of Completion as per agreement	Actual Date of Completion	Requisitioned Amount of 5 year Maintenance (in Lacs)	Remarks
				Sanction	Letter No.	Date	Length (in Km)	Amount (in Lacs)	Initial Rectification with Surface Renewal	5 Years Routine Maintenance					
1	2	3	4			5	6	7	8	9	10	11	12	13	14
11	RM/K.A/BHA/19/0013	Hazra Pul Nauratia Road to Misoi	13141032423	3354	1.08.2019	1.300	33.9159	20.865	8.31591	MBD-28/2019-20	05-Nov-20	18-Dec-20	1.24740	1.24740	1-3 Quarter
12	RM/K.A/BHA/19/0003	Itarhi - Bare Road	10301502014	3354	1.08.2019	1.300	58.336	43.279	9.6843	MBD-25/2019-20	30-Jun-20	25-Sep-20	1.93688	1.93688	1-4 Quarter
13	RM/K.A/BHA/19/0003	Pachgavan - Bhabhua Road Kudra	10301502027	3354	1.08.2019	1.297	53.7893	38.78	10.7513	MBD-25/2019-20	30-Jun-20	14-Jan-21	1.61268	1.61268	1-3 Quarter
14	RM/K.A/BHA/19/0003	BHABHUA-MOHANIA ROAD TO DHRA VILLAGE	10109640	3354	1.08.2019	0.950	34.124	25.252	8.86534	MBD-25/2019-20	30-Jun-20	14-Jan-21	1.35981	1.35981	1-3 Quarter
15	RM/K.A/BHA/19/0003	Beaur Kohari Canal Path to Dardith	13141032518	3354	1.08.2019	2.300	101.997	81.916	18.39661	MBD-25/2019-20	30-Jun-20	05-Jan-21	2.75949	2.75949	1-3 Quarter
16	RM/K.A/BHA/19/0003	Bhabhua Kudra Road to Meer	13141032788	3354	1.08.2019	2.000	95.9396	65.046	16.14935	MBD-25/2019-20	30-Jun-20	14-Jan-21	2.42241	2.42241	1-3 Quarter
		Total											71.84288		

Sunil Kumar
 Divisional Accounts Officer
 Rural Works Department,
 Works Division, Bhabhua
 (Kaimur)

S. S. S.
 Executive Engineer
 Rural Works Department
 Works Division, Bhabhua
 (Kaimur)

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to date

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lacs Rs.)	Amount Received (In lacs Rs.)	Particulars
1	Maintenance of Rural roads Under MR (New Maintenance Policy-2018 MR (3054) BRRDA PATNA)	New Maintenance Policy-2018 MR (3054) BRRDA PATNA	367.82929	Certified that out of Rs. 367.82929 lakh of grants-in-aid sanctioned during the years 2023-24 In favor of EE, RWD works division Bhabhua a sum of Rs. 352.50784 lakh has been utilized for the purpose of Maintenance of New Maintenance Policy-2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 15.32145 lakh remaining unutilized at the end of the period under report.
	Total:		367.82929	

2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- i. Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii. Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii. Construction materials have been tested.
- iv. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- v. All other caudal formalities have been observed.

3. Physical Progress achieved:-

- i. Construction of Road Works.
- ii. Construction of CD works.


Sandil Kumar
26/01/23
Divisional Accounts Officer
R.W.D, works Division
Bhabhua.


9/6/23
Executive Engineer
R.W.D, works Division
Bhabhua
(Signature)

No	standard Of Work Item	Work Unit	Unit Of Required in each Kilometere										Comments
			1	2	3	4	5	6	7	8	9	10	
OM400	Vegetation												
	Grass Control												
OM401	(a) Roadside- General Tidy	Ha	Nil	Nil	Nil								Not Required
	(b) Clear near Safety signs, kilometer posts and roadside furniture	Ha	Nil	Nil	Nil								Not Required
OM402	Tree and Shrub Management	Ha	Nil	Nil	Nil								Not Required
	Cutting Of Branches Of Trees	No	Nil	Nil	Nil								Not Required
	Cutting Of Shrubs From Road Way	No	Nil	Nil	Nil								Not Required
	Other activities (Trimming of Grass)	m ²	Nil	Nil	Nil								Not Required
OM500	Safety Signage and Road												
OM501	Signs Maintenance	No	Nil	Nil	Nil								Not Required
OM502	Guard Stones	Lm	NA	NA	NA								Not Required
OM503	Distance Stones	No	NA	NA	NA								Not Required
OM504	Road Marking	No	Nil	Nil	Nil								Not Required
	Other activities												


Bidder




Appendix


24.6.23
AE

Executive Engineer
Rural works Department
Works Division, Bhabhua


24.6.23

Name of Customer: W. J. Benda Luna Inc
 Name of Work: road to Horta Durgawati Road
 Road: 44
 Lab Job number: 44
 Date: 04-06-2013
 Section No: 44


Test Date: 04-06-2013
 Road Name: Road to Horta Durgawati Road
 Machine No: 472
 Road Type: (R) RURAL ROAD
 Start S No: 1637
 Side: Interval
 Start E No: 2837
 Weather: 1637 To 5000 1000 mm/hum
 Start Location: 0 To 29 01 1000 m
 End Location: Egation: Y = 0.0 * X + 2.1136 * X + 132.5

Print Generate Report and Graph

Redraw Graph

Map View

File: C:\Users\BPPQAS71\OneDrive\Desktop\disk1\formate new mean\BUENORA\Traw to Horta Durgawati
 Name of Customer: Name of Work/ Road: Lab Job number:



Handwritten notes:
 24/6/2013
 24/6/23
 14/6/14

Road Name - Tiwai to Hatta Durgawati Road

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	TEGORY ROAD	Latitude	Longitude	Event
4/6/23	7:30:31	44	0.1	220	0	2200	2631	G	25.054915	83.461868	Normal
4/6/23	7:30:51	44	0.1	310	20.2	3100	3654	G	25.05521	83.460353	Normal
4/6/23	7:31:24	44	0.1	300	30.3	3000	3540	G	25.055472	83.45936	Normal
4/6/23	7:31:55	44	0.1	310	30.3	3100	3654	G	25.055775	83.458265	Normal
4/6/23	7:32:23	44	0.1	280	30.3	2800	3313	G	25.055855	83.457288	Curve
4/6/23	7:32:51	44	0.1	240	40.4	2400	2858	G	25.056302	83.455875	Normal
4/6/23	7:33:31	44	0.1	290	30.3	2900	3426	G	25.056573	83.455285	Normal
4/6/23	7:33:56	44	0.1	280	30.3	2800	3313	G	25.071353	83.455852	Normal
4/6/23	7:34:32	44	0.1	230	40.4	2300	2745	G	25.071352	83.455852	Normal
4/6/23	7:34:55	44	0.1	290	30.3	2900	3426	G	25.057494	83.452548	Normal
4/6/23	7:35:31	44	0.1	310	30.3	3100	3654	G	25.057544	83.451889	Normal
4/6/23	7:35:52	44	0.1	300	30.3	3000	3540	G	25.057315	83.451421	Normal
4/6/23	7:36:27	44	0.1	290	30.3	2900	3426	G	25.056347	83.451231	Normal
4/6/23	7:36:51	44	0.1	300	30.3	3000	3540	G	25.055615	83.450683	Normal
4/6/23	7:37:32	44	0.1	310	30.3	3100	3654	G	25.055189	83.450091	Normal
4/6/23	7:37:56	44	0.1	290	30.3	2900	3426	G	25.054515	83.449671	Normal
4/6/23	7:38:24	44	0.1	300	30.3	3000	3540	G	25.053869	83.449309	Curve
4/6/23	7:38:52	44	0.1	310	30.3	3100	3654	G	25.053104	83.449461	Normal
4/6/23	7:39:31	44	0.1	300	30.3	3000	3540	G	25.052251	83.449649	Normal
4/6/23	7:39:56	44	0.1	310	30.3	3100	3654	G	25.052228	83.449865	Normal
4/6/23	7:40:32	44	0.1	300	30.3	3000	3540	G	25.052632	83.450749	Normal
4/6/23	7:40:51	44	0.1	310	30.3	3100	3654	G	25.052997	83.451348	Normal
4/6/23	7:41:22	44	0.1	300	30.3	3000	3540	G	25.053535	83.451638	Curve
4/6/23	7:41:51	44	0.1	310	30.3	3100	3654	G	25.052949	83.452089	Normal
4/6/23	7:42:25	44	0.1	290	30.3	2900	3426	G	25.052491	83.452361	Normal
4/6/23	7:42:55	44	0.1	230	40.4	2300	2745	G	25.052082	83.452403	Normal
4/6/23	7:43:21	44	0.1	290	40.4	2900	3426	G	25.050557	83.452293	Normal
4/6/23	7:43:51	44	0.1	240	0	2400	2858	G	25.048944	83.452278	Normal

$Y = 0 * X^2 + 1.136 * X + 132.5$
 $X = 2400$
 $Y = 2858$
 (R) RURAL ROAD
 Good Average Poor
 <4000 4001-5000 >5001

Total IRI
 Average 3393.96


 24/6/2023
 24/6/23
 24/6/23
 24/6/23

STANDARD FORMAT FOR ROADS QUARTERLY STATEMENT

PIU Name :- RWD, Works Division, Bhabhua

Quarter:- 5						
1	Name of the Road	Tiwai - Hatta Durgawati Road				
2	Batch No./Package No.	RM/KA/BHA/19/0004				
3	Project ID	10301402031				
4	Total Lenth of Road (in KM)	2.860				
5	Length of Road to Meet Required Service Level [Completed length](in Km) [1]	2.860				
6	No. of Total Quarter (ie 3 Months as a unit) in 5 years	20				
7	Ordinary Maintenance Cost as per Schedule [Agreement Amount for Maintenance] (in Lakh)	21.200				
8	Quarterly Payment : 1/20 of Ordinary Maintenance Cost as per Schedule (in Lakh) [2]	1.06002				
Compliance Criteria	Standard Job Description	Non-Compliance		Reduction Payment [6]=[3]/[1]*[2]*[4]		
		Length Non-Compliant [3]	Weighted Value for Payment Reduction (%) [4]			
		I	PAVED ROADS (CARRIAGEWAY)	-	60%	-
		II	SHOULDERS AND EMBANMENTS	-	10%	-
		III	CROSS DRAINAGE INCLUDING CULVERTS AND BRIDGES	-	15%	-
		IV	SIGNAGE AND ROAD SAFETY	-	10%	-
V	VEGATION	-	5%	-		
TOTAL PAYMENT REDUCTION FOR THE QUARTER (IN Lakh) [5]				0.00		
TO BE PAID FOR THE QUARTER/DEMAND (in Lakh) [6]				1.06002		

Date of inspection by E/I or his agent

Prepare by Contractor's self Control unit

Name and Designation of person inspecting road

Date

(Signature)

Signature of person inspecting road

Certify by E/I [signature] Date:-

Executive Engineer
Rural Works Department
Works Division, Bhabhua

Requisition Formlet for Scheme Head-MR-(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Quarter:- 5

RWD, Works Division:- Bhabhua

Government Of Bihar OM01

Rural Works Department

SUMMARY OF ORDINARY MAINTENANCE INSPECTION REPORT

To,

Executive Engineer

RWD (w) Div. Bhabhua

Road From: Tiwai - Hatta Durgawati Road

(Package No.-RM/KA/BHA/19/0004

Length of Road:- 2.86 KM

Inspector :- JE RWD Sub Division Chainpur			Position :- J.E.										
No	Standard Of Work Item	Work Unit	Unit Of Required in each Kilometer										Comments
	Name		1	2	3	4	5	6	7	8	9	10	
OM100	Sealed payment												No Pot Hole found.
OM101	Pothole Patching	m ²	Nil	Nil	Nil								Not Surface Depression & Rut Patching found.
OM102	Surface Depression and Rut patching	m ³	Nil	Nil	Nil								No Crack Sealling found
OM103	Crack Sealing	Lm	Nil	Nil	Nil								No Loss of Aggregates (Surface Ravelling) Found
	Surface Treatment												No Loss of Aggregates (Surface Ravelling) Found
OM104	(a) Loss of Aggregate (Surface Ravelling)	m ²	Nil	Nil	Nil								No Loss of Aggregates (Surface Ravelling) Found
	(b) Bleeding / Flushing	m ²	Nil	Nil	Nil								No Bleeding / Flushing found.
	(c) Crocodile Cracking	m ²	Nil	Nil	Nil								No Crocodile Cracking Found
105	Edge Repair	m ²	Nil	Nil	Nil								No Edge Repair Required
106	Digouts	m ²	NA	NA	NA								
107	Concrete pavement	m ³	NA	NA	NA								
	Other activities												
OM200	Shoulder												
	Unsealed Shoulder	Lm	Nil	Nil	Nil								No Edge Drop-Off Required
	(a) Edge Drop-off	Lm	Nil	Nil	Nil								Not Required
OM201	(b) Roughness, Scouring or Potholes	Lm	Nil	Nil	Nil								No Holding water Found.
	(c) Holding water	m ³	Nil	Nil	Nil								Not Required
OM202	Embankment Repair		Nil	Nil	Nil								Not Required
	Other activities (Rain Cuts)												
OM300	Drainage including culverts major	Lm	NA	NA	NA								Not Required
OM301	Surface Drains & Verge	No	Nil	Nil	Nil								Not Required
OM302	Culvert Cleaning	m ³	Nil	Nil	Nil								Not Required
OM303	Culvert and pit Repair	m ²	Nil	Nil	Nil								Not Required
	Other activities(Whitw washing)												


 J.E. Chainpur
 24.6.23
 24/6/23