

**कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, मनिहारी।**

पत्रांक :- 306

/मनिहारी, दिनांक- 06/03/2023

प्रेषक,

कार्यपालक अभियंता,
ग्रा0का0वि0, मनिहारी।

सेवा में,

अपर-मुख्य-कार्यपालक-पदाधिकारी,
BRRDA, 3रीं मंजिल, भूमि विकास बैंक भवन,
बिहार, पटना।

विषय :- शीर्ष **New Maintenance Policy-2018** योजनान्तर्गत निर्माण हेतु आवंटन की अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि शीर्ष **New Maintenance Policy-2018** योजनान्तर्गत ग्रा0का0वि0, कार्य प्रमंडल, मनिहारी द्वारा विहित प्रपत्र में अधियाचना तैयार कर आपके अग्रेतर कार्रवाई हेतु समर्पित की जाती है।

अनु0:-यथोक्त।

विश्वनाथभाजन,

6/3/23

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, मनिहारी।

EXECUTIVE ENGINEER, WORK DEPARTMENT, WORKS DIVISION, MANIHARI

FORM GER - 19 - A

(See Government of India's Decision (i) below Rule - 150)

Form of Utilization Certificate up to month of March-2023

Form of Utilization Certificate up to month of March-2023						
Sl. No.	Name of Scheme	Sanction No. & Date with Amount (In Lacs)		Total Amount Received (In Lacs)	Particulars	Balance Amount (In Lakh) Bank+ CFMS
1	Construction of Rural Road under MR (New- Maintenance Policy-2018)	Letter No.22 we. Dt- 08.08.2022	317.2483	1767.22026	Certified that out of Rs. 1767.22026 lakh through CFMS of grants in aid sanctioned during the years in favour of Engineer incharge , R.W.D, Works Division, Manihari, Sum of Rs. 1706.59702 Lacs has been utilized for the purpose New-Maintenance Policy-2018 New Rural Roads & Bridge Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 60.623 Lacs remaining unutilized at the end of the period under.	60.62300
		Total	317.248	1767.22026		60.62300
Certified that I have satisfied myself that the condition on which the grants in aid sanctioned have been duly fulfilled / are being fulfilled and that I have Exercised the following Checks to see that the money was actually utilized for the purpose for which it was sanctioned .						
2	i	Works have been supervised by Executive Engineer / Superintending Engineer.				
	ii	Periodical inspection has been conducted by A.E. / Executive Engineer / Superintending Engineer.				
	iii	Construction materials have been tested.				
	iv	Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer / Executive Engineer.				
	v	All other Codal formalities have been observed.				



6/3/23
Executive Engineer
Rural works Department
Works Division Manihari

RWD, Works Division, Manihari

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Name of Division : Manihari

Sl. No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allotted Amount (In Lac)	up to date expenditure as per MIS (In Lac)	Requisition Against work done (In lac)	Remarks
					Length (In Km)	Amount (in Lac)	Initial Rectification with Surface Renewal (in lac)	5 years Routine Maintenance (In lac)										
1	RM/KA/MNA/20/003	Kumaripur Se Adivasi Tola Hote Hue Baigachi Tak	21105701002	666 dt 10.02.2020	3.500	141.6696	86.72	43.99235	70/MBD/2021-22 04.06.2021	03.06.2022	28.02.23	2416.26	25mm	5.1%	0.00000	0.00000	81.72000	
Total															0.00000	0.00000	81.72000	


6/3/23
Executive Engineer
RWD, Works Division, Manihari

Lab Job number :86

Date :28-02-2023

Name of Customer :Rajesh Kumar

Name of Work/ Road :Kumaripur Se Aadiwasi Tola Hote Hue Bairgachhi Tak

Sr.no	Location of test (in km)	Corrected U.I value (mm/km)	Road catagory
1	0.100	2109	G
2	0.200	2303	G
3	0.300	1818	G
4	0.400	2400	G
5	0.500	2206	G
6	0.600	2593	G
7	0.700	1915	G
8	0.800	2109	G
9	0.900	2497	G
10	1.000	2690	G
11	1.100	2884	G
12	1.200	2109	G
13	1.300	2012	G
14	1.400	2303	G
15	1.500	2787	G
16	1.600	2884	G
17	1.700	2981	G
18	1.800	2593	G
19	1.900	2109	G
20	2.000	2400	G
21	2.100	2593	G
22	2.200	2012	G
23	2.300	1818	G
24	2.400	2303	G
25	2.500	3175	G
26	2.600	2497	G
27	2.700	2400	G
28	2.800	2303	G
29	2.900	2206	G
30	2.900	2593	G
31	3.000	2690	G
32	3.100	2303	G
33	3.200	2690	G
34	3.300	2303	G
35	3.400	2981	G
Average IRI Value		2416.26	

for
28.02.23
+E

6/3/23
E o B.

Lab Job number :86

Date :28-02-2023

Name of Customer :Rajesh Kumar

Name of Work/ Road :Kumaripur Se Aadiwasi Tola Hote Hue Bairgachhi Tak

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
28/ 2/ 23	9: 18: 4	86	0.1	210	0	2100	2109	G	25.440313	87.620538	Normal
28/ 2/ 23	9: 18: 39	86	0.1	230	10.1	2300	2303	G	25.440403	87.621480	Normal
28/ 2/ 23	9: 19: 0	86	0.1	180	10.1	1800	1818	G	25.440125	87.622373	Normal
28/ 2/ 23	9: 19: 13	86	0.1	240	20.2	2400	2400	G	25.439920	87.623350	Normal
28/ 2/ 23	9: 19: 49	86	0.1	220	10.1	2200	2206	G	25.439735	87.624308	Normal
28/ 2/ 23	9: 20: 0	86	0.1	260	10.1	2600	2593	G	25.439558	87.625302	Normal
28/ 2/ 23	9: 20: 24	86	0.1	190	10.1	1900	1915	G	25.439428	87.626328	Normal
28/ 2/ 23	9: 21: 0	86	0.1	210	10.1	2100	2109	G	25.439463	87.627305	Normal
28/ 2/ 23	9: 21: 34	86	0.1	250	10.1	2500	2497	G	25.439570	87.628000	Normal
28/ 2/ 23	9: 21: 34	86	0.1	270	20.2	2700	2690	G	25.439562	87.629292	Normal
28/ 2/ 23	9: 22: 10	86	0.1	290	20.2	2900	2884	G	25.439455	87.630252	Normal
28/ 2/ 23	9: 22: 10	86	0.1	210	20.2	2100	2109	G	25.439130	87.631228	Normal
28/ 2/ 23	9: 22: 10	86	0.1	200	20.2	2000	2012	G	25.438873	87.632153	Normal
28/ 2/ 23	9: 22: 45	86	0.1	230	30.3	2300	2303	G	25.438620	87.633113	Normal
28/ 2/ 23	9: 23: 0	86	0.1	280	30.3	2800	2787	G	25.438380	87.634057	Speed Breaker
28/ 2/ 23	9: 23: 20	86	0.1	290	20.2	2900	2884	G	25.438948	87.634662	Speed Breaker
28/ 2/ 23	9: 23: 20	86	0.1	300	20.2	3000	2981	G	25.439663	87.635168	Speed Breaker
28/ 2/ 23	9: 23: 20	86	0.1	260	30.3	2600	2593	G	25.439643	87.636127	Normal
28/ 2/ 23	9: 23: 56	86	0.1	210	30.3	2100	2109	G	25.439447	87.637087	Normal
28/ 2/ 23	9: 24: 0	86	0.1	240	30.3	2400	2400	G	25.439185	87.638097	Normal
28/ 2/ 23	9: 24: 0	86	0.1	260	20.2	2600	2593	G	25.439030	87.639107	Normal
28/ 2/ 23	9: 24: 31	86	0.1	200	20.2	2000	2012	G	25.438832	87.640050	Normal
28/ 2/ 23	9: 25: 0	86	0.1	180	10.1	1800	1818	G	25.438752	87.640992	Normal
28/ 2/ 23	9: 25: 6	86	0.1	230	10.1	2300	2303	G	25.438685	87.642070	Curve
28/ 2/ 23	9: 25: 41	86	0.1	320	10.1	3200	3175	G	25.438172	87.642525	Speed Breaker
28/ 2/ 23	9: 26: 0	86	0.1	250	20.2	2500	2497	G	25.437448	87.642743	Normal
28/ 2/ 23	9: 26: 17	86	0.1	240	20.2	2400	2400	G	25.437222	87.643670	Normal
28/ 2/ 23	9: 26: 17	86	0.1	230	10.1	2300	2303	G	25.437032	87.644645	Normal
28/ 2/ 23	9: 26: 52	86	0.1	220	20.2	2200	2206	G	25.436788	87.645588	Normal
28/ 2/ 23	9: 27: 27	86	0.1	260	10.1	2600	2593	G	25.436508	87.646615	Normal
28/ 2/ 23	9: 28: 3	86	0.1	270	10.1	2700	2690	G	25.436278	87.647525	Normal
28/ 2/ 23	9: 28: 3	86	0.1	230	20.2	2300	2303	G	25.436087	87.648480	Normal
28/ 2/ 23	9: 28: 38	86	0.1	270	10.1	2700	2690	G	25.435958	87.649493	Normal
28/ 2/ 23	9: 29: 0	86	0.1	230	20.2	2300	2303	G	25.435957	87.650453	Normal
28/ 2/ 23	9: 29: 13	86	0.09	270	20.2	3000	2981	G	25.435907	87.650823	Normal

$$Y = 0 * X^2 + 0.969 * X + 74.60$$

$$X = 3000$$

$$Y = 2981$$

(R) RURAL ROAD


Good Average Poor

<4000 4001-5000 >5001

28.02.23
AE

6/3/23
E.F.

File : E:\RAM KUMAR\MISC Files\Bump integrator\Manihari\Kumaripur Se Aadiwasi Tola Hote Hue Bairgachhi
Name of Customer : Rajesh Kumar. Name of Work/ Road : Kumaripur Se Aadiwasi Tola Hote Hue Bairgachhi Tak.



[Signature]
28-02-23
AE

[Signature]
6/3/23
E. E.